GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax: 011-23412593, Email: cfohq.dlfire@nic.in, Ph. 011-23414333

No. F.6/DFS/MS/EH/2013/52/539

Dated: 09/07/13

FIRE SAFETY CERTIFICATE

Certified that the Swagath Restaurant, (A unit of Red Chilly Foods Pvt. Ltd.) at M-9, 1st & 2nd floor, GK-2 New Delhi running at first floor & second floor of the building comprised of basement, ground plus two upper floors was granted NOC by this department vide letter No. F6/DFS/MS/EH/2010/1692 dated 10.06.2010. The premises was re-inspected by the officer concerned of Delhi Fire Service on 26/06/2013 in the presence of Mr. Reynold, manager of the restaurant and observed that fire safety norms as required under Rule 33 of Delhi Fire Service Rules, 2010 have deemed complied and that the building / premises is fit for occupancy class-D "Assembly building Restaurant" (NOC renewed for 1st Floor and 2nd floor) with effect from of 1/2 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010.

Issued on 69/67//3 at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

d. In

Copy to: -

- 1. The DHO(South Zone), Office of Deputy Health Officer, M.C.D. Health Department South Zone, Green Park, New Delhi,
- The Manageri, M/s Swagath Restaurant, (A unit of Red Chilly Foods Pvt. Ltd.) at M-9, 1st & 2nd floor, GK-2 New Delhi

Conditions for the validity of Fire Safety Certificate

- 1. All the Fire Safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning Authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The Basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

		ISPEC	TION REI	PORT		
1 🦸	Name & address of the building	M/s Swagath Restaurant, (A unit of Red Chilly Foods Pvt. Ltd.) at M 9, 1st & 2nd floor, GK-2 New Delhi				
2	Type of Occupancy	Assembly Building "D" Restauant				
3	Type of case		Renewal			
4	Details of previous NOC	F6/DFS/MS/EH/2010/1692 dt 10.06.2010				
5	Fire safety directives letter No	Nil				
6	Date of inspection					
7	Name of the inspecting Officers :	26.06.2013			<u> </u>	
		D.O. (South) D.P. Bhardwaj				
8	Name and designation of officers	Mr. Reynold (Manager),				
	from the building side			4		
9	Year of construction		D 3	Basement, ground plus two upper floor		
10 S. NO.	Applicant's letter No.	Nil		01.05.2013	(Resturant ru 2nd floor)	unning at 1st ar
	Minimum Standards on fire prevention and fire safety U/R 33	NBC F	equiremen	t Provid	ded at site	Remarks MR / NMR
1	Access to building					
	Road width 2. Gate width	Require	ed	12 Mtr Provide	d	MR
	Gate width Width of internal road	N/A		N/A		N/A
2		N/A		N/A	8.	N/A
	Number, width Type & arrangement of exits 1. Number of staircases	<u> </u>				
	a. Upper floors	0110				
	b. Basements	Old Ca	se	Two Provided		MR
	2. Width of staircase	N/A		N/A	*	N/A
	a. Upper floors	Old Cas	20	0.95 & 0.67 m	atro	MD
	b. Basements	N/A		N/A	1115	MR N/A
	3. Protection of exits					IN/A
	a. Fire check door	N/A		N/A	X	N/A
	b. Pressurization	N/A		N/A		N/A
	4. No of continuous staircase to terrace	Requie	t	One		MR
	5. Width of corridor	N/A		N/A		N/A
3	6. Door size	Require	d	Two Exit Provid	ded	MR
<u> </u>	1. Fire check door	NI/A		1	:	
	2. Sealing of electrical shafts	N/A N/A		N/A		N/A
	3. Fire Rating of shaft door	N/A	N/A N/A			N/A
	4. Water curtain	N/A		N/A N/A		N/A N/A
	5. Fire dampers			N/A		N/A
4	Smoke Management system.			1.47.0		IN/A
	1.Basement	30 a/c per hour		N/A		N/A
-	2. Upper floors	12 a/c per hour		Exhust Fans Pr	ovided	MR
5	Fire Extinguishers 1. Total numbers			T		
	2. Types		* 1	08 Nos		MR
	3. ISI marking	ISI		ABC, Co2		MR
6	First-Aid Hose Reels.	101		Yes		MR
	Total numbers on each floor	One		Provided		MR
		30 m		Provided		MR
		5 mm		Provided		MR

7	Automatic fire detection and alarming sys	Lein .	N/A	Pag
-	1. Type of detectors	N/A		N/A
	2. Location of Main Panel	N/A	N/A	N/A
	3. Location of Repeater panel	N/A	N/A	N/A
	4. Alternate source of power	N/A	N/A	N/A
	5. Hooter's location	N/A	N/A	MR
8	MOEFA	Required	Provided	N/A
9	Public Address System.	N/A	N/A	14// 4
10	Automatic Sprinkler System.		21/2	N/A
	1. Basement	N/A	N/A	MR
	2. Upper floors	Required	Provided	N/A
3	3. Sprinkler above false ceiling	N/A	N/A	14/74
11	Internal Hydrants			MR
	1. Size of riser/down-corner	100 mm	Provided	MR
	2. Number of Hydrants per floor	One	Provided	MR
	3. Hose Box	One	Provided	IIVIN
12	Yard Hydrants.			NI/A
	1. Total number of hydrants	N/A	N/A	N/A
	2. Hose box	N/A	N/A	N/A
13	Pumping arrangements			
-10	1. Ground level			
	a. Discharge of main Pump	N/A	N/A	N/A
	b. Head of main pump	N/A	N/A	N/A
	c. Number of main pumps	N/A	N/A	N/A
	d. Jockey pump out put	N/A N/A		N/A
	e. Jockey pump head	N/A	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
	g. Stanby Pump head	N/A N/A		N/A
	h. Auto Starting/Manual stopping	N/A	N/A	N/A
	i. pump house access	N/A N/A		N/A
	2.Terrace level			
	a. Discharge of pump	Old Case	450 LPM Provided	MR
	b. head of the pump	Old Case	35 Mtr Provided	MR
	c. Power supply	Required	Provided	MR
	d. Auto starting of pump	Required	Provided	MR
11			the second	
14	Captive water storage for fire fighting		Not Doguirod	MR
	1. Underground tank capacity	Not Required	Not Required	MR
	a. Draw-off connection	Not Required	Not Required	MR
	b. fire service inlet	Not Required	Not Required	MR
	c. Access to tank	Not Required	Not Required	MR
¥2	2. Over head tank Capacity	Old Case	5,000 ItrProvided	MR
15	Exit Signage.	Required	Provided	IVII t
16	Provision of lifts.			N/A
	1. Pressurization of lift shaft	N/A	N/A	N/A
	2. Pressurization of lift lobby	N/A	N/A	MR
	3. Communication in lift car	Required	Provided	MR
	4. Fireman's grounding switch	Required	Provided	N/A
	5. Lift signage	N/A N/A		
17	Standby power supply	Required	Provided	MR
18				D.//A
	1Total area	N/A	N/A	N/A
		N/A	N/A	N/A

		511	×				
	e control room			NI/A			
	Detector system Panel 2. Flow switch Panel	N/A	N/A	N/A			
		N/A	N/A	N/A			
				N/A			
	3. PA system Panel	N/A	N/A				
	4. Batter backup	N/A	N/A	N/A			
			N/A	N/A			
	5. Building floor plans						
20	Special Fire Protection systems for protection of special risks, if any: N/A						
1	5. Building floor plans	N/A N/A	N/A N/A	N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers......

Accordingly DFA is put up for your approval and signature please.

Signature of the Inspecting Officer Name D.P. BHARDWAJ Designation:- D.O. (South)