GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2013/ 572 9

Dated: 08/07/13

FIRE SAFETY CERTIFICATE

Certified that the Guest House **The Daanish Residency** located at 12A/19, WEA, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus four upper floors. At the time of issuance of NOC to run a guest house the first floor was used as reception, office and five guest rooms. Now the owner of the guest house proposed to use the first floor as reception, office, five guest rooms and the remaining portion of reception as Inhouse/Dinning facilities for guests .Above guest house was issued Fire Safety Certificate by this department vide letter No.F.6/DFS/MS/GH/2013/828 dated 27.02.2013 owned/occupied by Smt. Payal Bajaj. The guest house building was re inspected by the officer concerned of this department on 22.06.2013 in the presence of Sh. Anil Bajaj and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

1. The Addl. Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No. 3440/Addl. C.P./Lic.(H), Dated 21.01.2013)

Out

- 2. Smt. Payal Bajaj (Owner), Guest House The Daanish Residency, 12A/19, WEA, Karol Bagh, New Delhi-110005.
- 3. The Deputy Health Officer, Karol Bagh Zone, North Delhi Municipal Corporation, Anand Prabat, New Delhi-110005. (Re. No. DHO/KBZ/2013/1286 dated 13.05.2013)

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPEC	TION REPORT	The second section of the section of the second section of the section of the second section of the second section of the section of th					
	 Name & address of the building: 	GH The Daan	sh Residence 1	9 ALO LIFA KOLO	10000			
		MEDIACHTAI CO	N.D.05	Bagh				
	1 0-1-1-1-1-1	: N ew Cas e/Renewal						
	actains of Lievious MOC	Letter No. F.6/DFS/MS/GH/10/1184 Date 23.04.10 N/A						
	5. Fire Safety directives letter No5. Date of inspection							
	7. Name of Inspecting Officer	13.02.2013						
	8. Name and designation of officer.	D.O. H.L. Aneja & A.D.O. P.S. Dahiyee						
	9. Year of Construction	Sh. Rajnish Kunar Tha (Manager)						
	10. Applicant's letter No.	er No. 2440 Add Colling to the						
5.	Minimum Standards on fire	NBC BBL Provided at Remarks						
No.	prevention and fire safety U/R 33	Requirement	Provided at site	Remarks	B			
1	Access to building	negatient	Sife	MR/NMR	1			
	 Road width 	Accessible	06mtr	MR				
	 Gate width 		122 cms	MR				
	 Width of internal road 		1 da cms	IVIK				
2.	Number, Width, Type & Arrangemen	t of Exits						
	a. Number of staircases	LATES						
	 Upper Floors 	760						
	 Basements 	- do -	Two	MR COld	(ase			
	b. Width of staircases	~ 200 ~	-do-	mR, -do	-			
	 Upper Floor 		19600 0 6000	h-0 (a) (
	• Basements		126cms, 60cms	MR (Old)	1			
	c. Protection of exits		126 cms, 60 cms	- MR, - do	-			
	 Fire check door 	N/A		The second secon				
	 pressurization 	N/A	A CONTRACTOR OF THE PROPERTY O					
	d. No. of continuous staircases to	19/71						
	terrace	•	One					
	e. Width of Corridor f. Door Size		The state of the s					
	i. Duoi size	magnetic for the comment of a fight of the comment	146 cms, 122 cms	The state of the s				
3.	Compartmentation	A	87cm, x201cms	-				
	The second secon							
	• Fire check door	NIA	-					
	Fire Rating of shaft door		Sealed		-			
		N/A	Jearca	and characters of the second s				
	vocei cuitani	N/A						
	inc bampers	NIA						
4.	Smoke Management System	141/1						
	* Basements	30 a/c per	Exhaust fons					
	 Upper flcors 	hour	are Provided	MR				
	The state of the s		Matural Ventila	Ann MR				

MJS 12 At19, WEA, Sarapwah' Marg, Old Core Karol Bagh, New Delli-110005.

	Pump House Access	NIA		-
	 Terrace level 			
	Discharge of pump	450 LPM	4.56 LPM	MR
	Head of the pump			MR
	Power Supply	30 M Required	30 M Provided	INR
	Auto Starting of pump	/-	- Carrier - Carr	_
4.	Captive Water Storage for fire fighting			
	 Underground tank capacity 	NIA	•	
	Draw-off connection	NIA		7-
	Fire service inlet		Provided	MR
	Access to tank	NIA	_	_
	 Overhead Tank capacity 	_	Socotir	MR, Being a Olo
5.	Exit Signage.	Required	Provided	MR
L6.	Provision of Lifts.	F	5	
	 Pressurization of Lift Shaft 	NIA		_
	 Pressurization of Lift lobby 	NIA		-
	 Communication In lift Car 	74/7	0 11	
	 Fireman's Grounding Switch 		Provided	MR
	Lift Signage	Required - do-	-do-	MR
		- do	-do-	MR
17.	Standby power supply	Required	Provided	MR
18.	. Refuge Area.			
•	> Total Area	N/A		
	Location	NIA		_
19.	Fire Control Room			
13.	Detector System Panel	NIA		
	Flow Switch Panel			
	PA System Panel	NIA		
	Batter backup	NIA	0	
	 Building Floor Plans 	Required	Provided	MR
nandar nanan	0,	MA		
20.	Special Fire Protection System for Protection of special Risks, if any:	NIA	. —	~

ald (as)

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Signature of Inspecting Officer

Name H.L. Aneja

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation AssH. Divisional Officer.