GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

7

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2013/52/63]

Dated: 29/07/13

FIRE SAFETY CERTIFICATE

Certified that the Hotel J.P. Residency (A Unit of ATM Hotels Pvt. Ltd.) located at 15A/28, WEA, Saraswati Marg, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus three upper floors, using basement as storage (Others property), ground floor as reception, office & shops, first & second floor each having 08 guest rooms respectively, third floor having 06 guest rooms with two staff rooms (Total 22 guest rooms), A pantry for staff in temporary tin shed on terrace was issued NOC by 07.09.2010 letter No.F.6/DFS/MS/GH/2010/2604 dated department vide owned/occupied by Sh. Jatin Sachdeva. The guest house building was re-inspected by the officer concerned of this department on 23.07.2013 in the presence of Sh. A.M. Pandian (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.)
 1st floor, P.S., Defence Colony, New Delhi.
 (Re. No.32658/Addl. C.P./Lic.(H), Dated 02.07.2013)
- 2. Sh. Jatin Sachdeva (Owner), Hotel J.P. Residency, 15A/28, W.E.A Saraswati Marg, Karol Bagh, N.D-05.

ML

ay

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPEC	TION REPORT					
	 Name & address of the building: 	Hotel J. P. R.	exidency ICA	28 WEA CONSTI			
	i the of occupancy	Residential (Guest House) Mary, Karol Bagh, N.					
	i type of case :	: New Case/Renewal					
	4. Details of Previous NOC :5. Fire Safety directives letter No :	: Letter No. F. 6 DFS MS 6H 2010 2604 Date 07.00					
	6. Date of inspection	23	3.07.2013				
	7. Name of Inspecting Officer :	A. N. O	P.S. Dahiya	The second secon			
	8. Name and designation of officers	5	8	The district of the sea and th			
	From the building side	Sh. A.	M. Pondian (Manager)			
	9. Year of Construction	Beto	re 2008				
S.	10. Applicant's letter No.	326.58/Add/.		dated 02.07.2013			
No.	Minimum Standards on fire	NBC/BBL	Provided at	Remarks			
1.	prevention and fire safety U/R 33	Requirement	site	MR/NMR			
4.	Access to building		1				
	Road width	Accessible	09mtr	MR			
	Gate width	_	240 cms, 100 cms	MR			
2	• Width of internal road	•	_	_			
2.	Number, Width, Type & Arrangemen	t of Exits					
	a. Number of staircases						
	• Upper Floors	One	One	MR, Being a old Cap			
	Basements	- do -	- do -	-do-			
	b. Width of staircases						
	Upper Floor		128 cms to 132 cms	MR, Being a old Cas			
l	Basements	1	126 cms	- do -			
	c. Protection of exits						
	Fire check door						
	• pressurization						
	d. No. of continuous staircases to						
	e. Width of Corridor	-	One				
	e. Width of Corridor f. Door Size		160 cms				
			92 cm 8 x 202 cms				
3.	Compartmentation						
	Fire check door		·				
	Sealing of electrical shaftsFire Rating of shaft door						
			Sealed				
	Water Curtain						
	• Fire Dampers						
4.	Smoke Management System						
	Basements	20 - /	Exhaust Fans				
	• Upper floors	30 a/c per hour	are Provided MR				
Service decreases a		Inciri	Matural Ventilation MR				

		The second secon		-	
		12 a/c per		1	
		hour			0
5.	Fire Extinguishers				
	Total numbers	Two at each Floor	Poorided	MR	
	Types	WCo, ABC, Co,			
	 IS marking 	ISI marked	-do- ISI Marked	MR	-
6,	First-Aid Hose Reels		1 13 IV wrked	MR	-
	 Total numbers on each floor 	One	Provided	MR	
	 Length of hose reel hose 	30 m	- do -		
	 Nozzle diameter 	5 mm		MR	
7.	Automatic fire detection and alarming		= do:-	MR	
	Type of detectors	System			
	Location of Main Panel			ļ 	
	 Location of Repeater Panel 		*	<u> </u>	
		-			
	Alternate source of powerHooters' Location		D. G. Set of 82.5k	VA +	
8.					
9.	MOEFA	Keq.cired	Provided	MR	
10.	Public Address System	- do-	- do -	MR	
10.	Automatic Sprinkler System		· · · · · · · · · · · · · · · · · · ·		
	• Basement			Old Cape (other property
	 Upper Floor 	*		<u> </u>	
	 Sprinkler above false ceiling 				
11.	Internal Hydrants		!	1	
	 Size of riser/down-comer 		,	+	
	 Number of hydrants per floor 			- 1	
	 Hose Box 		· · ·		77.6.4
12.	Yard Hydrants		J		100
	 Total number of hydrants 				
	 Hose Box 		C. Garage		
13.	Pumping Arrangements	1			
	 Ground Level 			100	
	Discharge of main Pump		-		or a second
	Head of Main pump				
	Number of main pumps				
	Jockey Pump out put				
	Jockey pump head				
	Standby Pump out put				
	Standby Pump Head		:		
	Auto Starting/Manual			-	
	stopping		1		

15A/28, WEA, Saraswati Marg. Karol Bagh, New Delli-110005.

	Pump House AccessTerrace level	-						
	Discharge of pumpHead of the pump	450 LPM	456 LPM	h 10				
	Power Supply	30 M		MR				
	Auto Starting of pump	Required	30M Provided	MR				
	riate starting of pump	V	7001140	(-V)K				
14.	Captive Water Storage for fire fightin	g						
110	 Underground tank capacity 	5						
	Draw-off connection			_				
	Fire service inlet	-						
	Access to tank	,	Provided	_				
	 Overhead Tank capacity 			-				
		5000 Ur	10000 Gr	MR				
15.	Exit Signage.	Required	Provided	MR				
16.	Provision of Lifts.			3				
	Pressurization of Lift Shaft		3					
	Pressurization of Lift lobby	-						
	Communication In lift Car	-						
	• Fireman's Grounding Switch		Provided	h a O				
	Lift Signage	Realisad		MR				
	Lift Signage	Kegwired	-do-	MR				
		-00-	-do-	MR				
17.	Standby power supply	Required	Provided	MR				
18.	Refuge Area.							
	> Total Area							
	Location							
	1		- A -					
19.	Fire Control Room							
19.	Fire Control Room • Detector System Panel							
19.	 Detector System Panel 							
19.	Detector System PanelFlow Switch Panel							
19.	 Detector System Panel Flow Switch Panel PA System Panel 							
19.	 Detector System Panel Flow Switch Panel PA System Panel Batter backup 	Regsuired	Provided	D 4 2				
19.	 Detector System Panel Flow Switch Panel PA System Panel 	Required	Provided	MR				
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	Required	Provided	MR				
19.	 Detector System Panel Flow Switch Panel PA System Panel Batter backup 	Required	Provided	MR				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial-

Name P.S. Dahiyee
Designation Appth. Divisional Officer.

Signature of Inspecting Officer

Name

Designation