GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No. F6/MS/DFS/GH/2013/ NOZ/640

Dated: 29/07/13

FIRE SAFETY CERTIFICATE

Certified that the **Sudershan Palace Guest House** located at 4723, Shora Kothi, Pahar Ganj, New Delhi-110055 comprised of ground floor (02 guest rooms + reception), 1st floor (04 guest rooms), 2nd floor (04 guest rooms) and 3rd floor (04 guest rooms), total 14 guest rooms, owned / occupied by M/s Sudershan Palace guest house have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 12-07-2013 in the presence of Sh. Sunil Bhandari (owner) and that the building / premises, is fit for occupancy class Group A Sub Division A-I Lodging or Rooming Houses with effect from -2-2/2-2-2013 for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 2.9/07/12. at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049 wrt. No.19604-05/Addl.C.P./Lic.(H) New Delhi dated 29-4-2012
- 2. M/s Sudershan Palace Guest House, 4723, Shora Kothi, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Sudershan Palace Guest House, 4723, Shora Kothi, Pahar Ganj, New Delhi-110055

INSPECTION REPORT

1. Name & address of the building : Sudershan Palace Guest House, 4723, Shora Kothi, Pahar

Ganj New Delhi-110055

2. Type of Occupancy : Lodging House

3. Type of Case : New Case

4. Details of previous NOC : Letter No. N/A Dated N/A

5. Fire Safety directives Letter No. : N/A

6. Date of inspection : 12-07-2013

7. Name of the Inspecting Officer : Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side : Sh. Sunil Bhandari (owner)

9. Year of Construction : 2007

10. Applicant's letter No. : Nil dated 22-05-2013

| S No | Minimum standards on fire prevention | BBL | Provided at site | Remarks MR/NMR | | | |
|------|---|-----------------|---------------------------------|----------------|--|--|--|
| | and fire safety U/R 33 | Requirements | (PSS Area) | | | | |
| 1. | Access of building | | | | | | |
| | Road width | N/A | 3 mtrs. Approx. (notified gali) | MR | | | |
| | Gate widthWidth of internal road | | Directly Accessible from Road. | MR | | | |
| | 7, 1401 61 1110111111 1600 | N/A | N/A | N/A | | | |
| 2. | Number, width, Type & Arrangements of exits | | | | | | |
| | a. Number of staircases | | | | | | |
| | Upper floors | 01 | 01 | MR | | | |
| | Basements | N/A | N/A | N/A | | | |
| | b. Width of staircases | | | | | | |
| | Upper floors | 80 cms | 140 cms. | MR | | | |
| | Basements | N/A | N/A | N/A | | | |
| | c. Protection of exits | | L | | | | |
| | Fire check door | N/A | N/A | N/A | | | |
| | Pressurization | N/A | N/A | N/A | | | |
| | d. No of continuous staircase to terrace | 01 | 01 | MR | | | |
| | e. Width Of Corridor | N/A | N/A | N/A | | | |
| | f. Door Size | | 202 cms X 80 cms | N/A | | | |
| 3. | Compartmentation | | | | | | |
| | Fire check door | N/A | N/A | N/A | | | |
| | Sealing of electrical shafts | N/A | N/A | N/A | | | |
| | Fire Rating of shaft door | N/A | N/A | N/A | | | |
| | Water Curtain | N/A | N/A | N/A | | | |
| | Fire Dampers | N/A | N/A | N/A | | | |
| 4. | Smoke managements System | : | | | | | |
| | Basements | 30 a/c per hour | N/A | N/A | | | |

Sudershan Palace Guest House, 4723, Shora Kothi, Pahar Ganj, New Delhi-110055

| , L | Upper floors | 12 a/c per hour | 7 | MR | | |
|-----|---|------------------|----------------------|-------|--|--|
| 5. | Fire Extinguishers | 12 a/c per flour | Ivatural ventilation | IVIK | | |
| J | Total numbers | 10 | 10 | MR | | |
| | • Types | | Water Co2 & | MR | | |
| | Types | | A.B.C. type. | IVIIC | | |
| | IS marking | ISI marked | Provided | MR | | |
| 6. | First – Aid Hose Reels | | 1101144 | 17117 | | |
| ·- | Total numbers on each floor | 01 | 01 | MR | | |
| | • Length of hose reel hose | 30 M | Provided | MR | | |
| | Nozzle diameter | 5 mm | Provided | MR | | |
| 7. | Automatic fire detection and alarming sy | | Trovided | IVIIX | | |
| | Type of detectors | N/A | N/A | N/A | | |
| | Location of Main Panel | N/A | N/A | N/A | | |
| | Location of Repeater Panel | N/A | N/A | N/A | | |
| | Alternate source of power | N/A | N/A | N/A | | |
| | Hooters' Location | N/A | N/A | N/A | | |
| 8. | MOEFA | Not Required | Provided | MR | | |
| 9. | Public Address System | Required | Provided | MR | | |
| 10. | Automatic Sprinkler System | Required | TTOVIGEU | IVIK | | |
| | Basements | N/A | N/A | N/A | | |
| | Upper Floor | N/A | N/A | N/A | | |
| | Sprinkler above false ceiling | N/A | N/A | N/A | | |
| 11. | Internal Hydrants | | 11/11 | IVII | | |
| | Size of riser/down- comer | N/A | N/A | N/A | | |
| | Number of hydrants per floor | N/A | N/A | N/A | | |
| | Hose Box | N/A | N/A | N/A | | |
| 12. | Yard Hydrants | | | | | |
| 12. | Total number of hydrants | N/A | N/A | N/A | | |
| | Hose Box | N/A | N/A | N/A | | |
| 13. | Pumping Arrangements | 11/11 | 11/11 | IVIA | | |
| | Ground Level | | | | | |
| | Discharge of main pump | N/A | N/A | N/A | | |
| | > Head of main pump | N/A | N/A | N/A | | |
| | Number of main pumps | N/A | N/A | N/A | | |
| | > Jockey pump out put | N/A | N/A | N/A | | |
| | > Jockey pump head | N/A | N/A | N/A | | |
| | Standby Pump out put | N/A | N/A | N/A | | |
| | Standby Pump Head | N/A | N/A | N/A | | |
| | auto Staring/Manual stopping | N/A | N/A | N/A | | |
| | Pump House Access | N/A | N/A | N/A | | |
| | Terrace level | | | | | |
| | Discharge of pump | 450 LPM | Provided | MR | | |
| | Head of the pump | 30 Mtrs. | Provided. | MR | | |
| | Power supply | Required | Provided | MR | | |
| | > Auto starting of pump | Required | Provided | MR | | |
| 14. | Captive water Storage for fire fighting | | | | | |
| | Under ground tank capacity | N/A | N/A | N/A | | |
| | Draw of connection | N/A | N/A | N/A | | |
| | Fire service inlet | N/A | N/A | N/A | | |
| | Access to tank | N/A | N/A | N/A | | |
| | Overhead Tank capacity | 5000 Ltrs. | Provided. | MR | | |
| 15 | Exit Signage | Required | Provided | MR | | |
| 16. | Provision of Lifts | | | | | |

| | udershan Palace Guest House, 4723, Shora Kothi, Pahar Ganj, New Delhi-110055 | | | | | |
|-----|---|----------|------------------|-----|--|--|
| Su | dershan Palace Guest House, 4723, Si | N/A | N/A | N/A | | |
| 7 | > Pressurization of Lift Shall | 14/11 | N/A | N/A | | |
| | Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage | N/A | N/A | N/A | | |
| | | N/A | | N/A | | |
| | | N/A | N/A | N/A | | |
| | | N/A | N/A | | | |
| | | Required | Provided(DG Set) | MR | | |
| 7. | Standby power supply | 1 | | | | |
| 8. | Refuge Area > Total area | N/A | N/A | N/A | | |
| | | | N/A | N/A | | |
| | > Location | N/A | IN/A | | | |
| 19. | Fire control room | | N/A | N/A | | |
| 17. | Detector system panel Flow Switch Panel PA System Panel Batter backup | N/A | | N/A | | |
| | | N/A | N/A | N/A | | |
| | | N/A | N/A | | | |
| | | N/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| 20. | Special Fire Protection Systems for | IN/A | | | | |
| | Protection of special Risks, if any; | | | | | |

The fire protection systems provided in the building were test checked and found functional at the time of inspection

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

Name Thorn vis singh youder.
Designation Divisional offices (central)