GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No. F6/MS/DFS/EH/2013/52/660

Dated 0// 68/13

FIRE SAFETY CERTIFICATE

Certified that the M/s Spice Market located at GF-17 -18 & First Floor 18, D-2, Southern Park, District Centre, Saket, New Delhi-110017, comprised of 02 Basements, Ground Floor + Five Upper Floors and the restaurant is running in ground floor & First Floor only was granted FSC by this department vide letter No.F6/DFS/MS/EH/2009/3311 dated 09/11/2009. The premises was re-inspected by the officer concerned of this department on 16/07/13 in the presence of Mr. Goutam and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group – D Assembly Building with effect from 21/22 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 88 of the Delhi Fire Service Rules 2010.

Issued - D/ OR/13 -at New Delhi by.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:- (1) Dy. Health Officer, MCD, South Zone, Green Park, New Delhi.

Aso Bus

- (2) Assistant Commissioner Restaurant Branch.,
 Office of The Commissioner of Excise, Entt. & Tax, Govt. of NCT of Delhi
 L & J Block, I.P. Estate, Vikas Bhawan, New Delhi-110002.
- (3) M/s Spice Market GF-17-18, D-2, Southern Park, District Centre, Saket, New Delhi-110017

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of NBC

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

1.Name & address of the building:-M/s Spice Market, GF-17-18 & First Floor 18, D-2, Southern Park, District Centre, Saket, New Delhi-110017

- 2. Type of occupancy:- Assembly Building, Group D, Restaurant
- 3. Type of case:- Renewal
- 4. Details of previous NOC:-No. F6/DFS/MS/EH/2009/3311 dated 09/11/2009.
- 5. Fire safety directives No.- Nil
- 6. Date of inspection:-16 /07/13
- 7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
- 8. Name & designation of officer From the building side:- Mr. Gautam
- 9. Year of construction:- 2010.
- 10. Applicant's letter No:-Nil dated 03/07/13, Restaurant is running in Ground floor & First floor

S.No	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	Required	Provided	MR			
	2) Gate width	N/A	N/A	MR			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arrangement of Exits						
	A. Number of staircases						
	1. Upper floors	Two	02 No.s	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	1.5 mtrs	Provided	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	Required	Provided	MR			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase to terrace	One	Provided by mall	MR			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	Required	Two Exits Provided	MR			
3.	Compartmentation						
	1) Fire check door	Required	Provided by Mall	MR			
	2) Sealing of electrical shafts	Required	Provided by Mall	MR			
*******************************	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	1) Basements	30 a/c per hour	N/A	N/A			
	2) Upper floors	12 a/c per hour	Mech. Ventilation Provided by Mall	MR			
5.	Fire Extinguishers		<u> </u>	A			
	1) Total numbers		05 Nos.	MR			
	2) Types	ISI Marked	ABC, Co2	MR			
	3) ISI marking		Yes	MR			
6.	First-Aid Hose Reel	Provided and maintained by Mall					
	1) Total number of each floor	do	do	do			
	2) Length of hose reel hose	do	do	do			
	3) Nozzle diameter	do	do	do			

7.	Automatic Fire Detection & Alarming Sys		d and maintained by Mail		13-	
	1) Type of detectors	do	do	- 4	do	
	2) Location of main panel	do	đo	- lé	do	
	3) Location of repeater panel	do	do		do	
	4) Alternate source of power	do	do	i d	do	
	5) Hooter's Location	do	do	i.	do	
B.	MOEFA	Provided a	nd maintained by Mail	5		
9.	Public Address System	Provided and maintained by Mall				
10.	Automatic Sprinkler System	Provided a	Provided and maintained by Mall			
	1) Basement	do	do		do	
	2) Upper floors	do	do		do	
	3) Sprinkler above false ceiling	do	do		do	
11.	Internal Hydrants Provided and maintained by Mall					
	Size of riser/down-comer	do	do		do	
	2) Number of hydrants per floor	do	do		do	
	3) Hose box	do	do		do	
12.	Yard Hydrants	1 40			40	
L de o	1) Total number of hydrants	do	do		do	
	2) Hose box	do	do		do	
13.	Pumping Arrangement		nd maintained by Mall		100	
	1) Ground level	do	do do		do	
		do	do		do	
	a) Discharge of main pump				do	
	b) Head of main pump	do	do		do	
	c) Number of main pump	do	do		do	
	d) Jockey pump out put	do			do	
	e) Jockey pump head	do	do		do	
	f) Stand by pump output	do	do		do	
	g) Stand by pump head	do	do			
	h) Auto starting/Manual stopping	do	do	,	do	
	2) Terrace level	do	do	-	do	
	a) Discharge of pump	do	do		do	
	b) Head of pump	do	do		do	
	c) Power supply	do	do		do	
	d) Auto starting of pump	do	do		do	
14.	Captive Water Storage for Fire Fighting Provided and maintained by Mail					
	Under ground tank capacity	do	do		do	
	a) Draw-off connection	do	do		do	
	b) Fire service inlet	do	do	1	do	
	c) Access to tank	do	do		do	
	d) Over head tank capacity	do	do			
15.	Exit Signage.	Provided a	nd maintained by Mall			
16.	Provision of Lifts.	Provided and maintained by Mall				
	a) Pressurization of lift shaft	do	do		do	
	b) Pressurization of lift lobby	do	do		do	
	c) Communication in lift car	do	do		do	
	d) Fireman's switch	do	do		do	
	e) Lift signage	do	do			
17.	Stand by Power Supply	Provided a	and maintained by Mail		t.	
18.	Refuge Area	Provided and maintained by Mail				
10.	Total area	do	do		do	
	location	do	do		do	
	av emily it	100			1	

9. Fire Control Room a) Detector system panel b) Flow switch panel c) PA system panel do do do do do do do do	do do
a) Detector system panel do do b) Flow switch panel do do c) PA system panel do do	do
b) Flow switch panel do do do c) PA system panel do do do	
c) PA system panel do do	do
c) PA system paner	
do	do
d) Battery backup	do
e) Building floor plan do do 20. Special Fire Protection System for Protection of special Risk, if any:	

The fire protection system provided in the building were checked and found functional at the time of inspection. The shortcomings issued vide letter No.F6/DFS/MS/2013/EH/430 Dated 31/01/2013 have been rectified.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules

Accordingly DFA is put up please.

Signature of the inspecting officer

Name :- D.B. Mukherjee.

Designation :- Assistant Divisional Officer.

Dete 24-7-17
Diary No. 683