GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID: cfohq.dlfire@nic.in

No F 6 / DFS / MS / GH / 2013 / 645

Dated 29/7//3

FIRE SAFETY CERTIFICATE

Certified that **The Grand Park Inn** guest house at **1041/17 Abdul Rehman Road**, **Naiwala**, **Karol Bagh**, **New Delhi** comprised of basement (used for storage purpose), ground floor (reception), 1st to 2nd floor (07 guest rooms at each floor) and 3rd floor (03 guest rooms) total 17 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2010/1640 dated 04-06-2010. The premises was re-inspected by the officer concerned of this department on 26-06-2013 in the presence of Mr. Kalra (owner) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 17 guest rooms with effect from 29/7//3 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on $\frac{29}{7}$ $\frac{12013}{12013}$ at New Delhi by.

(Dr G. C. Misra) Chief Fire Officer Delhi Fire Service Ph – 011-23414333

Copy to:-

1. The Grand Park Inn 1041/17 Abdul Rehman Road, Naiwala, Karol Bagh, New Delhi

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi -110049 w.r.t. letter No 16959 Addl. C.P./Lic(H) New Delhi 11-04-2013.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

State of the second state and a second		Base And Andrews Co.	TION REPORT		S. C.
1. Nam	ne & address of the building :	Grane	1 Parle Inh	1041/17 Aba	dul Rehme
2. Тур е	e of Occupancy :	Render	icrol begli a	der Dell	0 -1
3. Турс	e of Case :	Remain	I Park Inn ierral Bugh a march - (Gruss	F Harm) B	19 +3 Fler
4. Deta	nils of previous NOC :		1 My GH /2012		
		,	1 1115/44/2014	1 But 124 4	10/10
	afety directives Letter No. :	NA.			
Date of	f inspection :	26/6/13	0.1		
Name	of the Inspecting Officer :	ADO	MIR Shar	~	
Name	and designation of Officer			6	
	from the building side	Mr	Kerra Co	when,	
Year o	of Construction :	2007	<u>.</u>		
10. Ap	oplicant's letter No.	16959	102 dol. CP./H	1 dt New	sell my
S No	Minimum standards on fire profire safety U/R 33	evention and	BBL Requirements	Provided at site (PSS Area)	Remarks MR/NMR (P.S.S Area)
1.	Access of building				
	 Road width 		NA	10 mg	MR
	Gate width		2 Mr	2m2	MR
	Width of internal ro		NA	NA	NA
2	Number, width, Type & Arrangements of exits				
	a. Number of staircases		0)		100
	• Upper floors	A 6	01		MR
	· Basements ohu C	antro	01	P	MR
	b.Width of staircases		· 8 M+	147-1871ts.	MR
	Upper floors		K	N	MR
	Basements		NA	NA	NO
	c.Protection of exits		MA	NA	Nn
	• Fire check door		NN	NII	NN
	 Pressurization 		NA	NA	MA
	d.No of continuous stairca	se to terrace	TK THE	P	MR
	e. Width Of Corridor		12 ~ MM	1230	MR
	f. Door Size		NA	NA	NA
3.	Compartmentation				
	Fire check doorSealing of electrical shaftsFire Rating of shaft door				
			1	111-	
	Water Curtain				
	water Curtain				
4	• Fire Dampers Smoke managements System Sm	·m			

	Upper floors	NA	NA	NA			
5	Fire Extinguishers	Annual Control of the	The state of the s				
	• Total numbers 12.	R	P	MR			
	 Total numbers /2. Types ABe, vo. 	R	P	MR			
	 IS marking 	Yes	P	Mn			
5	First – Aid Hose Reels						
	 Total numbers on each floor 	0	P	MR			
	 Length of hose reel hose 	30 M	The second secon	MR			
	Nozzle diameter	osmm	P	mp			
7	Automatic fire detection and alarming system						
	 Type of detectors 		:				
	 Location of Main Panel 						
	 Location of Repeater Panel 	1					
	 Alternate source of power 						
	 Hooters' Location 		The second secon	100			
8	MOEFA	R	P	MR			
9	Public Address System	R	P	mn			
10	Automatic Sprinkler System						
	• Basements	R	P	mr			
	Upper Floor	NR	NP	mn			
	 Sprinkler above false ceiling 	NA	NA	NA			
11	Internal Hydrants			/			
	 Size of riser/down- comer 		and the second				
	 Number of hydrants per floor 	1	Wilder Statement and Committee				
	Hose Box						
12	Yard Hydrants						
	 Total number of hydrants 						
	Hose Box						
13	Pumping Arrangements	The second section of the second section of the second section of the second section section section (section second section (section second section (section second section (section second section s	10				
	o Ground Level						
	 Discharge of main pump 			12			
	 Head of main pump 						
	 Number of main pumps 			The second secon			
	 Jockey pump out put 						
	 Jockey pump head 		Andrew An				
	 Standby Pump out put 						
	 Standby Pump Head 		II.	7 (A)			
	 auto Staring/Manual stopping 						
	 Pump House Access 						
	o Terrace level						
	 Discharge of pump 						
	 Head of the pump 	450 LPM	P	MR			
	 Power supply 	30 M7	P	MR			
	 Auto starting of pump 	K		MR			
14		NA	NA	ND			
14	Captive water Storage for fire fighting	NA	NA	NA			
-	 Under ground tank capacity 		1411	1 4 1)			

	Draw of connectionFire service inlet					
	Access to tank		MA			
	Overhead Tank capacity	5000	P	MR		
15	Exit Signage	R	- b	MR		
16	Provision of Lifts					
	 Pressurization of Lift Shaft Pressurization of lift lobby Communication in lift Car 					
	Fireman's Grounding SwitchLift Signage	P	1			
17	Standby power supply	R	1110	MR		
18	Refuge Area)			
	Total areaLocation					
19	Fire control room					
	Detector system panelFlow Switch Panel					
	PA System Panel					
1 -	Batter backup					
4	 Building Floor Plans 	6		THE THE STREET, AND ASSESSED TO STREET, AND ASSESSED T		
20	Special Fire Protection Systems for Protection of special Risks, if any;	R	ABe, Coz	MR		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 / issue shortcoming as noted at serial numbers. Blely to comprise of

Service Rules 2010 / issue shortcoming as noted at serial numbers. Bledg is composited of Bof Grow Flw with 17 Gust Run. Burnet is we fire Storege propose by other perty:

Signature of the Inspecting Officer

Name:-

Designation:-

Signature of the Inspecting Office

Name:-M.K. Sharma Designation:-A.D.O. (C.C.)