## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No.F6/MS/DFS/EH/2013/52/6/5

Dated: 25/67/13

## FIRE SAFETY CERTIFICATE

Certified that the Hotel Comfort Zone, E-586, Greater Kailash-II, New Delhi-110048 comprised of Basement, Ground Floor + 3 Upper floors (27 Guest Rooms) was granted FSC by this department vide letter No.F6/DFS/MS/EH/2010/1407 dated 12/05/2010. The premises was re-inspected by the officer concerned of this department on 12/07/13 in the presence of Mr. Dinesh Wadhwa and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Residential (Guest House) with effect from 25/02/13—for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 25/07/13—at New Delhi by.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:- (1) Dy. Health Officer, MCD, South Zone Green Park, New Delhi.

> (2) Mr. Dinesh Wadhwa Hotel Comfort Zone E-586, Greater Kailash-II New Delhi-110048

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of BBL.

- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## INSPECTION REPORT

First-Aid Hose Reel

Automatic Fire Detection & Alarming System

- 1. Name & address of the building: Hotel Comfort Zone, E-586, Greater Kailash-II, New Delhi-110048
- 2. Type of occupancy:- Residential (Guest House)
- 3. Type of case: Renewal.
- 4. Details of previous NOC:-No. F6/DFS/MS/EH/2010/1407 dated 12/05/2010.
- Fire safety directives No.- No
- 6. Date of inspection:-12 /07/13
- 7. Name of the inspecting officer: D.B. Mukherjee A.D.O. (BCP) is a seried of the inspecting officer.
- 8. Name & designation of officer From the building side: Mr. Dinesh Wadhwa
- 9. Year of construction:- Nil
- 10. Applicant's letter No:-NIL, dated 13/06/2013

0.11		0	25	Old Case			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	NBC Requirement	Provided at	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	Required	Provided	MR			
	2) Gate width	N/A	N/A state	NO TO BRITISH CO. (C.			
	3)Width of internal road	N/A	N/A VOUS	N/ADDIEG OA/N			
2.	Number, Width Type & Arrangement of Exits on the street of						
	A. Numberiof staircases 4						
	1. Upper floors	Required	Provided 01	Yard Hyam			
	2 Basements	Required	Provided 02 exits	MR			
	B. Width of staircase						
	1. Upper floors	Required	1.25 mtr	MR			
	2. Basements	Required	1.25 mtr & 1mtr	MR			
	C. Protection of exits						
3.	1. Fire check door	Required	Provided	MR			
	2. Pressurization	NA AW	N/A	N/A			
	D. No. of continuous staircase to terrace	Required	Oue drived Ad	MR'C (P			
	E. Width of corridor	Not required	Provided	MR			
	F. Door size	N/A	N/A	N/A			
<b>5.</b>	Compartmentation						
4.	1) Fire check door	N/A	NA	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System						
	1) Basements	30 a/c per hour	Exhaust fan Provided	e water stoAlde			
	2) Upper floors	12 a/c per hour	N/A	NA			
5.	Fire Extinguishers						

R

	1) Total numbers		12 Nos.	MR				
	2) Types	ISI Marked	ABC, Co2 & W.Co2	MR MR				
	3) ISI marking	TENETT MOTO	Yes					
6.	First-Aid Hose Reel		1.100	1 1411 4				
-	1) Total number of each floor	Required	Provided one at each floor	MRGIOL X 9				
	2) Length of hose reel hose	30 m	Yes	MR rest in an				
	3) Nozzle diameter	5 mm	Yes	MRC 10 10 20 E				
7.	Automatic Fire Detection & Alarming System							
	1) Type of detectors	N/A	NA	N/A				
	2) Location of main panel	N/Anenhum 8	N/Aprile and	NA				
	3) Location of repeater panel	SMADING BUT U	N/A	N/A BEEN A				
	4) Alternate source of power	Required	DG Set	MR				
	5) Hooter's Location	NR	Provided	MR				
3.	MOEFA	Required	Provided	MR				
9.	Public Address System	Required	Provided	MR				
10.	Automatic Sprinkler System							
	1) Basement	Required	Provided	MR 22900A				
	2) Upper floors	N/A	N/A	N/A				
	3) Sprinkler above false ceiling	NAUDSA	N/A	N/A DEC				
11.	Internal Hydrants							
	1) Size of riser/down-comer	100 mm.	Provided -	MR W				
	2) Number of hydrants per floor			NumberAW				
	3) Hose box	N/A	N/Asse Tiets	A Numbaya				
12.	Yard Hydrants On the bound bounds 5000 5000 5000 5							
	1) Total number of hydrants	N/A	N/A	N/A				
	2) Hose box on harryona	N/A nes	N/A	NAMES E				
13.								
10.	Pumping Arrangement ORBOT STORY &							
	1) Ground level	N/A mag	N/A	N/A				
	a) Discharge of main pump	N/A	N/A	N/A				
	b) Head of main pump	N/A	N/A	N/A				
	c) Number of main pump	N/A	N/A streets	NA SOT C				
	d) Jockey pump out put	N/A	N/A	Ne ci AVA				
	e) Jockey pump head	N/A AW	N/A	NA 22979				
	f) Stand by pump output	N/A	N/A	NA ULC				
	g) Stand by pump head	N/A	N/A	N/Amaro:				
	h) Auto starting/Manual stopping	N/A	N/A volum	N/A denily				
	2) Terrace level		nons	Compartmen				
	a) Discharge of pump	Required	900 LPM	MR				
	b) Head of pump	Required	30 m	MR DELLE				
	c) Power supply	Required	Electric	MP				
	W	911	Supply &	MR a SIR (C				
	A\V	AW	also by D.G.	· vvater curta				
	N. N. N. A.	AW	Set	agmed and 12				
	d) Auto starting of pump	Required	yes	MR				
14.Capti	ve Water Storage for Fire Fighting	130 310 0	11	Stantinose				
	Under ground tank     capacity	NA S	N/A	N/A Score				
	a) Draw-off connection	N/A	N/A	NA +y=				
	b) Fire service inlet	Required	Provided	MR				
	b) The service fillet	required	Flovided	IMIX				

S No

B.

25				
	c) Access to tank	N/A	N/A	N/A
	<ul> <li>d) Over head tank capacity</li> </ul>	Required	6000 Ltrs	MR
15.	Exit Signage.	Yes	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Yes	Provided DG Set	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	Required	Provided	MR
20.	Special Fire Protection System Risk, if any:	of special	N/A	

The fire protection system provided in the building were checked and found functional at the time of inspection. The shortcomings as issued vide letter no. F6/DFS/MS/2013/GH/1284 dated 03/05/2013 has been rectified.

Accordingly DFA is put up please.

Signature of the inspecting officer

Name: - D.B. Mukherjee.

Designation:- Assistant Divisional Officer (BCP)

