## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

Email ID: - cfowz.dlfire.nic.in

Ph - 011-23414250

No F 6 / DFS / MS / SCHOOL / 2013 / WZ / 686

Dated: 08/08/13

## FIRE SAFETY CERTIFICATE

Certified that the Adharshila Vidyapeeth at CD Block, Pitam Pura, Delhi-88 comprised of Basement + Gound + Three upper floors owned / occupied by the Vaish Aggarwal Educational Society has already been issued Fire Safety Certificate vide letter No F 6 / MS / DFS / 2004 / 3026 dated 15.12.2004 have deemed complied with the fire prevention and fire safety requirements in accordance with Circular issued by Directorate of Education, Govt of NCT of Delhi vide letter No 262-362 dated 17.01.2005 and verified by the officer concerned of Fire Service on 05.07.2013 in the presence of Sh Byomakesh Mishra (Principal) and that the building / premises is fit for occupancy class Educational with effect from.... a8./.58/.13............. for a period of three years subject to conditions printed below.

## Conditions for the validity of Fire Safety Certificate.

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to construction etc shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used strictly as per the provision of Building Bye Laws:
- 6. This Certificate cannot be treated in any case for regularization of unauthorized construction.
- 7. The owner / occupier shall submit a declaration every year in Form K provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

(SH SANTOKH SINGH)
Chief Fire Officer
Delhi Fire Service

Copy to:-

 Sh Byomakesh Mishra (Principal), Adharshila Vidyapeeth, CD Block, Pitam Pura, Delhi - 88

2. The Director Of Edu, Govt. of NCT of Delhi, Old Sectt., Delhi.

ole

INSPECTION REPORT					
1.	Name & address of the building:	Adhar Spila Vidua Peath CD-Rlock			
		Petampura, New Delly - 110088			
2.	Type of Occupancy :	Educational			
3.	Type of Case :	Renewal			
4.	Details of previous NOC	: Letter No: F6/MS/DFS/2004/3026/15.12.04 : DOE eixcular dated 17/01/2005			
5.	Fire Safety directives Letter No.	: DOE execular dalled 1+10+12005			
6	Date of inspection	. 5 / 20 3			
7.	Name of the Inspecting Officer	A.K. JAISWAL			
	Name and designation of Officer				
	from the building side	Byomkerh Mishra (Principal) 2004			
9.	Year of Construction	•			
10	O.Applicant's letter No.:	Nel dated 17/06/2013			

		DD1 13 of 6 1	D	Remarks MR/NMR	
S	Minimum standards on fire	BBL / DOE eight Provided at Requirements 17.1. Site		Remarks MR/MMR	
No 1.	prevention and fire safety U/R 33 Access of building	Requirements			
1.	Road width	Accessible	Provided	MR	
	Gate width	Accessible	Provided	MR	
	Width of internal road	NIA	NIA	NIA	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases				
	Upper floors	4	4	MR	
	Basements	4	4	MR	
	b. Width of staircases			**	
	Upper floors	old case	old Case	old Case	
	Basements	old case	old ase	old Case	
	c. Protection of exits				
	Fire check door				
	• Pressurization		NR_		
	d. No of continuous staircase to terrace	old case	old Case	old Case	
	e. Width Of Corridor	old case	old Osse		
	f. Door Size	old case	old Case	old case	

3.	Compartmentation			
	Fire check door			
	<ul> <li>Sealing of electrical shafts</li> </ul>			
	<ul> <li>Fire Rating of shaft door</li> </ul>		RIG	
	Water Curtain			
	Fire Dampers			
4.				
7.	Smoke managements System  • Basements	30 a/a par haur		
	Busomones	30 a/c per hour	Provided	MR
	Upper floors	12 a/c per hour		
5.	Fire Extinguishers		Deantosky	- MR
	Total numbers	22	2 0	
	• Types		25	IMR
	IS marking	ISI marked	Provided	MR
				1.70
6.	First – Aid Hose Reels	ABCICOL	Paprido	MR
0.	Total numbers on each floor			
	Total numbers on each moor	2 ateach floor	Provided	MR
	<ul> <li>Length of hose reel hose</li> </ul>	30 Mtr.	Provided	h @ A
	Nozzle diameter		1 000000	MR
		6.5 mm	Providual	MA
7.	Automatic fire detection and alarming	g system		
	Type of detectors	Smoke (Audi)	Provided	147 R
	<ul> <li>Location of Main Panel</li> </ul>	0 -		
	T the CD	GF	Provided	MR
	Location of Repeater Panel	GF/AllFloor	Provided	MR
	Alternate source of power	Required	Provided	147 R
	Hooters' Location	Each Flor	Provided	MR
8.	MOEFA			1.1K
9.	Dublic Add G	Regnikoo	Provided	MR
	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basements	Required	Provided	MR
	Upper Floor		7 00 0,00	
		Not Required	of the More	NR
	Sprinkler above false ceiling	Regnined (Aredi)	Provided	MR

11.	Internal Hydrants		×	
	Size of riser/down- comer	100 mm	Provided	MR
	<ul> <li>Number of hydrants per floor</li> </ul>	1	Provided	MR
8	Hose Box		Provided	MR
12.	Yard Hydrants	•		
	Total number of hydrants	NR	Providual	MR
	Hose Box	NR	Provided	MR
13.	Pumping Arrangements		, ,	<u> </u>
	Ground Level			7
	Discharge of main pump			
	> Head of main pump			/
	Number of main pumps			
	> Jockey pump out put		a	
	> Jockey pump head			
	> Standby Pump out put		NA	
	> Standby Pump Head			e .
	> Auto Staring/Manual stopping			
	➤ Pump House Access			
	Terrace level			
	Discharge of pump	900 lpm 180 lpm	povidual	MR
	➤ Head of the pump	50 MH	Provided	MR
	> Power supply	Regnired	Provided	MR
	> Auto starting of pump	Reguined	Pro violed	MYR
14.	Captive water Storage for fire fighting	g		
	Under ground tank capacity	1,00000 lts		MR
	> Draw of connection	Required	provided	MR
	> Fire service inlet	Required	provided	MR
	Access to tank	Reguired	Provided	MR
	Overhead Tank capacity	20,000 lts	provoped	MR
15	Exit Signage	Regnined	Provided	16) R
16.	Provision of Lifts			

	> Pressurization of Lift Shaft		4	
	> Pressurization of lift lobby			
	Communication in lift Car		NA	
	<ul><li>Fireman's Grounding Switch</li></ul>			
	<ul><li>Lift Signage</li></ul>		b	
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area			
	> Total area			
	7 Total area		n 1 A	
e*	> Location		NH	
19.	Fire control room		1	/
	> Detector system panel			
	> Flow Switch Panel			1 10
	> PA System Panel		blie	all
	> Batter backup		of Philip	
- TO	> Building Floor Plans	N		
20.	Special Fire Protection Systems for Protection of special Risks, if any;			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Signature of the Inspecting Officer

Signature of the Inspecting Officer, in E

Name

Ashok. Kr. Jauser

Name

Designation

Designation