GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/EH/2013/\$2/890

Dated: 09/09/13

FIRE SAFETY CERTIFICATE

Certified that Madhuban Restaurant, 18-19, Community Center, PVR Saket, New Delhi-110017 comprised of **Basement, Ground floor** + **03 Upper floors**. The restaurant is running in First Floor only with seating capacity of 140 persons, was granted FSC by this department vide letter No.F6/DFS/MS/EH/2010/1937 dated 30/06/2010. The premises was re-inspected by the officer concerned of this department on 30/08/13 in the presence of Mr.Navin and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group – D Assembly Building (Restaurant) with effect from 25/15/13-------------------------for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued -09/09/13 -- at New Delhi by.

Yours faithfully,

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- (1) Dy. Health Officer, MCD,South Zone,Green Park,New Delhi.
- (2) Assistant Commissioner (Restaurant Branch)
 Office of The Commissioner of Excise, Entt. & Tax, Govt. of NCT of Delhi
 L & J Block, I.P. Estate, Vikas Bhawan, New Delhi-110002.
- (3) M/s Madhuban Restaurant 18-19, Community Center, PVR Saket, New Delhi-110017

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of NBC
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Madhuban Resturant, 18-19, Community Center,

PVR Saket New Delhi - 110017

2. Type of Occupancy

: Assembly Building, Group – D, Restaurant

3. Type of Case

: Renewal

4. Details of previous NOC

: No. F6/DFS/MS/EH/2010/1937 Dated 30-06-2010

5. Fire Safety directives letter No : Nil

6. Date of inspection

: 30/08/2013

7. Name of the Inspecting Officers: ADO D.B.Mukherjee

8. Name and designation of officers from the building side : Mr. Navin

9. Year of Construction

: 2000

10. Applicant's letter No.: Nil dated 30/07/2013 (Basement, Ground Plus Three Upper Floors)

,Restaurent is running in First Floor only

			8	(Old Case)	
S.	Minimum Standards on fire prevention	NBC	Provided at site	Remarks	
No	and fire safety U/R 33	Requirement		MR/NMR	
1	Access to building				
	Road width	Required	Provided	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	Upper Floors	Required	02	MR	
	• Basements	N/A	N/A	N/A	
	b. Width of staircases	Vidth of staircases			
	Upper Floors	Required	1.18mtr & 1.35 mtrs	MR (Old Case)	
	• Basements	N/A	N/A	N/A	
	c. Protection of exits				
	• Fire check door	Required	Provided	MR	
	 Pressurization 	N/A	N/A	N/A	
	e. No. of continuous staircases to terrace	01	01	MR	
	g. Width of Corridor	N/A	N/A	N/A	
	h. Door Size	Required	02 Nos. 0.85mtr each & one 1mtr	MR (Old Case)	

N-7

3	Compartmentation.	5 to 10 to 1	9		
	Fire check door	Required	D	CO.	
	 Sealing of electrical shafts 		Provided	MR	
	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.	N/A	N/A	N/A	
	Basements				
	Upper floors	30 a/c per hor		N/A	
5		12 a/c per hou	ır Exhaust Fan	MR	
	Fire Extinguishers				
-	• Total numbers		Provided 05 Nos.	. MR	
	• Types	ISI marked		MR	
6	• ISI marking		Provided	MR	
	First-Aid Hose Reels.			1411	
	 Total numbers on each floor 	One	Provided	MR	
	 Length of hose reel hose 	30 m	Provided	MR	
	 Nozzle diameter 	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	• Type of detectors	N/A	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of powerHooters' Location	N/A	N/A	N/A	
N		N/A	N/A	N/A	
-	MOEFA	Required	Provided	MR	
	ublic Address System.	Required	Provided	MR	
) A	utomatic Sprinkler System			IVIK	
	Basement	N/A	N/A	N/A	
	 Upper Floor Sprinkler above false ceiling	Required	Provided	MR	
In		N/A	N/A	N/A	
In	ternal Hydrants				
	Size of riser/down-comer Number of hydronts are G	100 mm	Provided	MR	
	Number of hydrants per floorHose Box	One	Provided	MR	
	6	One	Provided	MR	

Yard Hydrants.			
Total number of hydrants	N/A	N/A	N/A
Hose Box	N/A	N/A	N/A
3 Pumping Arrangements			<u>, </u>
Ground Level			
Discharge of main Pump	N/A	N/A	N/A
Head of Main pump	N/A	N/A	N/A
Number of main pumps	N/A	N/A	N/A
Jockey Pump out put	N/A	N/A	N/A
Jockey pump head	N/A	N/A	N/A
Standby Pump out put	N/A	N/A	N/A
Standby Pump Head	N/A	N/A	N/A
➤ Auto Starting/ Manual stopping	N/A	N/A	N/A
Pump House Access	N/A	N/A	N/A
Terrace level			I
Discharge of pump	450 LPM	450 LPM	MR
➤ Head of the pump	Required	39 mtrs	MR
> Power Supply	Required	Provided	MR
> Auto Starting of pump	Required	Provided	MR
Captive Water Storage for fire fighting			
 Underground tank capacity 	N/A	N/A	N/A
> Draw-off connection	N/A	N/A	N/A
Fire service inlet	N/A	N/A	N/A
> Access to tank	N/A	N/A	N/A
 Overhead Tank capacity 	Required	5000 ltrs.	MR
Exit Signage.	Required	Provided	MR,
Provision of Lifts.			
Pressurization of Lift Shaft	N/A	N/A	N/A
Pressurization of Lift lobby	N/A	N/A	N/A
Communication In lift Car	N/A	N/A	N/A
Fireman's Grounding Switch	N/A	N/A	N/A
• Lift Signage	N/A	N/A	N/A
Standby power supply	Required	Provided, DG Set	MR

18	Refuge Area.			3		
	Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	 Building Floor Plans 	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/------

Accordingly DFA is put up for sign. if approved please.

Do (South)

Signature of the Inspecting Officer

Name: D.B.Mukherjee

Designation: - Assistant Divisional Officer (BCP)