GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: <u>cfohq.dlfire@nic.in</u>, <u>Tel:-</u> 011-23414333

No. f6/0 F5/ms/school/2013/52/923 Dated: 17/09/13

FIRE SAFETY CERTIFICATE

Certified that Jasola Public School, located at 203, Jasola, New Delhi-110025 comprised of ground floor only was inspected by the officer concerned of this department on 26.08.2013 in presence of Mr. Pankaj Panwar, Manager of the school and found that the School management have complied with the fire prevention and fire safety requirements in accordance with the Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 issued by the Directorate of Education and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the below mentioned conditions.

Issued on $-\frac{1}{2}$ / $\frac{3}{2}$ at New Delhi by.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

- 1. The Principal, Jasola Public School, located at 203, Jasola, New Delhi-110025.
- 2. The Directorate of Education, Old Secretariat, Delhi-110006

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : Jasola Public School, 203, Jasola, New Delhi-110025.

2. Type of Occupancy

: Educational

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No : Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011

6. Date of inspection

: 26.08.2013

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(M.Road)

8. Name and designation of officers

from the building side

: Pankaj Panwar, Manager

9. Year of Construction

: 2007

10. Applicant's letter No.

: NHPS/1/FS dated: 05/08/2013.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
2	Road width	06 mts	More than 06 mts	MR	
	Gate width	06 mts	06 mts	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, Width, Type & Arrangement	of Exits	7.		
	a. Number of staircases				
	Upper Floors	N/A	N/A	N/A	
	Basements	N/A	N/A	N/A	
	b. Width of staircases				
	* 8	N/A	N/A	N/A	
	Upper Floors	N/A	N/A	N/A	
	Basements	N/A	N/A	N/A	
	c. Protection of exits	N/A	N/A	N/A	
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	e. No. of continuous staircases to terrace	N/A	N/A	N/A	
	g. Width of Corridor	N/A	N/A	N/A	
	h. Door Size	N/A	N/A	N/A	
3	Compartmentation.	Not required	y s		
	Fire check door	N/A	N/A	N/A	

M	V
- 1	

	• Size of riser/down-comer	N/A	N/A	N/A	
11 Int	ternal Hydrants	DIA	27/4	77/4	
	Sprinkler above false ceiling	N/A	N/A	N/A	
	Upper Floor Sprinkler above false sailing	N/A	N/A	N/A	
	• Basement	N/A	N/A	N/A	
0 Au	tomatic Sprinkler System	27/4	DT/A	77/4	
Pu	blic Address System.	N/A	N/A	N/A	
MO	OEFA	N/A	N/A	N/A	
	- Hoolers Location	N/A	N/A	N/A	
	 Hooters' Location 	N/A	N/A	N/A	
2 ⁶	Alternate source of power	N/A	N/A	N/A	
8	 Location of Nam Panel Location of Repeater Panel 	5			
	 Location of Main Panel 	N/A	N/A	N/A	
	Type of detectors	N/A	N/A	N/A	
Au	Automatic fire detection and alarming system. Not required				
	 Nozzle diameter 	5 mm	N/A	N/A	
N N	 Length of hose reel hose 	30 m	N/A	N/A	
LII	Total numbers on each floor	01	N/A	N/A	
Fir	*st-Aid Hose Reels.	Tot manea	Trovided	IVIIX	
8	TypesIS marking	ISI marked	Provided Provided	MR MR	
	• Total numbers	04 nos.	Provided	MR	
Fir	e Extinguishers	04 nos	Drovidad	MD	
			N/A	N/A	
	• Upper floors	12 a/c per hour	NT/A	NT/A	
	• Basements	30 a/c per hour	N/A	N/A	
Sm	oke Management System.		-		
	• Fire Dampers	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Rating of shaft door	N/A	N/A	N/A	
	 Sealing of electrical shafts 	N/A	N/A	N/A	

飯

	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.			
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements		9	
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/ Manual	N/A	N/A	N/A
	stopping	N/A	N/A	N/A
	> Pump House Access		1771	17/11
	Terrace levelDischarge of pump	N/A	N/A	N/A
	Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for fire fighting	σ		
	Underground tank capacity	N/A	N/A	N/A
6	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
2 25 (1) 20	 Overhead Tank capacity 	N/A	N/A	N/A
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Not Applica	9	1
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A



My

	T .				
e s	Communication In lift Car	N/A	N/A	N/A	
× ×	Fireman's Grounding Switch	N/A	N/A	N/A	
20	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18 Refuge Area.				8	
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	 PA System Panel 	N/A	N/A	N/A	
, a	 Batter backup 	N/A	N/A	N/A	
99 S	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 ABC type fire extinguisher is provided near elect. Panel.	MR	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under rule 35 of the Delhi Fire Service rules 2010

The school building is comprised of ground floor having total 09 rooms (07 class rooms + 01 office + 01 store etc).

Signature of the Inspecting Officer Name (M.K. CHATTOPADHYAY)

Designation: - A. D.O (M. Road)

12-4-17

DO(57) / 10/9/13