

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI-110001.

E-mail:- [cfohq.dfire@nic.in](mailto:cfohq.dfire@nic.in)

Fax:- 011-23412593

No. F.6/DFS/MS/EH/2013/52/938

Dated: 20/08/13

**FIRE SAFETY CERTIFICATE**

Certified that the **M/S Mehphil Restaurant** located at WZ-40/ S-1 & WZ-41/ S-3 Meenakshi Garden, New Delhi-110018. The building is comprised of basement, ground floor plus three upper floors. The restaurant is running at Ground, First and Second floor of above said building. The restaurant having two exits was issued NOC by this department vide letter F.6/DFS/MS/EH/2010/2418 dated 18.08.2010 owned/occupied by the management. The Restaurant was re-inspected by the officers concerned of this department on 06.09.2013 in the presence of Sh Rajesh Kumar (Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Ground, First and Second floor only) is fit for occupancy class Group D assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....20/08/13.....at New Delhi.

  
(DR. G.C. MISRA)  
CHIEF FIRE OFFICER  
DELHI FIRE SERVICE  
Ph:- 011-2341433

Copy to:-

- 1 The Manager,  
Mehphil Restaurant,  
WZ-40/ S-1 & WZ-41/ S-3,  
Meenakshi Garden, New Delhi-110018.

Following fire safety directives must be adhered to –

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)

N/11

Basement, Ground floor plus three upper floors

Restaurant at Ground floor, 1st floor &amp; 2nd floor only

## INSPECTION REPORT

1. Name & address of the building : Mehphil Restaurant, WZ-40/S-1, 41/S-3, Meenakshi Garden, New Delhi-18.
2. Type of Occupancy : Assembly
3. Type of Case : New Case/Renewal
4. Details of Previous NOC : Letter No. F6/DFS/MS/EH/2010/2418 Date 18/09/2010
5. Fire Safety directives letter No : \_\_\_\_\_
6. Date of inspection : 06-09-2013
7. Name of Inspecting Officer : ADO Sandeep Duggal
8. Name and designation of officers  
From the building side : Sh Rajesh Kumar (Manager)
9. Year of Construction : 2001-02
10. Applicant's letter No. : Nil dated Nil

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> <li>Road width</li> <li>Gate width</li> <li>Width of internal road</li> </ul>	18 mtr — —	18 mtr 120 cm —	MR MR (old case) —
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> <li>Upper Floors</li> <li>Basements</li> </ul>	02 No's 02 No's	02 No's 02 No's	MR MR
	b. Width of staircases			
	<ul style="list-style-type: none"> <li>Upper Floor</li> <li>Basements</li> </ul>	— —	100 & 95 cms 115 & 100 cms	MR (old case) —do—
	c. Protection of exits			
	<ul style="list-style-type: none"> <li>Fire check door</li> <li>pressurization</li> </ul>	— —	— —	— —
	d. No. of continuous staircases to terrace			
		—	01	—
	e. Width of Corridor			
		—	115 cms	—
	f. Door Size			
		—	1st floor - 85 x 215 cm 2nd floor - 172 x 226 cm	—
3.	Compartmentation			
	<ul style="list-style-type: none"> <li>Fire check door</li> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> <li>Fire Dampers</li> </ul>	— — — — —	— Sealed — — —	— — — — —
4.	Smoke Management System			
	<ul style="list-style-type: none"> <li>Basements</li> <li>Upper floors</li> </ul>	30 a/c per hour —	Exhaust Fans Natural Ventilation	MR MR

Saw

N/12

		12 a/c per hour	—	—
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> <li>Total numbers</li> <li>Types</li> <li>IS marking</li> </ul>	03 of each floor CO <sub>2</sub> /ABC ISI marked	Provided <del>do</del> ISI marked	MR MR MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	one 30 m 5 mm	Provided <del>do</del> <del>do</del>	MR MR MR
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> <li>Type of detectors</li> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>	—	—	—
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> <li>Basement</li> <li>Upper Floor</li> <li>Sprinkler above false ceiling</li> </ul>	Required <del>Required</del>	Provided Provided	MR MR
11.	Internal Hydrants			
	<ul style="list-style-type: none"> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	100 mm one one	Provided <del>do</del> <del>do</del>	MR MR MR
12.	Yard Hydrants			
	<ul style="list-style-type: none"> <li>Total number of hydrants</li> <li>Hose Box</li> </ul>	—	—	—
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> <li>Ground Level</li> <li>➤ Discharge of main Pump</li> <li>➤ Head of Main pump</li> <li>➤ Number of main pumps</li> <li>➤ Jockey Pump out put</li> <li>➤ Jockey pump head</li> <li>➤ Standby Pump out put</li> <li>➤ Standby Pump Head</li> <li>➤ Auto Starting/Manual stopping</li> </ul>	—	—	—

SAN

N/13

Mehphil Restaurant, W2-40/s-1, 41/s-3, Meenakshi Garden,  
New Delhi - 110018

	<ul style="list-style-type: none"> <li>➤ Pump House Access</li> <li>• Terrace level</li> <li>➤ Discharge of pump</li> <li>➤ Head of the pump</li> <li>➤ Power Supply</li> <li>➤ Auto Starting of pump</li> </ul>	—	—	—
		—	450 UPM	MR (Being old case)
		—	40 mts	MR (Being old case)
		—	—	—
<b>14.</b>	<b>Captive Water Storage for fire fighting</b>			
	<ul style="list-style-type: none"> <li>• Underground tank capacity</li> <li>➤ Draw-off connection</li> <li>➤ Fire service inlet</li> <li>➤ Access to tank</li> <li>• Overhead Tank capacity</li> </ul>	—	—	—
		—	—	—
		Required	Provided	MR
		—	—	—
		— <sup>Sam</sup>	10000 lts	MR (Being old case)
<b>15.</b>	<b>Exit Signage.</b>	Required	Provided	MR
<b>16.</b>	<b>Provision of Lifts:</b>			
	<ul style="list-style-type: none"> <li>• Pressurization of Lift Shaft</li> <li>• Pressurization of Lift lobby</li> <li>• Communication In lift Car</li> <li>• Fireman's Grounding Switch</li> <li>• Lift Signage</li> </ul>	—	—	—
		—	—	—
		—	Provided	—
		—	Provided	—
		—	Provided	—
<b>17.</b>	<b>Standby power supply</b>	Required	62.5 KVA	MR
<b>18.</b>	<b>Refuge Area.</b>			
	<ul style="list-style-type: none"> <li>➤ Total Area</li> <li>➤ Location</li> </ul>	—	—	—
		—	—	—
<b>19.</b>	<b>Fire Control Room</b>			
	<ul style="list-style-type: none"> <li>• Detector System Panel</li> <li>• Flow Switch Panel</li> <li>• PA System Panel</li> <li>• Batter backup</li> <li>• Building Floor Plans</li> </ul>	—	—	—
		—	—	—
		—	—	—
		—	—	—
		—	—	—
<b>20.</b>	<b>Special Fire Protection System for Protection of special Risks, if any:</b>	—	—	—

N/14

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to <sup>renewal</sup> grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....



~~Sandeep~~  
13/9/13

Signature of Inspecting Officer

Name Sandeep Duggal

Designation Asst. Divisional officer

Signature of Inspecting Officer

Name

Designation