GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/EH/2013/ \$2/937

Dated: 20/09/13

FIRE SAFETY CERTIFICATE

Certified that the M/S Om Sweets Pvt. Ltd located at GL-23 Shaheed Bhagat Singh Marg, Jail Road, New Delhi-110064. The building is comprised of basement, ground floor plus three upper floors. The restaurant is running at First floor only of above said building. The restaurant having two exits was issued NOC by this department vide letter F.6/DFS/MS/EH/2010/1835 dated 21.06.2010 owned/occupied by the management. The Restaurant was re-inspected by the officers concerned of this department on 06.09.2013 in the presence of Sh Anand Mohan Thakur (Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (first floor only) is fit for occupancy class Group D assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 20/09/13 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Jur

Copy to:-

- The Manager,
 Om Sweets Pvt. Ltd.,
 GL-23, Shaheed Bhagat Singh Marg (Jail Road),
 Hari Nagar, New Delhi-110064.
- The Dy.Health Officer, South Delhi Municipal Corporation, West Zone, New Delhi. (Ref. No. DHO/WZ/1752 dated 14.06.2013)

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

Basement, around floor plus three upper floors. (Restaurant running at first floor enty).

	INSPEC	TION REPORT					
	1. Name & address of the building	Om Curch Pu	4 114 61 22 00	1 101 111			
	1. Name & address of the building: om Sweets Pvt. 1td, GL-23, Shaheed Bhagat Singh M. 2. Type of Occupancy Assembly. (Tailfood), Han Nagar, New Delvi-41006						
	16000000	New Casa/Pana	real	1 WEN THEM THOSE			
=	1 D 1 11 6	New Case/Renewal					
	5. Fire Safety directives letter No :	Safety directives letter No. :					
	6. Date of inspection	06 40 5					
1	7. Name of Inspecting Officer	06-09-2013					
1	8. Name and designation of officers	ADO San	deep Duggol				
	From the building side :		1 - 5				
	9. Year of Construction .	209-2010	chan Thakus (N	lanager)			
	10. Applicant's letter No.	Noil date	The same of the sa	- Kanada			
5.	Minimum Standards on fire	NBC NBC					
No.	prevention and fire safety U/R 33		Provided at	Remarks			
1.	Access to building	Requirement	site	MR/NMR			
-	Road width						
	Gate width	12 mm	12 mm	MR			
	• Width of internal road	_	3 mhz	MR			
2.	Number Width The Control						
	Number, Width, Type & Arrangement a. Number of staircases	of Exits					
		Δ.		1 1			
	• Upper Floors	02 NO'S	02 NO'S	ML			
	Basements Width of staircases	02 NO'S	02 NOS	MR			
	1 11						
	Upper Floor		1st - 150 to 111 cms 2nd - 85 cms	MR (Beingolocose)			
	Basements	6.00	1st - 130 cms 2nd - 85 cms	MR (Beingold case)			
	c. Protection of exits	3	2ng - 85 CMS	The Gengola case)			
	Fire check door	Required	Provided	440			
	• pressurization	- Tegative Col	Tievided	MR			
	d. Not of continuous staircases to		N 1 5 5 1 N	·.			
	terrace		0	::			
	e. Width of Corridor	1 14	160 cms				
	f. Door Size		4	- CO - A			
3.			TWO 92 X 210 CMS \$ NOS (15 X 210 CMS)	mp (Being old:)			
٥,	Compartmentation			- (0.8)			
	Fire check door	Reguerad	An 10 1	4.0			
	 Sealing of electrical shafts 	Keguired	provided	MR			
	Fire Rating of shaft door		Sealed	-			
	Water Curtain			-			
	Fire Dampers						
4.							
7.	Smoke Management System		and the state of t				
	 Basements 	30 a/c per	Exhaust fans	A . O			
	Upper floors	hour		MR			
			Natural Ventilation	n MR			

	N17 100%	III		₹.
		12 a/c per hour		
5.	Fire Extinguishers			
	Total numbers	03 at each floor	Provided	1 1
	Types	CO2/ABC		MR
;	 IS marking 	ISI marked	Isi marked	MR
6.	First-Aid Hose Reels		151 marked	MR
	 Total numbers on each floor 	one	Provided	21.1
	 Length of hose reel hose 	30 m	1100,0100	MR
1	Nozzle diameter	5 mm	00	
7.	Automatic fire detection and alarming	1 1 1	a_	MR
	Type of detectors	Smoke delecto	Provided	MR
1	 Location of Main Panel 		Ground Hoor	MK
	 Location of Repeater Panel 		9104110 HOOY	
	 Alternate source of power 	Required	Provided	MR
100	 Hooters' Location 	710.0		- NO. K
8.	MOEFA	0 - 3 - 0	Near Steircase	
9.	Public Address System	Required	Provided Provided	MR
10.	Automätic Sprinkler System	Required	roovicedi	MR
	Basement	Regional	Pro vided	MR
	Upper Floor	Required **	Presided	
	 Sprinkler above false ceiling 	Required	Provided	MR
11.	Internal Hydrants	required	1800 TUCA	
	Size of riser/down-comer	100 min	Provided	MK
	 Number of hydrants per floor 	one	Provided	- 410
	 Hose Box 	ane	Provided	410
12.	Yard Hydrants		1000000	PIR
	 Total number of hydrants 			
	* Hose Box			
13.	Pumping Arrangements			
	Ground Level			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Discharge of main Pump	1620 Ym	1620 Um	MR
	> Head of Main pump	70 mbg	. 70 mpg	MR
	Number of main pumps	one	Poorided	ML
	> Jockey Pump out put	180 Um	180 Um	MR
	> Jockey pump head	40 my 52	40 mby saw	MR
	Standby Pump out putStandby Pump Head	1620 Um	1620 Um	MA
	The state of the s	70 mbg		0 00
	> Auto Starting/Manual stopping	Required	70 mm	MR
	Stopping :	WE THE PARTY OF	Provided.	MR

Om Sweets Pot Ord, GL-23, Shaheed Bhagat Singh Mary, Jail Road, Hari Nagar, New Delhi-110064

	1	,	0	1,000 9		
W 10	Pump House Access	Required	foorided	MR		
	Terrace level	V				
	Discharge of pump	900 Um	900 Um	MR		
	> Head of the pump	40 mm	40 mm	MR		
	Power Supply		70 7417	MIX		
	> Auto Starting of pump	1.	5	The state of the s		
14.	Captive Water Storage for fire fighting			· · · · · · · · · · · · · · · · · · ·		
	 Underground tank capacity 	70,000 ly	70,000 LM	MR		
	Draw-off connection	Regumed	Provided	MR		
	Fire service inlet	Required	frovided	MR		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	10000 lh	Provided	MR		
1.	11	100000	1100,000	MIL		
15.	Exit Signage.	Required	foorided	HR		
16.	Provision of Lifts.		may (see			
	 Pressurization of Lift Shaft 					
	Pressurization of Lift lobby					
	Communication In lift Car		Provided			
	• * Fireman's Grounding Switch	0 - 1		110		
	Lift Signage	Required	Provided	MR		
			Provided	MR		
17.	Standby power supply	Required	8	MR		
-7.	Standby power suppry			1111		
18.	Refuge Area.					
	> Total Area					
	> Location					
19.	Fire Control Room					
	Detector System Panel			1		
	Flow Switch Panel					
	PA System Panel			1		
	Batter backup					
	Building Floor Plans					
20.	Special Fire Protection System for					
20.	Special Fire Protection System for Protection of special Risks, if any:					

Sam

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Note: - Management has rectified all the short caning of this dept. letter no f6/DFS/MS/EH/2013/1787 dated 12-07-2013. FSC renewed is recommended please

Signature of Inspecting Officer

Name Sander Duggal
Designation ASSA. Divisional Officer

Signature of Inspecting Officer

Name

Designation