## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, Email: <a href="mailto:cfohq.dlfire@nic.in">cfohq.dlfire@nic.in</a>, Tel:- 011-23414333

NO.F6/DFS/MS/school/2013/ ND2/ 970

Dated: 25/09/13

## FIRE SAFETY CERTIFICATE

Certified that Govt Girls Sr. Sec. School, Nicholson Road, Mori Gate Delhi-6 comprised of ground plus two upper floors. The school premises was inspected by the officer concerned of this department on 30.08.2013 in presence of Sh. A. K. Chaubey, HOS/ V. Principal of the school and found that the School management have complied with fire prevention and fire safety requirements in accordance with the Delhi Fire Service Act-2010 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the following conditions.

Issued on -- 25/29/13 -- at New Delhi by.

(Dr. G.C. Misra) **Chief Fire Officer Delhi Fire Service** S

Copy to: -

- 1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-54.
- 2. The Govt Girls Sr. Sec School, Nicholson Road, Mori Gate Delhi-6

## Conditions for the validity of fire safety certificate

- a. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- b. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- c. The trained staff should be available round the clock.
- d. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- e. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- f. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

## INSPECTION REPORT

1. Name & address of the building: Govl. Girls Sr. Sec School, Nicholson Road, Delhi-

2. Type of Occupancy <u>Educationa</u> G+2

3. Type of Case Educatina New

4. Details of previous NOC : Letter No - 711L

5. Fire Safety directives Letter No. : Elk/Estate /sc/Fire Safety /2011/3298 to3398 Dated 01/03/2011

6. Date of inspection 30 08 2013

7. Name of the Inspecting Officer: Sanjay Kumar Comor

8. Name and designation of Officer Sh.A.K. Choubey (Hos)

9. Year of Construction 1950

10. Applicant's letter No. : 66.55 5/17 th. Rd 2013-14 216 Dt. 30/8/2013

5	Minimum standards on fire	BBL	Provided at	Remarks MR/NMR	
Vo	prevention and fire safety U/R 33	Requirements	site	Remarks WIR/NMR	
1.	Access of building		Site		
	Road width	Accessible to fire engine	2 mli (approx) Provided	MR	
	Gate width	HIA	FILA	FI IA	
	Width of internal road	HIA	FILA	rila	
2	Number, width, Type & Arrangemen	nts of exits			
	a. Number of staircases		**************************************	A	
	Upper floors	One	Two Provided	mR	
	Basements	MIA	HIA	50/0	
	b. Width of staircases		8		
	Upper floors	1.5 mt.	Provided	MR	
	Basements	MIA	HIA	MIA	
	c. Protection of exits	q			
	Fire check door	M/A	H/A	18/4	
	Pressurization	11/4	HIA	MA	
4.	d. No of continuous staircase to terrace	One	Provided	MA	
	e. Width Of Corridor	r /A	H/A	H /A ···	
	f. Door Size	MIA	MA	HIA	

3.	Compartmentation				
	Fire check door		8.0		
	Sealing of electrical shafts				
	Fire Rating of shaft door	· · · · · · · · · · · · · · · · · · ·	N		
	Water Curtain		0		
	Fire Dampers		1		
	The Dampers				
4.	Smoke managements System				
	Basements	30 a/c per hour	71		
ii.	Upper floors	12 a/c per hour		A	
5.	Fire Extinguishers				
	<ul><li> Total numbers</li><li> Types</li></ul>	18	26 nos. Provided	mR	
	IS marking	ABC & W. Co 2  ISI marked	Provided	IN 8	
			Provided	MR	
6.	First – Aid Hose Reels			7	
	Total numbers on each floor	one	Two Provided	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 mtr	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7.	Automatic fire detection and alarming system				
	Type of detectors				
	Location of Main Panel				
	Location of Repeater Panel				
	Alternate source of power	F 2	N		
	Hooters' Location	40 40 40	A	5	
8.	MOEFA		-		
9.	Public Address System			9	
10.	Automatic Sprinkler System			A source services and a service service service service services and a service service service services and a service servi	
122	Basements		N		
	Upper Floor		A		

11	Sprinkler above false ceiling	N/A	MIA	11/A
11.	Internal Hydrants			
	<ul> <li>Size of riser/down- comer</li> </ul>		THE STATE OF STATE	
	<ul> <li>Number of hydrants per</li> </ul>		N	
	floor		0	
			1	
10	Hose Box			
12.	Yard Hydrants	-		
	<ul> <li>Total number of hydrants</li> </ul>	MIA	MIA	# 1A
10	Hose Box	MIA	MIA	MIA
13.	Pumping Arrangements	The state of the s	A major open to the same transfer over the same of the	A CONTRACTOR OF THE PROPERTY O
	Ground Level			
	<ul> <li>Discharge of main pump</li> </ul>			
		4		
	Head of main pump			/
	Number of main pumps			
distance	t.	•		
	Jockey pump out put			
	, , , , , , , , , , , , , , , , , , ,			
	Jockey pump head		N	
			11	
	Standby Pump out put		0	
			A	9 5
	Standby Pump Head			7
	Auto Staring/Manual			
	stopping			
	F 77			G
	Pump House Access		- &	
	Terrace level	-		8 1/2
	Discharge			A The same
	Discharge of pump	450 LPM	0	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )
	I I and a Cala		Provided	MR
	Head of the pump	40 M	Provided	Fra. Co.
	D		14001000	MR
	Power supply	Required	Provided	MR
	Avita atantina afa	Management of the state of the		
4.	Auto starting of pump	rt /A	HIR	P IA
-F.	Captive water Storage for fire fighting	5	T	
	Under ground tank capacity	the contract of the contract o		
	Draw of connection			
	Fire service inlet			
	Access to tank			
	Overhead Tank capacity	10,000 lms	5000X2 1tm	MR
5	Fi+ Ci		Provided	
5	Exit Signage	Required	Provided	00
	. 1	unred	rovioud	MR

Gout. Garls Sr. Sec. School, Micholson Road, Delhi-6

16.	Provision of Lifts	E.B.		
-	Pressurization of Lift Shaft		9 9	
Total Angelogia de la Carta de	Pressurization of lift lobby			
	<ul> <li>Communication in lift Car</li> </ul>		H /	
	Fireman's Grounding Switch		A	
	➢ Lift Signage			
17.	Standby power supply		a 6	8
18.	Refuge Area			
	> Total area		74 _	
	> Location		A	
19.	Fire control room			
	> Detector system panel			
	> Flow Switch Panel			
	> PA System Panel			/
	> Batter backup		A	
	Building Floor Plans			
20.	Special Fire Protection Systems for Protection of special Risks, if any;	/-	_	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the 2010/issue shortcomings as noted at serial numbers

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name Sanjay Kumar Tomar

Name

Designation
DOCCO) Submitted please 9-13

Designation Asstt. Dirnl. Officer