GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

Ph.23414333,Fax: 23412593, E-mail: cfohq.dlfire@nic.in

No. 66/065/ms/school/2013/M02/983

Dated: 27/09/13

FIRE SAFETY CERTIFICATE

Certified that the Greenway Modern School at Between Pockets A & D Dilshad Garden, Delhi 95. Comprised of basement, ground plus four upper floors owned/occupied by Greenway Modern School have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 06.09.13 & 19.09.13 in the presence of Sh.K.K.Sachdeva, Manager, of the school and that the building is fit for occupancy class B' Educational Building with effect from......for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on 2.7/13..at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

To,

Sh.K.K.Sachdeva(Manager) Greenway Modern School Between Pockets A & D Dilshad Garden, Delhi 95

Copy:-

The Director of Education Directorate of Education, Lucknow Road, Delhi -54.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall

be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. Basement shall be used as per B.B.L.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Greenway Modern School at Between Pockets

A & D Dilshad Garden, Delhi 95.

2. Building is comprised of

: Basement, Ground + 4, upper floors.

3. Type of Occupancy

: Educational

4. Type of Case

: New

5. Details of Previous NOC letter :F.6/MS/DFS/200/1107 Dated 12/05/2006 For G+3

6. Fire Safety direction letter No : F.6/MS/DFS/BP/2010/3019 Dated 27.10.2010.

7. Date of Inspection

: 06.09.13 & 19. 09.13

8. Name of the Inspecting officers : DO Virendra Singh & ADO Vijay Bahadur

9. Name and designation of Officer:

from the building side

: Sh.K.K.Sachdeva (Manager).

10. Year of Construction

- : 2005 -2010

11. Applicant's letter No

: 08.08.13

| NO. | Minimum Standards on fire prevention and fire safety U/R33 | NBC | Provided at | Rem | |
|-----|---|-------------|-------------|------|-----------|
| 1 | Access to building | Requirement | Site | MR/N | IMR |
| | Road widthGate width | 6 Mtrs. | 15 Mtrs. | MR | |
| | Width of internal road | 4.5 Mtrs. | 6.0 Mtrs | MR | ? |
| 2 | | N/A | N/A | N/A | |
| 2 | Number, Width, Type and Arrangement of Exits | | | | |
| | a. Number of Staircases | 05 Nos. | 05 Nos | | MR |
| | Upper Floor | 05 Nos. | 05 Nos | | MR |
| | Basement | 02 Nos. | 02 Nos. | | MR |
| | B. Width of Staircases | 1.5 M | Provided | | MR |
| | Upper Floor | 1.5 M | 1.5 M | | MR |
| | Basement Brotestian of switz | 1.5 M | 1.5 M+1 RAM | P | MR |
| | c. Protection of exitsFire check doorPressurization | N/A | N/A | | N/A |
| | | N/A | N/A | | N/A |
| | e. No. of continuous staircases to | N/A | N/A | | |
| | terrace | 2 Nos. | 2 Nos. | | N/A MR |
| | g. Width of Corridor h. Door Size | 1.5 mts. | 1.80 mts | | MR |
| | I.No.of door in class room | 1.0 Mtrs | 1.0 Mtrs | | MR |
| | reenway Modern School at Potygon David Land Co | 02Nos. | 01& 02 nos. | | MR |

Greenway Modern School at Between Pockets A & D Dilshad Garden, Delhi 95.

| 3 | Compartmentation. | N/A | N/A | N/A |
|----|---|------------|------------|-------|
| | Fire check door | Required | Provided | MR |
| | Sealing of electrical shafts | N/A | N/A | N/A |
| | Fire rating of shaft door | N/A | N/A | N/A |
| | Water curtain | N/A | N/A | N/A |
| 4 | Fire Dampers Overland Management Contains | IN/A | IN/A | IV/A |
| 4 | Smoke Management System. | Doguirod | Exhaust | MR |
| | Basement | Required | Fans | IVIIX |
| | Upper floor | N/A | N/A | N/A |
| 5. | Fire Extinguishers | | | |
| J. | - The Extrigationero | | | |
| | Total numbers | 22 Nos. | 26 Nos. | MR |
| | • types | ABC & Co2 | ABC& Co2 | MR |
| | IS marking | ISI marked | ISI marked | MR |
| 6 | First-aid-Hose Reels. | | 1 | T |
| | Total numbers of each floor | 2nos. | 2 nos. | MR |
| | Length of hose reel hose | 30 M | 30 M | MR |
| | Nozzle diameter | 5 MM | 5 MM | MR |
| 7 | Automatic fire detection and alarming system. | | | |
| | Type of detectors | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | Location of main panel | 1477 | | |
| | Location of repeater panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooter's location | N/A | N/A | N/A |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public address System. | Required | Provided | MR |
| 10 | Automatic Sprinkler System. | | | |
| | Basement | Required | Provided | MR |
| | upper floor | N/A | N/A | N/A |
| | sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants | N/A | N/A | N/A |
| | size of riser/down-comer | 100 MM | 100 MM | MR |
| | Number of hydrants per floor | 2 nos. | 2 nos. | MR |
| | Hose Box | 2 nos. | 2 nos. | MR |

Greenway Modern School at Between Pockets A & D Dilshad Garden, Delhi 95.



| | Location | N/A | N/A | N/A |
|----|--|--------------|--------------|------------|
| | Total area | N/A | N/A | N/A |
| 18 | Refuge Area. | Requried | Provided | MR |
| 17 | Lift Signage Standby power supply | Requried | Provided | MR |
| | The man end of the state of the | Requried | Provided | MR |
| | Communication in lift car Firemen's grounding switch | Requried | Provided | MR |
| | Pressurization of Lift lobby Communication in lift car | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 10 | Pressurization of Lift Shaft | NI/A | NI/A | NI/A |
| 16 | Exit Signage. Provision of Lifts. | Required | Provided | MR |
| 15 | | | A 24 a | |
| | Overhead Tank capacity | 25,000 Ltrs. | 25,000 Ltrs. | MR |
| | > Access to tank | Required | Provided | MR |
| | Fire service inlet | Reguried | Provided | MR |
| | > Draw-off connection | N/A | N/A | N/A |
| | Underground tank capacity | N/A | N/A | N/A |
| 14 | Captive Water Storage for Fire Fighting. | | | |
| | Auto Starting of pump | Requried | Auto | MR |
| | Power supply | Required | Electricity | MR |
| | > Head of the Pump | 40 M | 40 M | MR |
| | Discharge of pump | 900 LPM | 2 X 900 LPM | MR |
| | Terrace Level | | | |
| | 2 | rtequired | riovided | INILX |
| | > Pump House Access | Required | Provided | MR |
| | Auto Starting /Manual stopping | N/A | N/A N/A | N/A N/A |
| | > Standby pump out put > Standby pump Head | N/A N/A | N/A N/A | N/A |
| | Jockey pump headStandby pump out put | N/A | N/A | N/A |
| | > Jockey pump out put | N/A | N/A | N/A |
| | Number of main pumps | N/A | N/A | N/A |
| | Head of Main Pump | N/A | N/A | N/A |
| | Discharge of main Pump | N/A | N/A | N/A |
| | Ground Level | N/A | N/A | N/A |
| 13 | Pumping Arrangements. | N/A | N/A | N/A |
| n | Hose Box | N/A | N/A | N/A |
| | Total number of hydrants | N/A | N/A | N/A |

Greenway Modern School at Between Pockets A & D Dilshad Garden, Delhi 95.

| | " I brand | Required | Provided | MR |
|----|---|----------|----------------|-----------------|
| n | Flow switch panel | Required | Provided | MR |
| | PA system panel | | Provided | MR |
| | Battery backup | Required | | MR *** |
| | Building Floor Plans | Required | Provided | |
| 0 | Special Fire Protection systems for protection of | Required | Provided | MR |
| 20 | special Risks, if any: | | packed and fou | nd functional a |

The fire protection systems provided in the building were tested/checked and found functional at the

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service

Rule 2010.

Signature of the Inspecting Officer

Name: Vijay Bahaber
Designation ADO (TD)

Name: VIRENDAA SINGH

Designation

DOLE)