GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No.F6//DFS/MS/GH/2013/52/10 28

Dated: 04/10/13

FIRE SAFETY CERTIFICATE

Issued -- 4-13--- at New Delhi by.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

400 (BCP)
4110/2013

Copy to:-

- (1) Addl.Commissioner of Police Licencing 1st Floor,PS Defence Colony,New Delhi
- (2) Mr. R.K.YadavHotel Sri Krishna Palace,226-B/5A, Prakash Mohalla, East Of Kailash,New Delhi-110065

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

old Cerl

INSPECTION REPORT

- 1.Name & address of the building:- Hotel Sri Krishna Palace, 226-B/5A, Prakash Mohalla, East Of Kailash, New Delhi-110065
- 2. Type of occupancy:- Residential (Guest House)
- 3. Type of case: Renewal.
- 4. Details of previous NOC:-No. F6/DFS/MS/2009/3538 dated 24/11/2009.
- 5. Fire safety directives No.- No
- 6. Date of inspection:-27/09/2013
- 7. Name of the inspecting officer:- D.B.Mukherjee A.D.O.(BCP)
- 8. Name & designation of officer From the building side: Mr.R.K.Yadav
- 9. Year of construction:- 1994
- 10.Applicant's letter No:- Nil, Dated 13/08/2013, Building is comprised of Ground + 03 Upper Floors, Guest House is running in First, Second & Third Floor with 32 Rooms.

				Old Case		
SI. No	Minimum Standards on fire Prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	Required	Provided	MR		
	2) Gate width	N/A	Approachable	MR		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases					
	1. Upper floors	Required	Provided 02 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	1.25 m	1.25 m & 1.18 m	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	Required	01	MR		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	N/A	N/A	N/A		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 a/c per hour	N/A	N/A		
	2) Upper floors	12 a/c per hour	Natural Ventilation	MR		
5.	Fire Extinguishers		•			
	1) Total numbers		10 Nos.	MR		
	2) Types	ISI Marked	ABC, Co ₂ & WCO ₂	MR		

			Yes	MR		
	3) ISI marking			MD		
	First-Aid Hose Reel	Required 01	Provided	MR		
	Total number of each floor	30 m	Yes	MR		
	2) Length of hose reel hose	5 mm	Yes	MR		
	2) Nozzle diameter					
	Automatic Fire Detection & Alarming Sy	stem	N/A	N/A		
•	1) Type of detectors	14// 1	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
-	Location of repeater panel	N/A	DG Set	MR		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Required		MR		
2	MOEFA	Required	Provided	MR		
B	Public Address System	Required	Provided	IVIIX		
9.	Automatic Sprinkler System			N/A		
10.	Automatic Sprinkler System	N/A	N/A	N/A		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	IN/A		
	3) Sprinkler above false ceiling	- 1000		MO		
11.	Internal Hydrants	100 mm.	Provided	MR		
	1) Size of riser/down-comer	01	Provided	MR		
	Number of hydrants per floor	01	Provided	MR		
	3) Hose box	U I				
12.	Yard Hydrants	N/A	N/A	N/A		
	1) Total number of hydrants		N/A	N/A		
	2) Hose box	N/A				
				NI/A		
13	. Pumping Arrangement	N/A	N/A	N/A		
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main pump	N/A	N/A	N/A		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put		N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	a) Stand by nump head	N/A	N/A	N/A		
	h) Auto starting/Manual stopping	N/A	INITA			
	Terrace level		450 LPM	MR		
		Required		MR		
	a) Discharge of pump b) Head of pump	Required	40 m			
	c) Power supply	Required	Electric Supply 8			
	C) Lower subbis		also by D.G. Set	MR		
	d) Auto starting of nump	Required	Yes	IVIIX		
	d) Auto starting of pump					
1	Captive Water Storage for The Figure Under ground tank capacity	N/A	N/A	N/A		
	1) Under ground tank capacity	N/A	N/A	MR		
	a) Draw-off connection	Required	Provided			
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	Required	5000 L	MR		
	d) Over head tank capacity	Yes	Provided	MR		
	15. Exit Signage.	163				
	46 Provision of Lifts.	N/A	N/A	N/A		
-	a) Pressurization of lift shaft		N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
_	e) Lift signage	N/A				
	E) List Signage	Yes	Provided DG S	N/A		
	17. Stand by Power Supply	N/A	N/A	N/A		
ı	18. Refuge Area	N/A	N/A	IN/A		

Old Cash

19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for	N/A		
				IN/A

The fire protection system provided in the building were checked and found functional at the time of inspection.

The shortcomings issued vide letter no. F6/DFS/MS/2012/GH/3680, Dated: 05/10/2012 has been rectified. Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/------

Accordingly DFA is put up for perusal and signature If approved.

Submitted please.

Signature of the inspecting officer

30/9/2013

Name: - D.B. Mukherjee.

Designation:- Assistant Divisional Officer (BCP)