GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No.F.6/DFS/MS/School/2013/ 5 2 103 9

Dated: 07) 10) 13

FIRE SAFETY CERTIFICATE

Certified that the building of **Star Shine Public School** located at Plot No. 84-85, Block K-5, Mohan Garden (Near Vikrant Chowk), Uttam Nagar, New Delhi-110059 comprised of ground floor plus one upper floor, having total 12 rooms (Including Class Rooms, Office, Comp. Room & Store etc.) was issued NOC by this department vide letter No.F.6/DFS/MS/2006/3510 dated 04.12.2006. The School building was reinspected by the officer concerned of this department on 17.09.2013 in the presence of Mrs. Manjula Rampal (Principal) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- The Manager, Star Shine Public School, Plot No. 84-85, Block K-5, Mohan Garden (Near Vikrant Chowk), Uttam Nagar, New Delhi-110059.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

N/3 oldese

School sunning at: Ground floor plus one upper
(Two rooms are on terrace). Hor

	INSPECTION REPORT							
	1. Name & address of the building: Stax Shine Public School, K-5 Block, 84-86, New 2. Type of Occupancy : Educational Viktorit Choick, Mohan Garden, Ullamily							
	2. Type of Occupancy :	· Educational Vikoant Choick, Mohan Garden, Ullam Ngy						
	3. Type of Case :	: New Case/Renewal						
Six	4. Details of Previous NOC :	Letter No. F6/	DEC / MS /2006 /35	10 Dated 04 12 06				
	5. Fire Safety directives letter No :							
	6. Date of inspection :	17/09/2013						
	po D Decree !							
	7. Name of Inspecting Officer8. Name and designation of officers							
	From the building side :		ela Rampal.					
	9. Year of Construction :		204-205					
	10. Applicant's letter No.	Nil dat	ed 29 08 2013.					
S.	Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks				
No.	and fire safety U/R 33	Circular dt.	1 Tovided at site	MR/NMR				
	and the salety of Res	01.03.2011		MANTANA				
1.	Access to building	01.05.2011						
	Road width	Accessible	04.5 mtrs	MR				
	Gate width	ricessible	03.05mts 4 117cm					
	Width of internal road		03.03 MR 4 11/0	18 MR				
2.	Number, Width, Type & Arrangement of E	vite						
	a. Number of staircases	7.7.113						
	• Upper Floors	20 1-4	10					
	Basements	02 NO'S	02 NOIS	MR				
	busernerns			No Basement.				
	b. Width of staircases	u.						
	Upper Floor	_	110 cm 24 gycms	MR (Beingoldrase)				
	Basements	_	-	No Basement				
	c. Protection of exits • Fire check door			The Dusemens				
	• pressurization	-						
	procedization							
	d. No. of continuous staircases to		ў — я «	,				
	terrace	~	O \					
	e. Width of Corridor		101	N N				
	f. Door Size	-	1.8 mt/2	-				
	*		85 cms	MR (Beingold case)				
3.	Compartmentation			9				
	Fire check door		8					
	Sealing of electrical shafts	-						
	Fire Rating of shaft door			-				
	Water Curtain	•						
	Fire Dampers							
	- The Dumpers							
4.	Smoke Management System							
	Basements	30 a/c per hour	T					
	- DOSCINCINS	30 a/c per nour	4	No basement				
	• Upper floors			NU LUSCINEUS				
	Upper floors		1151-1					
	a .		Natural Ventilation	MR				
			very lanon	141				

1 1	Ny			· -
		12 a/c per hour	_	
5.	Fire Extinguishers			
1	 Total numbers 	05	Provided	MR
i	TypesIS marking	ABC/Co_ ISI marked	-do	MR
6.	First-Aid Hose Reels		151 marked	MR
	 Total numbers on each floor Length of hose reel hose Nozzle diameter 	30 m	0 1 Provided	
7.	Automatic fire detection and alarming s	System	Provided	
1	 Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 			
8.	MOEFA			
9.	Public Address System		0 - 11	
10.	Automatic Sprinkler System		frovided	
	BasementUpper Floor`Sprinkler above false ceiling	-		No Pasement
11.	Internal Hydrants			
2	 Size of riser/down-comer Number of hydrants per floor Hose Box 			7
12.	Yard Hydrants			
The state of the s	Total number of hydrantsHose Box		1.	
13.	Pumping Arrangements			
4.	 Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head 			
u	 Standby Pump out put Standby Pump Head Auto Starting/Manual stopping 			

N)5

Star Shine Public School, K-5 Block, 85-84 New Vikrant Chowk, Mohan Garden, VHcim Nagar, ND-59.

		wonder wa	vaen, utterm ~	agar, 40-39
	Pump House Access			
	Terrace level			
20	> Discharge of pump		180 LPM	
	Head of the pumpPower Supply		30 mh	
	> Auto Starting of pump			
	ria to otal ting of parity			La company of the second
14.	Captive Water Storage for fire fighting			· 1
	Underground tank capacity			
	Draw-off connection			_
	Fire service inlet			
	Access to tank			
	Overhead Tank capacity		2000 lbs	
			2000 2713	
15.	Exit Signage.		e .	
16.	Provision of Lifts.			4
10.	Pressurization of Lift Shaft	_	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.0
				No left
	Pressurization of Lift lobby			-do -
	Communication In lift Car			-do
18	• * Fireman's Grounding Switch			-de-
	Lift Signage			do
17.	Standby power supply			
			A	
18.	Refuge Area.		* 1	
	> Total Area		1	
	> Location		A STATE OF THE STA	
4.0				2
19.	Fire Control Room	Ţ	T	
	Detector System Panel	•		1
_	Flow Switch Panel		5	
	PA System Panel	2 8		
	Batter backup			
	Building Floor Plans			
20				8
20.	Special Fire Protection System for	•		
	Protection of special Risks, if any:	3 "	n n n	

Sam

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Note: The Manager of school has submitted letter regarding no. of shokents less than 45 in each class. FSC in recommended for renewal please

Signature of Inspecting Officer

Name Sandrep Duggal

Designation Assil. Divisional Officer.

Signature of Inspecting Officer

Name

Designation