GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No.F.6/DFS/MS/School/2013/ 5 2 1036

Dated: 07 10 13

FIRE SAFETY CERTIFICATE

Certified that the building of Great Mary Public School located at RZ-53, Mahendra Park, Pankha Road, New Delhi-110059 comprised of ground floor plus one upper floor & temporary shed on terrace but the school is running on ground floor and first floor only, having total 11 rooms (Including Class Rooms, Office, Comp. Room, issued NOC by this department vide letter Hall Store etc.) was No.F.6/MS/DFS/2006/2380 dated 08.09.2006. The School building was re-inspected by the officer concerned of this department on 17.09.2013 in the presence of Smt. Kavita Sharma and found that the school management have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed below.

Issued on ... 07 10 13 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

or an

Following fire safety directives must be adhered to –

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.

3. The trained staff should be available round the clock.

4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.

5. The certificate may not be treated in any case for regularization of unauthorized

construction, if any.

6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

Copy to:-

1. The Principal, Great Mary Public School, RZ-53, Mahendra Park, Pankha Road, New Delhi-110059.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

School Running at: Ground floor plus one upper floor.

(There is temporary shed on terrace.)

	INSPEC	TION REPORT				
	Name & address of the building Type of Occupancy	: Great Mary	Public School, R	2-53 Mahendra Par		
-	2. Type of Occupancy	: Educational.	Ponkha Ro	ad, NDellii-11059		
	3. Type of Case	: New Case/Rei	newal			
	4. Details of Previous NOC	: Letter No. F6/n	ns/DFS/2006/23	80 Dated 08/9/16		
	Fire Safety directives letter No	:		9 11 10		
	Date of inspection	17-09-2	013			
	Name of Inspecting Officer	: ADO Sonder Duggar				
	8. Name and designation of office	ers	ω	The same of the sa		
	From the building side	: Mrs kav	ita Sharma			
	9. Year of Construction	1990-199				
	10. Applicant's letter No.	: Nil dated	1 04/05/2013	The second secon		
S.	Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks		
No.	and fire safety U/R 33	Circular dt.		MR/NMR		
		01.03.2011				
1.	Access to building			- Landa de la companya de la company		
	 Road width 	Accessible	05 mm	MR		
	Gate width	-	01.5040100 mh	MR (old case)		
2	Width of internal road			-		
2.	Number, Width, Type & Arrangement of	Exits				
	a. Number of staircases		<u> </u>			
	• Upper Floors	OZ NOIS	02 NO15	MR		
	 Basements 			No Basement		
	I. Wildle - F - t .			140 BUSE MEUT		
	b. Width of staircases		0 / 9			
	Upper Floor		112 cms 497 cms (Tw	mr (old case)		
	Basementsc. Protection of exits			No Basement		
	Fire check door					
	pressurization					
	pressurization					
	d. No. of continuous staircases to					
	terrace		one : con			
	e. Width of Corridor			3		
	f. Door Size		1.5 m/M			
			83cms to locans	MR (old case)		
3.	Compartmentation					
	Fire check door					
	 Sealing of electrical shafts 					
	Fire Rating of shaft door					
	Water Curtain			-		
	 Fire Dampers 			Commentered to the Commenter of the Comm		
				-		
4.	Smoke Management System					
	 Basements 	30 a/c per hour				
				No Basement		
	 Upper floors 					
			Natural	3.25		
,			verdi ation	MR		

	N	7/	· · · · · · · · · · · · · · · · · · ·	-
		12 a/c per		
		hour		
5.	Fire Extinguishers			
a 1	 Total numbers 	05 MOLL	Provided	MR
	 Types 	ABC/CO2	1 an aca	MIC
	 IS marking 	ISI marked	- Cl	Me
6.	First-Aid Hose Reels		131 marked	MR
	 Total numbers on each floor 		Provided	
	 Length of hose reel hose 	30 m	1 000/10/60	
	Nozzle diameter	5 mm	- 00	
7.	Automatic fire detection and alarming		1 - 00 -	L.,
	Type of detectors	Jystem	 	T-1 1
1	 Location of Main Panel 			+
	 Location of Repeater Panel 	-		
	Alternate source of power	: 15		
	Hooters' Location			
8.	MOEFA			
9.	Public Address System		0	
10.	Automatic Sprinkler System		Provided	
	Basement			
	Upper Floor			
	!	w		
11.	 Sprinkler above false ceiling Internal Hydrants 			
11.		1	!	1
	Size of riser/down-comer			
	Number of hydrants per floor			7
13	Hose Box			
12.	Yard Hydrants	77	j.	
	Total number of hydrants			
13.	* Hose Box			
13.	Pumping Arrangements	,	7	, class
	Ground Level		,	
	Discharge of main Pump			
	> Head of Main pump			
	> Number of main pumps			
	Jockey Pump out putJockey pump head			
	panip nead			
91	- amp out put	9		
	- Tamp ricad		i.	
	a describit mandal		i	
	stopping			1
-				

Great Mary Public School, RZ-53, Mahendra Pask, Pankha Road, Opp. Alz Janakpuri, NDelhi-59.

				- B. B.
	Pump House Access			
	Terrace level	5 5 2		
	Discharge of pump	-	220 Um	
	Head of the pump			
	Power Supply		30 m	
	Auto Starting of pump			
			<u> </u>	
14.	Captive Water Storage for fire fighting			
	Underground tank capacity			
	> Draw-off connection			
	> Fire service inlet			, x
	Access to tank			
	Overhead Tank capacity		2000 lh	
15.	Exit Signage.			
		3		
16.	Provision of Lifts.		* # * * * * * * * * * * * * * * * * * *	1
	Pressurization of Lift Shaft		3	NOUFF
	Pressurization of Lift lobby			
				do
	Communication In lift Car			-do-
	• * Fireman's Grounding Switch			-do-
	Lift Signage		F 5)
				— d ə
		2 - 1	(5)	
17.	Standby power supply			
18.	Refuge Area.			
	> Total Area			
	> Location	•	e ton	
	Location			
				A
19.	Fire Control Room			
13.				
	Detector System Panel			
	Flow Switch Panel	. *		
	PA System Panel			,
	Batter backup			
	Building Floor Plans			
			,	-
20.	Special Fire Protection System for			, X
	Protection of special Risks, if any:		-	-
	i Totalini of Special Risks, If ally:			5 .
			2	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Note: - The Principal of School has submitted letter regarding, number of students less than 45 is each class. FSC is recommended for renewal phase.

Signature of Inspecting Officer

Designation Asst Divisional Officer.

Signature of Inspecting Officer

Name

Designation