GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001 Ph.23414333, Fax: 23412593, E-mail:cfohq.dlfire@nic.in

No. F6/OFS/MS/2013/NOZ/1052

Dated: 09/10/13

FIRE SAFETY CERTIFICATE

Certified that the "Glassy Junction "situated at Second floor, of V³S East Mall, Plot No.12, Diatrict Centre, Laxmi Nagar, Delhi (For which this department had already issued NOC vide letter no.F.6/DFS/MS/2007/2092 dated 31.07.2007), owned/occupied by M/s A unit of KDM Hotel & Resorts Pvt. Ltd., have complied with the fire prevention and fire safety requirements in accordance with N.B.C. Part IV and verified by the officer concerned of Fire Service on 25.06.13 in the presence of Sh.Farhan Kazmi GM (Ops) and that the part of building (Second floor) is fit for occupancy Group –D 'Assembly building' (Disco Theque) with effect from .o.g././o./.\S. for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

To,

The Dy.Health Officer
East Delhi Municipal Corporation
Health Department, Karkardooma,
South Zone, Shahdara, Delhi.

Copy to:-

Sh. Jagdish Kumar Verma (Executive Director)
Glassy Juction M/s A unit of KDM Hotel & Resorts Pvt. Ltd.,
A-4, Mohan Co-operative Industrial Estate
Mathura Road, New Delhi-110044.

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/ unauthorized use of land if any.
- 6. All comments/directions of the Licensing Department shall always be permitted and followed.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: "Glassy Junction" (A Unit of KDM Hotel

& Resorts Pvt. Ltd. A 2nd floor Plot No.

12, Distt Centre, Laxmi Nagar, Delhi.

2. Building is comprised of : Two tier basement, Ground & three upper

floors.

3. Type of Occupancy : (Assembly) Disco Theque

4. Type of Case New

5. Details of Previous NOC letter: NA

6. Fire Safety direction letter No NA

7. Date of Inspection 25.06.2013

8. Name of the Inspecting officers: Gurmukh Singh

9. Name and designation of Officer: Mr. Farhan Kazmi (GM)

from the building side

10. Year of Construction 2006

11. Applicant's letter No -Nil- dated 13.06.2013

| S.NO. | Olandams on fir | e Requirement | Dravid | |
|-------|---|------------------|----------------------------|---------------------|
| 1 | prevention and fire safety U/R33 Access to building | 3 | Provided a Site | t Remarks MR/NMR |
| | • Pood will | | | INIVIAINIK |
| | Road widthGate width | 12 Mtr - | 24 Mtr | MR |
| | Width of internal road | 5.0 Mtr | 5.0 Mtr | MR |
| 2 | Number, Width, Type and Arrang | YOMAN - CF !! | | |
| | a. Number of Staircases | genient of Exits | | |
| 18 | Upper Floor | 2 Nos. · | | ••• |
| • | Basement | | 4 Nos. | MR |
| | B. Width of Staircases | NA | NA . | NA |
| | Upper Floor | 4.5.11 | | |
| | Basement | 1.5 Mtr | 1.55,1.38,1.59, 1.59Mtr | MR |
| | c. Protection of exits | NA | NA | NA · |
| | Fire check door | | | 14/7 |
| | Pressurization | Required | Provided | MR |
| | e. No. of continuous staircases | | | |
| . | to terrace g. Width of Corridor | 2 Nos. | 2 Nos. | MR |
| | 5. That of Collidor | 1.2Mtr | 2.5 Mtr | MR |

| • | I D 0: | | 10014 | | | |
|-----------|---|------------|--------------|--|--|--|
| | h. Door Size | 2.0 Mtr | 2.0 Mtr | MR | | |
| 3 | Compartmentation. | | T = | | | |
| | Fire check door | Required | Provided | MR . | | |
| | Sealing of electrical | | Provided | MR | | |
| | shafts | NA . | NA | NA | | |
| | Fire rating of shaft door | NA | NA | NA | | |
| | Water curtain | NA · | NA | NA | | |
| | Fire Dampers | | | 57 48 | | |
| 4 | Smoke Management System. | | T | T | | |
| | Basement | NA. | NA . | NA | | |
| - | Upper floor | Required | Provided | MR | | |
| 5. | Fire Extinguishers | | | | | |
| • | Total numbers | 4 Nos. | 4 Nos. | MR. | | |
| • | • types | ABC& CO2 | ABC&CO2 | MR | | |
| | IS marking | Required | Provided | MR · | | |
| 3 | First-aid-Hose Reels. | | | | | |
| | Total numbers at ground floor | 2 Nos. | 4 Nos. | MR . | | |
| | Length of hose reel hose | 30 mtr | 30 mtr | MR | | |
| | Nozzle diameter | 5 mm | 5mm | MR | | |
| 7 - | Automatic fire detection and alarm | | | | | |
| | Type of detectors | Heat/smoke | Heat & smoke | MR | | |
| | Location of main panel | Basement | Basement | MR | | |
| | Location of repeater panel | NA. | . NA | NA . | | |
| | . parier | | 2 × | ************************************** | | |
| | Alternate source of power | Required | Provided · | MR | | |
| • | Hooter's location | | 22 2 | · · · · | | |
| 3 · | MOEFA | Required | Provided | MR | | |
| 9 | Public Address System. | Required | Provided | MR | | |
| 10 | Automatic Sprinkler System. | Required | Provided | MR | | |
| * * * * . | Basement | NA . | NA | NA . | | |
| | upper floor | Required | Provided | MR | | |
| * | sprinkler above false ceiling | NA . | NA | NA | | |
| 11 | Internal Hydrants . | | | | | |
| | size of riser/down-comer | 150 MM | 150 MM · · | MR | | |
| | Number of hydrants per floor | | 4 Nos. | MR | | |
| | | 1 | | | | |
| | | 2 Nos. | 4 Nos. | MR | | |
| 12 | Hose Box Yard Hydrants. | 2 Nos. | 4 Nos. | MR | | |

-M/4- Glassy Innetion, (A unit of Kom Hotel
& Resorts PLtd) 2 and floor,
Plot 40 12 Dist Centre, Laxmin Hgr.

| | | γ | Adhi ssh .ce. | 100,000,000 |
|-------|--|-------------|---|-------------|
| 10 | Hose Box | Required | Provided | ·MR |
| 13 | Pumping Arrangements. | | | - ,1 d •. |
| . * 5 | Ground Level | | | |
| | ➤ Discharge of main Pump | 2850 LPM | 2850 LPM | MR |
| | ➤ Head of Main Pump | 70 Mtrs. | 70 mtrs | MR |
| | Number of main pumps | 2 Nos | 2 Nos. | MR |
| 8 | ➤ Jockey pump out put | 180LPM | 180LPM | MR |
| | Jockey pump head | 70 Mtrs. | 70 mtrs. | MR |
| 7 | Standby pump out put . | 2850 LPM | 2850 LPM | MR · |
| | ➤ Standby pump Head | 70Mtrs | 70 Mtrs. | MR |
| | ➤ Auto Starting /Manual stopping | Required | Provided | MR |
| • | ➤ Pump House Access | Required | Available | MR |
| | Terrace Level | NA | NA | NA |
| | ➤ Discharge of pump | NA · | NA | NA |
| | ➤ Head of the Pump | NA | NA | ·NA |
| | ➢ Power supply | NA | NA | NA - |
| | ➤ Auto Starting of pump | NA · | NA | NA |
| 4 | Captive Water Storage for Fire | | | |
| • | Fighting. | | * · · · · · · · · · · · · · · · · · · · | |
| | Underground tank capacity | 2,00,000Ltr | 2,00,000 Ltrs. | MR . |
| | Draw-off connection | Required | Provided | MR |
| | ➤ Fire service inlet | Required | Provided | MR |
| • | ➤ Access to tank | Required | Provided. | MR |
| | Overhead Tank capacity | 30,000Ltr. | 30,000Ltr. | MR |
| 5 | Exit Signage. | Required | Provided | MR |
| 6 . | Provision of Lifts. | Required | Provided | MR |
| | Pressurization of Lift Shaft | Required | Provided | MR |
| * | Pressurization of Lift lobby | Required | Provided | MR |
| | Communication in lift car | Required | Provided | MR |
| • | • Firemen's grounding switch | Required | Provided | MR |
| | Lift Signage | Required | Provided · · | MR |
| 7 | Standby power supply | Required | Provided | MR |
| 8 | Refuge Area. | NA | NA | IVII |
| | Total area | NA . · | NA | |
| • | Location | NA | NA · | |
| 9 | Fire Control Room | Required | Provided | MR |
| | Detector system panel | Required | Provided | MR |
| | | | | 1 1411 / |

| ta , | Flow switch panel | N.A. | NA | NΑ |
|------|-------------------------------------|----------|-----------|-----------|
| | PA system panel | NA . | NA | NA |
| * | Battery backup | Required | Provided. | MR |
| | Building Floor Plans | NA | NA | NA |
| 20 . | Special Fire Protection systems | NA | NA | NA |
| | for protection of special Risks, if | | | , , , , , |
| | any: | F | n " | |

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name GURMUKH SINGH Designation AND (1922)

DO(E)