GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 011-23412593 E-mail: cfohq.dlfire@nic.in Ph. 011-23414333.

No.F6/DFS/MS/EH/2013/52/1087

Dated: 15/10/13

FIRE SAFETY CERTIFICATE

Issued ______at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

de e

- Copy to:- (1) Dy. Health Officer, MCD,South Zone,Green Park,New Delhi.
- (2) Dhaba by Claridges, A Unit of M/s QSOP Hospitality Pvt. Ltd., Shop No. 303,304,305,2nd Floor, Plot No. A-4,DLF Place ,Saket, New Delhi. Following fire safety directives must be adhered to:-
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. The basement shall be used as per the provisions of BBL.
 - 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:- Dhaba by Claridges, A Unit of M.s QSOP Hospitality Pvt. Ltd., Shop No. 303,304,305,2nd Floor, Plot No. A-4,DLF Place, Saket, New Delhi.
- 2. Type of occupancy:- Group D Assembly Building (Eating House)
- 3. Type of case:- New
- 4. Details of previous NOC:-No.F6/DFS/MS/2012/4017 dated 26/10/12. (DLF Place Saket)
- 5. Fire safety directives No.- No
- 6. Date of inspection: 09/10/13.
- 7. Name of the inspecting officer:- Dy. C.F.O. Atul Garg & A.D.O. S.S. Kaushik
- 8. Name & designation of officer
 - From the building side:- Mr. Vineet Kochar.
- 9. Year of construction:- Not known
- 10. Applicant's letter No:-Nil. dated 17/09/13 3 Basement, Ground + 7 Upper Floors. The Restaurant is running on 2nd floor only

1	10015. The Restaurant is running of	ii 2 Hoor only		Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR	
1.	Access to Building		4 4	2	
	1) Road width	Existing in mall	Provided	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arrange		1,772		
	A. Number of staircases	Provided &	2		
		maintained by mall management			
	1. Upper floors	Required	2 Nos. of staircase near restaurant available	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase			П	
	1. Upper floors	1.5 mtr. required	1.5 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits		N N		
	1. Fire check door	Yes	Provided	MR	
	2. Pressurization	Yes	Provided	MR	
	D. No. of continuous staircase to terrace	Required	Provided	MR	
	E. Width of corridor	1.5 mtr.	Yes	MR	
	F. Door size	Required 2 mtr.	Provided	MR	
3.	Compartmentation				
	1) Fire check door	Yes	Provided	MR	
*. *	2) Sealing of electrical shafts	Yes	Provided	MR	
	3) Fire rating of shaft door	Yes	Provided	MR	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 a/c per hour	N/A	N/A	
	2) Upper floors	12 a/c per hour	Exhaust fan provided	MR	
5.	Fire Extinguishers		× .		
	1) Total numbers		07 Nos.	MR	

Maustel

	2) Types	ISI Marked	ABC, Co2 & W.Co2	MR	
	3) ISI marking		Yes	MR	
	First-Aid Hose Reel			9	
6.	1) Total number of each floor	Provided & Maintained by mall	2 Nos. available near restaurant	MR	
	2) Length of hose reel hose	30 m	Yes	MR	
	3) Nozzle diameter	5 mm	Yes	MR	
T.,	Automatic Fire Detection & Alarming	System			
7.	1) Type of detectors	Provided & maintained by mall management	Provided & maintained by mall management	MR	
	2) Location of main panel	do	do	do	
	3) Location of repeater panel	do	do	do	
	4) Alternate source of power	do	do	do	
	5) Hooter's Location	do	do	do	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Provided & maintained by mall management	Provided	MR	
10.	Automatic Sprinkler System				
	1) Basement	Yes	Provided	MR	
	2) Upper floors	Yes	Provided	MR	
	3) Sprinkler above false ceiling	Yes	Provided	MR	
11.	Internal Hydrants				
	1) Size of riser/down-comer	Provided & maintained by mall management	Provided & maintained by mall management	MR	
	2) Number of hydrants per floor	Required	2 Nos. available near restaurant	MR	
		1-	do	do	
	3) Hose box	do		- 40	
12.	Yard Hydrants 1) Total number of hydrants	Provided & maintained by	Provided & maintained	MR	
	* .	mall management	by mall management		
	2) Hose box	do	do		
	D				
13.	Pumping Arrangement 1) Ground level	Provided & maintained by mall management	by mall management		
	a) Discharge of main pump	do	do		
	b) Head of main pump	do	do	do	
				11 1	

----do-----

Number of main pump

Stand by pump output

Stand by pump head

Jockey pump out put

Jockey pump head

d)

e)

f)

- M2-

		4/3-			
	h) Auto starting/Manual stopping		do	do	
	2) Terrace level				
	a) Discharge of pump	do	do	do	
	b) Head of pump	do	do	do	
	c) Power supply	do	do	do	
	d) Auto starting of pump	do	do	do	
14.	Captive Water Storage for Fire Fighting :- Provided & maintained by mall				
	Under ground tank capacity	Provided & maintained by mall		MR	
		management			
	a) Draw-off connection	do	do	do	
	b) Fire service inlet	do	do	do	
	c) Access to tank	do	do	do	
	d) Over head tank capacity	do	do	do	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.	Provided & maintained by mall		MR	
	2 /	management			
	a) Pressurization of lift shaft	Yes	Provided	MR	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	Yes	Provided	MR	
	d) Fireman's switch	Yes	Provided	MR	
	e) Lift signage	Yes	Provided	MR	

	e) Lift signage	Yes	Provided	MR
17.	Stand by Power Supply	Yes	Provided	MR
18.	Refuge Area			
	Total area location	2 nd floor	Provided	MR
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	Yes	Provided	MR
CE .	b) Flow switch panel	Yes	Provided	MR
	c) PA system panel	Yes	Provided	MR
	d) Battery backup	Yes	Provided	MR
	e) Building floor plan	Yes	Provided	MR
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up please.

Signature of the inspecting officer

Signature of the inspecting officer

Name: S.S.Kaushik

Designation: - Assistant Divisional Officer.

Name:- Atul Garg

Designation:- Dy. C.F.O.