GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

Ph.23414333,Fax:23412593,E-mail:cfohq.dlfire@nic.in

No. F6/0/5/M5/2013/1/29

0

Dated: 24.10.2013

FIRE SAFETY CERTIFICATE

Certified that the V3S East Centre Mall at Plot no.12, District Centre, Laxmi Nagar, Delhi, owned/occupied by M/s V3S Infratech Ltd., comprising of two basements, NOC vide letter no. granted ground plus three upper floors was F6/DFS/MS/2009/2976 dated 08.10.2009. The Mercantile building was inspected by the officer concerned of this department on 15.10.13 in the presence of Sh.V.K.Parashar (Head Operations) and found that the Mercantile building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group "Mercantile Building" with effect from for a period of three years, subject to conditions printed overleaf.

Issued on 24.10.2013 at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

To,

M/s V3S Infratech Ltd., A-20, Naraina Industrial Area, Phase -1,New Delhi-110028

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. Basements shall be used as per BBL.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

▼ INSPECTION REPORT

1. Name & address of the building: V3S East Centre Mall at plot no. 12,District Centre

Laxmi Nagar, Delhi

2. Building is comprised of

:2 basements, Ground + 3 upper floors.

3. Type of Occupancy •

: Mercantile(Mall)

4. Type of Case

: Renewal

5.Details of Previous NOC letter: F6/DFS/MS/2009/2976 dated 08.10.2009

6. Fire Safety direction letter No : F.6/DFS/MS/BP/2007/1329 Dated 10.05.2007.

7. Date of Inspection

: 15.10.13

8. Name of the Inspecting officers: DO Virendra Singh

9. Name and designation of Officer

from the building side

:Sh.V.K.Parashar (Head Operations)

10. Year of Construction

:2006

11. Applicant's letter No

: 19.09.2013

S.NO.	Minimum Standards on fire prevention	NBC/BBL	Provided at Site	Remarks MR/NMR		
	and fire safety U/R33	Requirement				
1	Access to building		****			
	Road width	11 Mtrs.	45 Mtrs.	MR		
	Gate width	4.5 Mtrs.	6 Mtrs.	MR		
	Width of internal road	6 Mtrs.	6 Mtr:	MR		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases	11 Nos.	13 Nos.	MR		
	 Upper Floor 	11 nos.	13 Nos.	MR ,		
	 Basement 	13 nos.	15 Nos.+ 2	MR		
	9		ramp	e U.S.		
	B. Width of Staircases		40			
	Upper Floor	1.25 Mtrs.	1.4 M to 1.5 M	MR		
	 Basement 	1.25 Mtrs.	1.4 M to 1.5 M	MR		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	 Pressurization 	Required	Provided	MR		
	e. No. of continuous staircases to terrace	4 nos.	4 nos.	MR		
	g. Width of Corridor	2.0 Mtrs.	2.1 Mtrs.	MR		
	h. Door Size	1.5 M	1.5 M	MR		
3	Compartmentation.					
	Fire check door	Required	Provided	MR		
	 Sealing of electrical shafts 	Required	Sealed	MR		
	 Fire rating of shaft door 	0 2 hrs.	0 2 hrs.	MR		
	 Water curtain 	N/A	N/A	N/A		



	9			NAD .
	Fire Dampers	Required	Provided	MR .
	Smoke Management System.		D 11-4	MR
	Bacement	Required	Provided	MR
	Upper floor F	Required	Provided	IVIN
	Fire Extinguisher			MR
5.	• Total numbers 1	.20 nos.	140 Nos.	MR
	• types	ABC & Co2	ABC & Co2	
	IS marking	SI marked	ISI marked	MR
	First-aid-Hose Reels.			
6		12 nos.	12 nos.	MR
	Total numbers of each floor		30 m	MR
	• Length of flose reel flose	30 m	5 mm	MR
	Nozzie diametei	5 mm	311111	
7	Automatic fire detection and alarming syste	m.	Provided	MR
	Type of detectors	Heat & smoke	1st Basement	MR
	Location of main panel	Control room	Provided	MR
	 Location of repeater panel 	Security Room	Provided	MR
	 Alternate source of power 	Battery & DG	Provided	IVIIX
		Set		
				MR
	Hooters's location	Staircase	Provided	
8	MOEFA	Required	Provided	MR
9	Public address System.	Required	Provided	MR
10	Automatic Sprinkler System.			NAD.
10	• basement	Required	Provided	MR
		- · · · · · · · · · · · · · · · · · · ·	Provided	MR
	 upper floor 	Required		
	sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants			- 12
11	size of riser/down-comer	150 mm	150 mm	MR
	Number of hydrants per floor	12 nos.	12 nos.	MR
	Hose Box	12 nos.	12 nos.	MR
12	Yard Hydrants.			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
12	Total number of hydrants	11 nos.	11 nos.	MR
		11 nos.	11 nos.	MR
4.3			al al	
13	Pumping Arrangements.	Required	Provided	MŖ
	Ground Level Discharge of main Pump	2850 LPM	2850 LPM	MR
	Discharge of main Pump Head of Main Pump	70 Mtrs.	70 Mtrs.	MR
	> Head of Main Pump	2 Nos.	2 Nos.	MR
	> Number of main pumps	180 LPM	180 LPM	MR
	> Jockey pump out put	70 Mtrs.	70 Mtrs.	MR
	> Jockey pump head	2850 LPM	2850 LPM	MR
	> Standby pump out put	70 Mtrs	70 Mtrs	MR
	> Standby pump Head		Auto	MR
	Auto Starting / Manual stopping	Required	Auto	0
		D	Provided	MR
	Pump House Access	Required	Provided	IVIII

(/



¥	Terrace Level	N/A	N/A	N/A
	Discharge of pump	N/A	N/A	N/A
	➢ Head of the Pump	N/A	N/A	N/A
water and the second se	Power supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	1,00,000 Ltrs.	3,00,000 Ltrs.	MR
	Draw-off connection	Required	Provided	MR
	➢ Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 Ltrs.	40,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			. 2
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	Required	Provided	MR
	Communication in lift car	Required	Provided	MR
	Firemen's grounding switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector system panel	Required	Provided	MR
A	Flow switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR
	Batter backup	Required	Provided	MR
	Building Floor Plans	Required	provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	Required	Provided in all LT & HT Panels	MR

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Dy CFO(NOZ)

pylos

Signaturing the Inspecting Officer
Name VIRENDRA SINGH
Designation
DO (East)