## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No: F6./DFS/MS/GH/2013/NO2/1133

Dated: 29 /10/13

No:

Dated:

## FIRE SAFETY CERTIFICATE

Certified that the Working Girls Hostel, YWCA, located at Ashoka Road, New Delhi comprised of basement, ground + 3 upper floors, was granted NOC by this department vide letter No. F6/DFS/MS/95/BP/24 dated 12-01-95. The premises was re-inspected by the officer concerned of this department on 22-10-2013 in the presence of Mr. Jacab (Manager Hostel) and found that the said hostel building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of hostel with effect from 2.9./...2013 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 2.9./1.9./1.3. at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

Copy to:-

1. Working Girls Hostel, YWCA, Ashoka Road, New Delhi

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Working Girls Hostel, YWCA, Ashoka Road, New Delhi

**INSPECTION REPORT** 

1. Name & address of the building : Working Girls Hostel, YWCA, Ashoka Road, New Delhi

2. Type of Occupancy : Hostel

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. N/A dated N/A

5. Fire Safety directives Letter No. : No. F6/DFS/MS/95/BP/24 dated 12-01-95

6. Date of inspection : 22-10-2013

7. Name of the Inspecting Officer : Sh. D.S. Yadav (D.O.) & Sh. Manoj Kumar Sharma (ADO)

8. Name and designation of Officer

from the building side : Mr. Jacab (Manager Hostel)

9. Year of Construction : starting year 1995

10. Applicant's letter No. : Nil dated 12-08-2013

No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR		
	and fire safety U/R 33	Requirements				
•	Access of building  Road width					
	Rodd Width	6mtrs	Provided	MR		
	• Gate width	5mtrs.	Provided	MR		
	Width of internal road	N/A	N/A	N/A		
•	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	• Upper floors	03	03	MR		
	Basements	02	02			
	b. Width of staircases		02	MR		
	• Upper floors	125cms	125 cms each			
	Basements	125cms	125 cms each	MR		
	c. Protection of exits	12301113	123 cins each	MR		
	<ul> <li>Fire check door</li> </ul>	N/A	N/A			
	<ul> <li>Pressurization</li> </ul>	N/A	N/A N/A	N/A		
	d. No of continuous staircase to	01	01	N/A		
	terrace	O1	01	MR		
	e. Width Of Corridor	N/A	N/A			
	f. Door Size	N/A		N/A		
	Compartmentation	IN/A	N/A	N/A		
	Fire check door	N/A	27/4			
	Sealing of electrical shafts	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A N/A	N/A	N/A		
	Water Curtain	N/A N/A	N/A	N/A		
	• Fire Dampers		N/A	N/A		
	Smoke managements System	N/A	N/A	N/A		
	-	20 /		at a second and a second a second and a second a second and a second a second and a		
		30 a/c per hour	N/A	N/A		
	• Upper floors Fire Extinguishers	12 a/c per hour	Exhaust fans	MR		
+						
	Total Hullioels	18	18	MR		
	• Types	••••••	Water Co2 &	MR		
			A.B.C. type.	14117		

Working Girls Hostel, YWCA, Ashoka Road, New Delhi

	IC 1:						
6.	IS marking  First – Aid Hose Reels	ISI marked	Provided	MR			
0.		- 00		4			
	Total numbers on each floor	02	Provided	MR			
×	• Length of hose reel hose	30 M	Provided	MR			
7.	Nozzle diameter  Automotic fire data di	5 mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	• Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
8.	Hooters' Location	N/A	N/A	N/A			
9.	MOEFA	Required	Provided	MR			
10.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System		T				
	Basements	Required	Provided	MR			
	• Upper Floor	N/A	N/A	N/A			
1.1	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants	*					
	Size of riser/down- comer	100 mm.	provided	MR			
	Number of hydrants per floor	One	provided	MR			
10	Hose Box	One	provided	MR			
12.	Yard Hydrants						
	<ul> <li>Total number of hydrants</li> </ul>	04	04	MR			
	Hose Box	04	04	MR			
13.	Pumping Arrangements						
	<ul> <li>Ground Level</li> </ul>						
	<ul> <li>Discharge of main pump</li> </ul>	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	<ul> <li>auto Staring/Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A			
	Tump House Heeess	N/A	N/A	N/A			
	Terrace level     Discharge of nump			2 - 2 - 2			
	Discharge of pump	2 pumps 900	Provided	MR			
	➤ Head of the pump	LPM each					
	> Power supply	40mtrs	Provided	MR			
	<ul><li>Auto starting of pump</li></ul>	Required	Provided	MR			
1.4		Required	Provided	MR			
14.	Captive water Storage for fire fighting						
	Under ground tank capacity	100000	Provided	MR			
	Draw of connection	N/A	N/A	N/A			
	Fire service inlet	Required	Provided	MR			
	Access to tank	Required	Provided	MR			
1.5	Overhead Tank capacity	20000 Ltrs.	Provided	MR			
15	Exit Signage	Required .	Provided	MR			
16.	Provision of Lifts						
	> Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	Communication in lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
17.	➤ Lift Signage	Required	Provided	MR			
	Standby power supply	Required	Provided	3669 72			

Working Girls Hostel, YWCA, Ashoka Road, New Delhi

Z	Working Girls Hoster, T. W. C.T., Tishloka Road, T. W. Delin								
1	18.	Refuge Area							
1		Total area	N/A	N/A	N/A				
		> Location	N/A	N/A	N/A				
	19.	Fire control room							
		Detector system panel	N/A	N/A	N/A				
		Flow Switch Panel	N/A	N/A	N/A				
		PA System Panel	N/A	N/A	N/A				
		Batter backup	N/A	N/A	N/A				
		Building Floor Plans	N/A	N/A	N/A				
	20.	Special Fire Protection Systems for	Required	01 Co2 & 01 ABC	MR				
		Protection of special Risks, if any;		fire extinguisher					
				provided near					
				electric panel	, i				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name D. S. yadav.
Designation Divisional abbical (c-2)

Signature of the Inspecting Officer

Name

Designation