GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

Ph.23414333,Fax:23412593,E-mail:cfohq.dlfire@nic.in

No. F6/DFS/MS/2013/ NOZ/ 1146

Dated: 3 6 | 1 6 | 1 3

FIRE SAFETY CERTIFICATE

Certified that the V3S Mall at Plot no.10, District Centre, Laxmi Nagar, Delhi, owned/occupied by M/s V3S Infratech Ltd., comprising of basement, ground plus three upper floors was granted NOC vide letter no. F6/DFS/MS/2006/830 dated 05.04.2006. The Mercantile (Mixed occupancy) building was inspected by the officer concerned of this department on 15.10.13 in the presence of Sh.V.K. Parashar (Head Operations) and found that the Mercantile (Mixed occupancy) building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group "Mercantile Building" with effect from 3.0.1.0.13.... for a period of three years, subject to conditions printed pverleaf.

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

To,

M/s V3S Infratech Ltd., A-20,Naraina Industrial Area, Phase -1,New Delhi-110028.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures,

management shall be responsible.

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.

5. This Fire Safety certificate can not be treated in any case for regularizations of

unauthorized construction unauthorized use of land if any.

6. Basement shall be used as per BBL.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: V3S Mall at plot no. 10, District Centre, Laxmi Nagar, Delhi

2. Building is comprised of

: Basement, Ground + 3 upper floors.

3. Type of Occupancy

: Mercantile (Mixed Occupancy)

4. Type of Case

: Renewal

5.Details of Previous NOC letter: F6/DFS/MS/2006/830 dated 05.04.2006

6. Fire Safety direction letter No : F.6/DFS/MS/BP/2004/863 Dated 16.04.2004.

7.Date of Inspection

: 15.10.13

8. Name of the Inspecting officers: DO Virendra Singh

9. Name and designation of Officer

from the building side

:Sh.V.K.Parashar (Head Operations)

10.Year of Construction

:2006

11. Applicant's letter No

: 2...09.2013

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	NBC/BBL Requirement	Provided at Site	Remarks MR/NMR	
1	Access to building			MATERIA CONTRACTOR CON	
	Road width	12 Mtrs.	36 Mtrs.& 13.8 Mtr,	MR	
	Gate width	4.5 Mtrs.	6 Mtrs.	MR	
	Width of internal road	6 Mtrs.	6 Mtr.	MR	
2	Number, Width, Type and Arrangement of	Exits	. 40.0 00.000 00.0000000000000000000000		
2	a. Number of Staircases	2 2 -) Q	2 2	
	Upper Floor	2 nos.	Nos. (SIM)	MR	
	Basement	2 nos.	3 Nos.+2(one) ramp ←	MR	
	B. Width of Staircases			() () () () () () () () () ()	
	Upper Floor	1.5 Mtrs.	1.5 M& 1.8 M	MR	
	Basement	1.5 Mtrs.	1.5 M& 1.0 M	MR	
	c. Protection of exits		a to come from the control of the co		
	Fire check door	Required	Provided	MR ·	
	 Pressurization 	Required	Provided	MR	
	e. No. of continuous staircases to terrace	1no.	1 no.	MR	
	g. Width of Corridor	2.0 Mtrs.	2.5 Mtrs.	MR	
	h. Door Size	1.5 M	1.5 M	MR	
3	Compartmentation.				
	Fire check door	Required	Provided	MR	
	Sealing of electrical shafts	Required	Sealed	MR	
	Fire rating of shaft door	0 2 hrs.	0 2 hrs.	MR	
	Water curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	



1RN-3

4	Smoke Management System.	Doguirod	Provided	MR
	Basement	Required	Provided	MR
	Upper floor	Required	Flovided	TVIIV
5.	Fire Extinguisher	20 nos.	39 Nos.	MR
	Total numbers	ABC & Co2	ABC & Co2	MR
	• types	ISI marked	ISI marked	MR
	IS marking	131 IIIai keu	131 IIIai keu	IVII
ō	First-aid-Hose Reels.	× 2 ×	8	and the state of t
uman dangkan keralah kebuah di dan Pada Mada Mada Mada Mada Mada Mada Mada	Total numbers of each floor	2 nos.	2 nos.	MR
	 Length of hose reel hose 	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming syst		1	
	 Type of detectors 	Heat & smoke	Provided	MR
	 Location of main panel 	Control room	Basement	MR
	 Location of repeater panel 	Security Room	Provided	MR
	Alternate source of power	Battery & DG Set	Provided	MR
	Hooters's location	Staircase	Provided	MR
3	MOEFA	Required	Provided	MR
9	Public address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	• basement	Required	Provided	MR
	upper floor	Required	Provided	MR
	 sprinkler above false ceiling 	Required	Provided	MR
11	Internal Hydrants			
	size of riser/down-comer	150 mm	150 mm	MR
	 Number of hydrants per floor 	2 nos.	2 nos.	MR
	Hose Box	2 nos.	2 nos.	MR
12	Yard Hydrants.		٠,	
N	 Total number of hydrants 	5 nos.	5 nos.	MR
	Hose Box	5 nos.	5 nos.	MR
13	Pumping Arrangements.			
	 Ground Level 	Required	Provided	MR
	Discharge of main Pump	2850 LPM	2850 LPM	MR
	Head of Main Pump	70 Mtrs.	70 Mtrs.	MR.
	Number of main pumps	1 No.	1No.	MR
	Jockey pump out put	180 LPM	180 LPM	MR
	> Jockey pump head	70 Mtrs.	70 Mtrs.	MR
	> Standby pump out put	2850 LPM	2850 LPM	MR
	> Standby pump Head	70 Mtrs	70 Mtrs	MR
	Auto Starting / Manual stopping	Required	Auto	MR
	Pump House Access	Required	Provided	MR
	Terrace Level	N/A	N/A	N/A



1RN-4

	Discharge of pump	N/A	N/A	N/A
	Head of the Pump	N/A	N/A	N/A
anni di	> Power supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting.		*	
	 Underground tank capacity 	1,00,000 Ltrs.	1,20,000 Ltrs.	MR
	Draw-off connection	Required	Provided	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 Ltrs.	40,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	Required	Provided	MR
	Communication in lift car	Required	Provided	MR
AND THE PERSON NAMED IN COLUMN	Firemen's grounding switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
10	Total area	N/A	N/A	N/A
- Andrews - Andr	• Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector system panel	Required	Provided	MR
	Flow switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR
	Batter backup	Required	Provided	MR
	 Building Floor Plans 	Required	provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	Required	Provided in all LT & HT Panels	MR

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

04 000 (402)

Signature of the Inspecting Officer
Name VIREWORD SINGN
Designation