

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001  
Fax : 23412593, E-mail: [cfohq.dlfire@nic.in](mailto:cfohq.dlfire@nic.in) Tel :- 011-23414333**

NO.F6/DFS/MS/EH/2013/ SZ/ 1230

DATED: 27/11/2013

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Punjabi By Nature (A unit of A.R.Fisheries Pvt. Ltd) located at T-305,3<sup>rd</sup> Floor, Ambience Mall,Vasant Kunj, New Delhi-110017 is running at the third floor of a building comprised of three basement, ground plus three upper floors owned/occupied by M/s Punjabi By Nature have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 04.11.2013 in the presence of Mr. Tarak Majumdar, of the restaurant and that the building is fit for occupancy class D "Assembly building ( Restaurant)" with effect from...27/11/2013 for a period of **three** years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rule, 2010, as mentioned below.

Issued on ...27/11/2013..... at New Delhi by

(Dr. G.C. Misra)  
Chief Fire Officer  
Delhi Fire Service



**Copy To:-**

1. The DHO (Central Zone), Office of Deputy Health Officer, M.C.D. Health Department, Central Zone, Jal Vihar, Lajpat Nagar, New Delhi.
2. Mr. Tarak Majumdar , M/s Punjabi By Nature (A unit of A.R.Fisheries Pvt. Ltd) located at T-305,3<sup>rd</sup> Floor, Ambience Mall,Vasant Kunj, New Delhi-110017

**Conditions for the validity of fire safety certificate**

1. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
3. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye laws.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)



## INSPECTION REPORT

1. Name & address of the building:- M/s Punjabi By Nature (A unit of A.R.Fisheries Pvt. Ltd)  
T-305, 3<sup>rd</sup> Floor, Ambience Mall, Vasant Kunj, New Delhi-110017
2. Type of occupancy:- Assembly, Group – D, Restaurant
3. Type of case:- New
4. Details of previous NOC:-Nil
5. Fire safety directives No.- Nil
6. Date of inspection:-04/11/2013
7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
8. Name & designation of officer From the building side:- Mr.Tarak Majumdar
9. Year of construction:- 2010.
10. Applicant's letter No:-DHO/SZ/2012/D/1626 dated 25/10/13,  
Building is comprised of 03 Basement, Grpund + Three Upper Floors  
Restaurant is running in Third Floor

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC	Provided at site	Remarks MR/NMR
<b>1.</b>	<b>Access to Building</b>			
	1) Road width	09 m	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	06 m	Provided	MR
<b>2.</b>	<b>Number, Width Type &amp; Arrangement of Exits</b>			
	A. Number of staircases	<b>Provided and maintained by Mall</b>		
	1. Upper floors	Required	Two Provided near Restaurant	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	Required	1.4-1.5Mtr Provided	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required	Provided by mall	MR
	2. Pressurization	Required	Provided by mall	MR
	D. No. of continuous staircase to terrace	Required	Provided by mall	MR
	E. Width of corridor	Required	Provided by mall	MR
	F. Door size	02m	2 m & 1.10 m	MR
<b>3.</b>	<b>Compartmentation</b>			
	1) Fire check door	Required	Provided by Mall	MR
	2) Sealing of electrical shafts	Required	Provided by Mall	MR
	3) Fire rating of shaft door	Required	Provided by mall	MR
	4) Water curtain	Required	Provided by mall	MR
	5) Fire Dampers	Required	Provided by mall	MR
<b>4.</b>	<b>Smoke Management System</b>			
	1) Basements	30 a/c per hour	Provided by Mall	MR
	2) Upper floors	12 a/c per hour	Provided by Mall	MR
<b>5.</b>	<b>Fire Extinguishers</b>			
	<b>Provided and maintained by Mall</b>			
	1) Total numbers	ISI Marked	10 Nos.	MR
	2) Types		ABC, Co2 ,Mech. foam	MR
	3) ISI marking		Yes	MR
<b>6.</b>	<b>First-Aid Hose Reel</b>			
	<b>Provided and maintained by Mall</b>			



1) Total number of each floor	Required	Provided by Mall	MR
2) Length of hose reel hose	30 m	Provided by Mall	MR
3) Nozzle diameter	5 mm	Provided by Mall	MR

<b>7.</b>	<b>Automatic Fire Detection &amp; Alarming System</b>			<b>Provided and maintained by Mall</b>
	1) Type of detectors	do	do	do
	2) Location of main panel	do	do	do
	3) Location of repeater panel	do	do	do
	4) Alternate source of power	do	do	do
	5) Hooter's Location	do	do	do
<b>8.</b>	<b>MOEFA</b>	<b>Provided and maintained by Mall</b>		<b>MR</b>
<b>9.</b>	<b>Public Address System</b>	<b>Provided and maintained by Mall</b>		<b>MR</b>
<b>10.</b>	<b>Automatic Sprinkler System</b>			<b>Provided and maintained by Mall</b>
	1) Basement	do	do	do
	2) Upper floors	do	do	do
	3) Sprinkler above false ceiling	do	do	do
<b>11.</b>	<b>Internal Hydrants</b>			<b>Provided and maintained by Mall</b>
	1) Size of riser/down-comer	do	do	do
	2) Number of hydrants per floor	do	do	do
	3) Hose box	do	do	do
<b>12.</b>	<b>Yard Hydrants</b>			
	1) Total number of hydrants	do	do	do
	2) Hose box	do	do	do
<b>13.</b>	<b>Pumping Arrangement</b>			<b>Provided and maintained by Mall</b>
	1) Ground level	do	do	do
	a) Discharge of main pump	do	do	do
	b) Head of main pump	do	do	do
	c) Number of main pump	do	do	do
	d) Jockey pump out put	do	do	do
	e) Jockey pump head	do	do	do
	f) Stand by pump output	do	do	do
	g) Stand by pump head	do	do	do
	h) Auto starting/Manual stopping	do	do	do
	2) Terrace level	do	do	do
	a) Discharge of pump	do	do	do
	b) Head of pump	do	do	do
	c) Power supply	do	do	do
	d) Auto starting of pump	do	do	do
<b>14.</b>	<b>Captive Water Storage for Fire Fighting</b>			<b>Provided and maintained by Mall</b>
	1) Under ground tank capacity	do	do	do
	a) Draw-off connection	do	do	do
	b) Fire service inlet	do	do	do
	c) Access to tank	do	do	do
	d) Over head tank capacity	do	do	
<b>15.</b>	<b>Exit Signage.</b>	<b>Provided and maintained by Mall</b>		
<b>16.</b>	<b>Provision of Lifts.</b>			<b>Provided and maintained by Mall</b>
	a) Pressurization of lift shaft	do	do	do
	b) Pressurization of lift lobby	do	do	do
	c) Communication in lift car	do	do	do
	d) Fireman's switch	do	do	do

	e) Lift signage	do	do	
1.	<b>Stand by Power Supply</b>	<b>Provided and maintained by Mall</b>		

<b>18.</b>	<b>Refuge Area</b>			
	Total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
<b>19.</b>	<b>Fire Control Room</b>	<b>Provided and maintained by Mall</b>		
	a) Detector system panel	do	do	do
	b) Flow switch panel	do	do	do
	c) PA system panel	do	do	do
	d) Battery backup	do	do	do
	e) Building floor plan	do	do	do
<b>20.</b>	<b>Special Fire Protection System for Protection of special Risk, if any:</b>			N/A


The fire protection system provided in the building were checked and found functional at the time of inspection.

**The Mall has been issued fire safety certificate vide letter no. F6/DFS/MS/2013/SZ/1140 dated 30.10.2013.**

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up please.

Signature of the inspecting officer

  
6/11/2013

Name :- D.B. Mukherjee.

Designation :- Assistant Divisional Officer.