## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID: <a href="mailto:cfohq.dlfire@nic.in">cfohq.dlfire@nic.in</a>

No F 6 / DFS / MS / GH / 2013 / NO Z / 1337

Dated 24/12/13

## **FIRE SAFETY CERTIFICATE**

Certified that the Hotel Klick International at, 3357, Gali Hari Mandir Marg, Pahar Ganj, New Delhi – 110055 comprised of ground floor (05 guest rooms + reception), 1st floor to 3rd floor (07 guest rooms at each floor), 4th floor (05 guest rooms) and 5th floor (Sealed with bricks wall) total 31 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2010/3183 dated 15-11-2010. The premises was re-inspected by the officer concerned of this department on 04-11-2013 in the presence of Mr. Shanu (GM) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Guest house of 31 guest rooms with effect from --2-4-12-1--2013 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G. C. Misra) Chief Fire Officer Delhi Fire Service Ph – 011-23414333

O'c ML

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi 110049 w.r.t. letter No 43989/Joint.C.P./Lic(H) New Delhi 02-09-13.
- 2. Hotel Klick International at, 3357, Gali Hari Mandir Marg, Pahar Ganj, New Delhi 110055

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.



## **INSPECTION REPORT**

1. Name & address of the building : Hotel K lick International 3357, Gali Hari Mandir Marg, Pahar Ganj, New

Delhi - 110055

2. Type of Occupancy

: Residential (guest House) G+5 Floors (5th floor Sealed With bistchi)

3. Type of Case : RENEWAL

: F6/DFS/MS/GH/2010/3183 4. Details of previous NOC Dt 15/11/2010

Fire Safety directives Letter No.

Date of inspection 04/11/2013

Name of the Inspecting Officer : M.K.Sharma (Assistant Divisional Officer)

Name and designation of Officer

from the building side : Mr. Shanu (GM)

Year of Construction : 2007

10. Applicant's letter No. : 43989 /Joint.CP/Lic(H) dt New Delhi 02/09/2013

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site (PSS Area)	Remarks MR/NMR (P.S.S Area)
1.	Access of building			
	Road width	NA	4 mt	MR
7	Gate width	1.5 mt	1.5 mt	· MR
5 8	Width of internal road	NA	NA	NA NA
2.	Number, width, Type & Arrangements of	fexits		
	Number of staircases	01	01	MR
D 2	Upper floors	01	01	MR
	Basements	NA	NA	NA -
	Width of staircases		11.511.6	S C C C C C C C C C C C C C C C C C C C
	• Upper floors	.80 mt	1.20 mt	MR
	Basements	NÁ	NA	NA MARINE
	c.Protection of exits			
	Fire check door	NA	NA	NA NA
	Pressurization	NA	NA	NA -

new

2/7

	No of continuous staircase to terrace	01	P	MR	
	Width Of Corridor	1.25 mt	1.25 mt	MR	
	Door Size	NA	NA	·NA	
3.	Compartmentation				
	Fire check door	NA	NA	NA	
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA	
	<ul> <li>Fire Rating of shaft door</li> </ul>	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	Fire Dampers	NA	NA	NA	
4	Smoke managements System				
	Basements	NA	NA I	NA F	
	• Upper floors	12 ACPH	NATURAL	MR	
5	Fire Extinguishers				
	Total numbers	10	10	MR	
	• Types	ABC, Co <sub>2</sub> , Wco <sub>2</sub>	ABC,Co <sub>2</sub> , Wco <sub>2</sub>	MR	
	IS marking	YES	Provided	MR -	
6	First – Aid Hose Reels				
	Total numbers on each floor	01	01	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 mt	30 mt	MR	
	Nozzle diameter	05 mm	05 mm	MR	
7	Automatic fire detection and alarming system				
	Type of detectors	NA	NA Tributa	NA	
	<ul> <li>Location of Main Panel</li> </ul>	NA	NA MARINE	NA	
	Location of Repeater Panel	NA	NA PRINTER	NA	
	Alternate source of power	NA	NA 3	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	YES	P	MR	
9	Public Address System	NA	NA	NA	
10	Automatic Sprinkler System				
	• Basements	NA	NA	NA	
	Upper Floor	NA	NA - 1-30 - 1-20 - 1	NA	
		1		A STATE OF THE REAL PROPERTY.	



11	Internal Hydrants			
	Size of riser/down- comer	NA	NA	NT A
	<ul> <li>Number of hydrants per floor</li> </ul>	NA	NA	NA
	Hose Box	NA	NA	NA
12	Yard Hydrants	1771	INA	NA
	Total number of hydrants	NA		
	Hose Box	415.45.4	NA	NA
13	Pumping Arrangements	NA	NA	NA
	Ground Level			
	700			
	Discharge of main pump	NA	NA	NA
	Head of main pump	NA	NA	NA
	<ul> <li>Number of main pumps</li> </ul>	NA	NA	NA
	<ul> <li>Jockey pump out put</li> </ul>	NA	NA	NA
	<ul> <li>Jockey pump head</li> </ul>	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	Standby Pump Head	NA	NA	NA
	auto Staring/Manual stopping	NA	NA	NA
	<ul> <li>Pump House Access</li> </ul>	NA	NA	NA
	o Terrace level	NA	NA	NA
	Discharge of pump	NA	NA	NA
	Head of the pump	450 LPM	450 LPM	MR
	Power supply	30 mt	30 mt	MR
	Auto starting of pump	YES	Provided	MR
			Trovided	IVIK
	Captive water Storage for fire fighting	NA	NA	274
	Under ground tank capacity	NA	NA NA	NA
	Draw of connection	NA		NA
	• Fire service inlet	NA	NA NA	NA
	<ul> <li>Access to tank</li> </ul>	YES .	NA	NA
	Overhead Tank capacity		Provided	MR
-	Exit Signage	2500 ltr	2500 ltr	MR
	Provision of Lifts	YES	Provided	MR
	ASIGN OF LITES	NA	NA	NA



Pressurization of Lift Shaft     Pressurization of lift Johny	NA	NA	NA		
ressurization of fift loopy	NA	NA	NA		
• Communication in lift Car	NA	NA	NA		
<ul> <li>Fireman's Grounding Switch</li> </ul>	NA	NA	NA		
Lift Signage	NA	NA	NA		
17 Standby power supply	NR	Provided	MR		
18 Refuge Area			1.22		
Total area	NA	NA	NA		
• Location	NA	NA	NA		
19 Fire control room					
Detector system panel	NA	NA	NA		
Flow Switch Panel	NA	NA	NA		
PA System Panel	NA	NA	NA		
Batter backup	NA	NA	NA		
Building Floor Plans	NA	NA	NA		
Special Fire Protection Systems for	YES	ABC,Co <sub>2</sub>	MR		
Protection of special Risks, if any;					

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/GH/2010/3183 dated 15/11/2010 may be renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended. Accordingly, Mcommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma
Designation: - A. D.O. (CC)

Dy CFO (NDZ)