## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DF3/ms/school/2013/1333

Dated: 20/12/2013

## FIRE SAFETY CERTIFICATE

Certified that the Geeta Sr. Sec. School No.-2 at Geeta Chowk, Sultan Puri, Delhi110086 is comprised of Ground + One upper floor only owned / occupied by Geeta Sr. Sec.
School have complied with the fire prevention and fire safety requirements in accordance with
Director of Education Circular No. F6/Estate/CC/Fire/Safety/2011/3298-3398 dated
01/03/2011 and verified by the officer concerned of Fire Service on 21.11.2013 in presence of
Sh. S.P. Sharma (Principal) and that the building / premises is fit for occupancy class
Educational (Group-B) with effect from .... School No.-2 at Geeta Chowk, Sultan Puri, Delhi10086 is comprised by Geeta Sr. Sec.
School have complied by

## **Conditions for the validity of Fire Safety Certificate:**

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provision of building bye laws.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on <a href="https://www.dfs.Delhigovt.nic.in"><u>WWW.dfs.Delhigovt.nic.in</u></a>

Issued on 201/1/3 at New Delhi by.

(SANTOKH SINGH) CHIEF FIRE OFFICER DELHI FIRE SERVICE Phone:-23414250

E-mail: cfowz.dlfire@nic.in

Copy to :-

- 1. Sh. S.P. Sharma (Principal), Geeta Sr. Sec. School No.-2, Geeta Chowk, Sultan Puri, Delhi-110086.
- 2. The Director of Education, GNCT of Delhi, Old Secretariat, Delhi-110054.

School 1336/Datal 29/11/2011 INSPECTION REPORT 1. Name & address of the building: Geolg Senier Secondary School No-2, Geolg chook Sultanburi Delhi . Educational (G+1) 2. Type of Occupancy . New 3. Type of Case 4. Details of previous NOC : Letter No. Fire Safety directives Letter No.: - DO. E. Ciscular dated 01/03/2011 21 11 2013 Date of inspection 7. Name of the Inspecting Officer: ADO (A-K-JAISCOAL) S. P. Storma (Principal) 8. Name and designation of Officer from the building side : 1986 9. Year of Construction Greata No-2 | 2013-14 | 267 dt 20/9/13 10. Applicant's letter No. : -BBL DOF CIR Remarks MR/NMR Provided at S Minimum standards on fire Requirements 1 No prevention and fire safety U/R 33 site Access of building 1. Provided Accessible MR Road width Pravided Accessible MR Gate width NA NA NA Width of internal road 2. Number, width, Type & Arrangements of exits a. Number of staircases 4 MR Upper floors **Basements** NA b. Width of staircases 1.50 Mt. Upper floors NA **Basements** Protection of exits Fire check door MA Pressurization Provided d. No of continuous staircase MR to terrace 1.50 MM. e. Width Of Corridor f. Door Size 1:00 Mt.

Re-inspection to see the compliance of of live letter No F6/2FS/MS/2011/

3.	Compartmentation	2.00%	T	
-	Fire check door	-9 /7 / -		3
	THE SHEEK GOOT		19	
	<ul> <li>Sealing of electrical shafts</li> </ul>			
	*			
	<ul> <li>Fire Rating of shaft door</li> </ul>		NA	
	Water Cart			
	Water Curtain			
	Fire Dampers			
4.	Smoke managements System			
	Basements	20 -/ 1		
	Basements	30 a/c per hour	NA	NA
	Upper floors	12 a/c per hour		
		12 de per nour	NaturalVentikohi	n MR
5.	Fire Extinguishers			
	• Total numbers	16	20	MR
		ABC/COZ/Foam		TIR
	• Types	ISI marked	provided	109 R
	IS marking	131 Illaiked	Provided	.()
			provided	MR
6.	First – Aid Hose Reels			
	• Total numbers on each	,		
	floor			
	<ul> <li>Length of hose reel hose</li> </ul>		MR	
	Length of hose feet hose			
	Nozzle diameter			
7.	Automatic fire detection and alarmin	ng system		
	• Type of detector	,		
	н			
	<ul> <li>Location of Main Panel</li> </ul>			
	• Location of Donesto D			
	• Location of Repeater Panel		NR	
	Alternate source of power			3
	or power			
	<ul> <li>Hooters' Location</li> </ul>			
8.	MOEFA		- NR	
9.	Dublic Address C			
10.	Public Address System Automatic Sprinkler System		NR-	
10.	Basements			
	- Dasements			
	Upper Floor			
			NR.	
	<ul> <li>Sprinkler above false</li> </ul>			
	ceiling			T. C.

1	Internal Hydronta			
11.	Internal Hydrants			
	Size of riser/down- comer			
	Number of hydrants per floor		NR-	
	Hose Box			
12.	Yard Hydrants	:		
	Total number of hydrants		MR	
10	Hose Box			
13.	Pumping Arrangements	*	,	
	Ground Level			
	Discharge of main pump			
	> Head of main pump			
	> Number of main pumps			
	> Jockey pump out put			
	> Jockey pump head			
	> Standby Pump out put		_	75.
	> Standby Pump Head			
	> Auto Staring/Manual stopping			
	Pump House Access		-	
	Terrace level	/		
	Discharge of pump			
	> Head of the pump			
	Power supply			4
	> Auto starting of pump		7	
14	. Captive water Storage for fire fight	ing		
	Under ground tank			
	capacity		~1	R
	Draw of connection		N	
	> Fire service inlet			2
	> Access to tank			
	<ul> <li>Overhead Tank capacity</li> </ul>			

15	Exit Signage	NR-	
16.	Provision of Lifts		
	Pressurization of Lift Shaft	1	3
	<ul><li>Pressurization of lift lobby</li></ul>		
	➤ Communication in lift Car	NA	
	<ul><li>Fireman's Grounding</li><li>Switch</li><li>Lift Signage</li></ul>		
17.	Standby power supply	NR-	
18.	Refuge Area		
	> Total area	NR.	
	> Location		
19.	Fire control room		
	Detector system panel		
	Flow Switch Panel		
	> PA System Panel	NR	
	➤ Batter backup		, '
	Building Floor Plans		
20	Special Fire Protection Systems for Protection of special Risks, if any;	- NA-	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Note; School Management has complied the office letter No F61 SFS | MS | 2011 | School | 3236 | 29.11.2017

Contol on Ng

Greeta Senior Secondary School No-Z Greetachowk, Sultanpuri, Delhi-110086 (G+1)

21/11/2013

Signature of the Inspecting Officer

Name (A.K.JAISCOAL)

Designation ADO (JWA)

D.0.(4)

Name

Designation

Signature of the Inspecting Officer