GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, Email: cfohq.dlfire@nic.in, Tel:- 011-23414000

No.F6/MS/DFS/ Banquet/ 20/3/52/1360

Dated: 30 12 13

FIRE SAFETY CERTIFICATE

Certified that the M/s Ten (A unit of JPS Catering Pvt. Ltd.) located at B-10, DDA Community Centre, Triveni Complex, Saikh Sarai, New Delhi -110017 comprised of Lower Ground Floor, Ground Floor plus Two Upper Floors, has Banquet Hall at Lower Ground Floor. The Banquet Hall was inspected by the officers concerned of this department on 27/11/13 in the presence of Mr. Manish Thakur (manager) and found that the said Banquet Hall have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the Banquet Hall is fit for occupancy class Group – D Assembly Building (Banquet Hall) with effect from (Banquet Hall) with effect from (Banquet Hall) and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 30 12 13 -- at New Delhi.

(Dr. G.C. Misra) CHIEF FIRE OFFICER

Copy to:- (1) Dy. Health Officer,
SDMC, South Zone,
Aurobido Marg, Green Park

(2) M/s Ten (A unit of JPS Catering Pvt. Ltd.) B-10, DDA Community Centre, Triveni Complex, Saikh Sarai, New Delhi -110017

Following fire safety directives must be adhered to:-

New Delhi-110043.

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1.Name & address of the building:- M/s Ten (A unit of JPS Catering Pvt. Ltd.) B-10, DDA Community Centre, Triveni Complex, Saikh Sarai, New Delhi -110070
- 2. Type of occupancy:- Group D, Assembly Building (Banquet Hall)
- 3. Type of case:- New
- 4. Details of previous NOC:- Nil
- 5. Fire safety directives No.- Nil
- 6. Date of inspection:-27/11/2013
- 7. Name of the inspecting officer:- Darampal Bhardwaj, DO(SZ); D.B.Mukherjee, ADO(BCP)
- 8. Name & designation of officer From the building side:- Mr. Manish Thakur (Manager)
- 9. Year of construction:- Nil
- 10.Applicant's letter No:-DHO/SZ/2013/D/2051 dated 16/02/13;

Lower Ground floor, Ground plus Two Upper Floors. Banquet hall is at Lower Ground Floor

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC/BBL	Provided at site	Remarks MR/NMR			
1.	Access to Building	NDC/DDL					
1.		Required	Provided	MR			
	1) Road width	Required	Provided	MR			
	2) Gate width		NA ANTONE W. SEDIMONIANO				
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arrangement of Exits						
	A. Number of staircases		27/4	DI/A			
	1. Upper floors	N/A	N/A	N/A N/A			
	2. Lower Ground Floor/Ground Floor	N/A	N/A	N/A			
	B. Width of staircase		27/1	DT/A			
	1. Upper floors	N/A	N/A	N/A			
	2. Lower Ground Floor/Ground Floor	N/A	N/A	N/A			
	C. Protection of exits			77/4			
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase	N/A	N/A	N/A			
	to terrace		a * c				
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	2 m.	Provided total 05 Nos of exits	MR			
			having width of 2.5m, 1.37 m,				
			1.37 m, 0.88 & 0.88 m				
			respectively.				
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	1) Basements / Lower Ground Floor	30 a/c per hou	r Exhaust Fans	MR			
	2) Upper floors	12 a/c per hou	r N/A	N/A			
5.	Fire Extinguishers						
5.	1) Total numbers		06 Nos.	MR			
	2) Types	ISI Marked	ABC & Co ₂	MR			
	3) ISI marking		Yes	MR			

6.	First-Aid Hose Reel				
	1) Total number of each floor	01 Nos.	02 D 11 1	1.5	
	2) Length of hose reel hose	30 m	02 nos. Provided	1111	
1.	3) Nozzle diameter	5 mm	Provided	MR	
7.	Automatic Fire Detection & Aları	ning System	Provided	MR	
	1) Type of detectors	27/4			
	2) Location of main panel	N/A N/A	N/A	N/A	
	3) Location of repeater panel	N/A N/A	N/A	N/A	
	4) Alternate source of power	N/A N/A	N/A	N/A	
	5) Hooter's Location	N/A N/A	N/A	N/A	
8.	MOEFA		N/A	N/A	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System	Required	Provided	MR	
	1) Basement/ Lower Ground Floor	D			
	2) Upper floors	Required	Provided	MR	
	3) Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants	N/A	N/A	N/A	
	1) Size of riser/down-comer				
	2) Number of hydrants per floor	N/A	N/A	N/A	
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants	N/A	N/A	N/A	
	1) Total number of least			1 1/11	
	1) Total number of hydrants 2) Hose box	Not Required	02 nos. Provided	MR	
13.		Not Required	Provided	MR	
	Pumping Arrangement			17117	
	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main pump	N/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level		IV/A	N/A	
	a) Discharge of pump	450 LPM	100 % 000 I DV	1.00	
	b) Head of pump	Required	180 & 900 LPM	MR	
	c) Power supply	Required	46 mtrs each	MR	
	d) Auto starting of pump	Required	Provided	MR	
ļ	Captive Water Storage for Fig.	re Fighting	Provided	MR	
	1) Under ground tank capacity N/A N/A				
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	Required	N/A	N/A	
	c) Access to tank	Required	Provided	MR	
	d) Over head tank capacity	5000 Ltrs	Provided	MR	
	Exit Signage.		10000 Ltrs	MR	
	Provision of Lifts.	Required	Provided	MR	
	The strain of the shall	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
ē	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
•	Stand by Power Supply	Yes	Provided DG Set	MR	

18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for	N/A		

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/------

Accordingly DFA is put up please.

Signature of the inspecting officer

Signature of the inspecting officer

Name: - Dharampal Bhardwaj

Designation:- Divisional Officer

Name:-D.B.Mukherjee.

Designation:- Assistant Divisional Officer.