GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F6/01=3/ms/Pett/2013/32/1374

Dated: 3 1 /12 //3

FIRE SAFETY CERTIFICATE

Certified that the M/s Captain Amit Service Station (Petrol Pump) located at Adjoining Hari Nagar Fire Station, Hari Nagar Ghanta Ghar Road, New Delhi-110064 is comprised of ground floor only was issued NOC by this department vide letter No.F.5/(3A)/DFS/PETL/2010/346 dated 27.12.2010. The Petrol Pump was re- inspected by the officer concerned of this department on 17.12.2013 in the presence of Retd. Col. Surender Verma (Owner) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group J Hazardous Building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 31/12 / 2013 at New Delhi.

(DR. G.C. MI\$RA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:_011-23414333

Copy to:-

The Manager,
 M/s Captain Amit Service Station,
 Adjoining Hari Nagar Fire Station,
 Hari Nagar Ghanta Ghar Road, New Delhi-110064.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPECT	TION REPORT				
	1. Name & address of the building:	Capt. Amit Capie	a chatian Adiana	11-14- 0.0		
	2. Type of Occupancy :	TICH SON	an Nagar chant	1 Hannagay Hub		
	3. Type of Case	New Case / Ronor	San Building	mr / repetru = //wey		
	4. Details of Previous NOC	Letter No. 55%	Nac local contract	lie II		
	5. Fire Safety directives letter No.	E = /0=12/2	ANDES/PETY 2010/	346 Date 27/12/10		
	 b. Date of inspection 	fficer $17 - 12 - 2013$				
	7. Name of Inspecting Officer					
	8. Name and designation of officers	HUO Sande	cep Diggal.			
	From the building side	Pul CI Co		1		
	9. Year of Construction .	2010	wender Verma	(Owner)		
- Commission of the Augustian	10. Applicant's letter No.	Mi) dated	1 00 10 0-11	Annual Section of Contract of		
S.	Minimum Standards on fire	NBC NBC	The state of the s	The state of the s		
No.	prevention and fire safety U/R 33	Requirement	Provided at	Remarks		
1.	Access to building	Requirement	site	MR/NMR		
	 Road width 		3			
	Gate width		12 mtos	MR		
	Width of internal road		6 morre	MR		
2.	Number, Width, Type & Arrangement	f = 1				
	a. Number of staircases	of Exits				
	• Upper Floors					
	• Basements			Ground flor only		
	b. Width of staircases		-	No Basement		
	Upper Floor			The second secon		
	Basements					
	c. Protection of exits					
	Fire check door					
	• pressurization		Page Comments of the Comments	1		
	d. No. of continuous staircases to					
	terrace to			· .		
	e. Width of Corridor					
	f. Door Size					
	3301 3126		and the second s			
3.	Compartmentation					
				The state of the s		
	Fire check door			1		
	Sealing of electrical shafts					
	Fire Rating of shaft door					
	Water Curtain					
	• Fire Dampers					
4.	Smoke Management System					
	Basements					
	Upper floors	30 a/c per		No Basement		
	SPECITIONS	hour				
			Physical Company of the Company of t	Grand Hear only		

Capt Amit Service Station. N/11
Adjoining Hari Dagar FICTH, Han Dagar GhantaGhar Road,

	U	0 000-64				
	Pump House Access					
	Terrace level			e ?		
	Discharge of pump		***************************************			
	Head of the pump					
	Power Supply					
	Auto Starting of pump		¥			
14.	Captive Water Storage for fire fighting					
	Underground tank capacity					
	> Draw-off connection					
	> Fire service inlet					
	Access to tank		V-			
	Overhead Tank capacity			-		
	Overnead rank capacity	¥ <u>.</u>		-		
				2 2		
15.	Exit Signage.	•	With the second			
				<u>.</u>		
16.	Provision of Lifts.	1		· 8		
	 Pressurization of Lift Shaft 			No lift		
	 Pressurization of Lift lobby 		Village Control of the Control of th	//		
	Communication In lift Car	,		-do -		
	Fireman's Grounding SwitchLift Signage			40		
		**************************************		-do		
			90 To 100	-do		
17.	Standby power supply		250 KVA			
18.						
	Refuge Area.					
10.	Refuge Area.					
10.	Refuge Area. > Total Area					
10.						
10.	> Total Area					
10.	> Total Area					
19.	> Total Area					
	➤ Total Area ➤ Location Fire Control Room					
	Fire Control Room Detector System Panel					
	Fire Control Room Detector System Panel Flow Switch Panel					
	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel					
	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup					
	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel					
19.	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans					
	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup					
19.	Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers......

Note: - The petrol pump promises in Comparised of ground flow only There are adequante quantity (03 No!) of "No Smoking "Sign boards displayed and ten numbers of cand buckets provided at the site. FSC is recommended for renewal please."

Signature of Inspecting Officer

Name Sandeep Duggal

Designation Assit. Divisional officer

Signature of Inspecting Officer

Name

Designation