## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID: <a href="mailto:cfohq.dlfire@nic.in">cfohq.dlfire@nic.in</a>

No. F6/DFS/MS/GH/2013 /102/197/

Dated 3/1/2/13

## **FIRE SAFETY CERTIFICATE**

Certified that the Guest House in the name & style of Anmol International located at 8180/6, Arakashan Road, Pahar Ganj, New Delhi comprised ground floor (02 guest rooms + reception), 1<sup>st</sup> floor to 3<sup>rd</sup> floor(05 guest rooms at each floor), 4<sup>th</sup> floor(04 guest room) and Terrace floor (sealed with brick wall) total 21 guest rooms was granted NOC by this department vide letter No F6/DFS/MS/GH/2010/3190 dated 16/10/2010. The premises was re-inspected by the officer concerned of this department on 21-12-2013 in the presence of Mr. Pawan Katyal (Owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and the building is fit for occupancy of 18 guest rooms with effect from 31/1/2 1/12 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 3/1/12 12013 at New Delhi by.

(Dr G. C. Misra) Chief Fire Officer Delhi Fire Service Ph – 011-23414333

## Copy to:-

- 1. The Joint. Commissioner of Police(Lic), First Floor, P.S. Defence Colony New Delhi- 110049 w.r.t. letter no 48585/Joint. C.P./Lic(H)/ dated New Delhi 21-10-2013.
- 2. Anmol International located at 8180/6, Arakashan Road, Pahar Ganj, New Delhi.

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

**INSPECTION REPORT** 

1. Name & address of the building

: Anmol International Guest house, 8180/6, Arakashan Road, Pahar

Ganj, New Delhi.

2. Type of Occupancy

: Residential (guest house) G+4 Floor

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/GH/2010/3190 dated 16/11/2010

5. Fire Safety directives Letter No.

: NA

6 Date of inspection

: 21/12/2013

7 Name of the Inspecting Officer

: M. K. Sharma (Assistant Divisional Officer)

8 Name and designation of Officer

from the building side

: Mr. Pawan Katyal (Owner)

9 Year of Construction

: 2001

10. Applicant's letter No.

: 48585/Joint.C.P./Lic.(H) dated New Delhi the 19/09/13

S No	Minimum standards on fire prevention	BBL	Provided at site	Remarks
	and fire safety U/R 33	Requirements	(PSS Area)	MR/NMR
			* :: : : : : : : : : : : : : : : : : :	(P.S.S Area)
1.	Access of building			
	Road width	NA	4 mt	MR
	Gate width	1 mt	1.5 mt	MR
	Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements of	exits	1	
	a. Number of staircases			
	• Upper floors	01	01	MR
	Basements	NA	NA	NA
	b.Width of staircases			1111
	• Upper floors	.8 mt	1.2 mt	MR
	• Basements	NA	NA	NA NA
	cProtection of exits		- 12.2	11/1
	Fire check door	NA	NA	NA

mersh

	Pressurization	NA	NA	NA	
	d. No of continuous staircase to terrace	01	Provided	MR	
	e. Width Of Corridor	NA	NA	NA	
	f. Door Size	NA	NA	NA	
3.	Compartmentation				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	• Fire Dampers	NA	NA	NA	
4	Smoke managements System				
	Basements	30 ACPH	NA	NA	
	• Upper floors	12 ACPH	NATURAL	MR	
5	Fire Extinguishers				
	Total numbers	08	10	MR	
	• Types	ABC, CO <sub>2</sub> , Wco <sub>2</sub>	ABC, CO <sub>2</sub> , Wco <sub>2</sub>	MR	
	IS marking	YES	Provided	MR	
6	First – Aid Hose Reels				
	Total numbers on each floor	01	01	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 mt	30 mt	MR	
	Nozzle diameter	05 mm	05 mm	MR	
7	Automatic fire detection and alarming system				
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	YES	Provided	MR	
9	Public Address System	YES	Provided	MR	
10	Automatic Sprinkler				
	Basement	NA	NA	NA	

	Pressurization	NA	NA	NA		
	d. No of continuous staircase to terrace	01	Provided	MR		
	e. Width Of Corridor	NA	NA	NA		
	f. Door Size	NA	NA	NA		
3.	Compartmentation	Compartmentation				
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4	Smoke managements System					
	Basements	30 ACPH	NA	NA		
	• Upper floors	12 ACPH	NATURAL	MR		
5	Fire Extinguishers					
	Total numbers	08	10	MR		
	• Types	ABC, CO <sub>2</sub> , Wco <sub>2</sub>	ABC, CO <sub>2</sub> , Wco <sub>2</sub>	MR		
	IS marking	YES	Provided	MR		
6	First – Aid Hose Reels					
	Total numbers on each floor	01	01	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 mt	30 mt	MR		
	Nozzle diameter	05 mm	05 mm	MR		
7	Automatic fire detection and alarming system					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
8	MOEFA	YES	Provided	MR		
9	Public Address System	YES	Provided	MR		
10	Automatic Sprinkler					
	Basement					

15	Exit Signage	YES	Provided	MR	
16	Provision of Lifts	NA	NA	NA	
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of lift lobby</li> <li>Communication in lift Car</li> <li>Fireman's Grounding Switch</li> </ul>	NA	NA	NA	
		NA	NA	NA	
		NA	NA	NA	
		NA	NA	NA	
	Lift Signage	NA	NA	NA	
17	Standby power supply	NR	Provided	MR	
18	Refuge Area				
	Total area	NA	NA	NA	
	• Location	NA	NA	NA	
19	Fire control room				
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection Systems for	YES	ABC	MR	
	Protection of special Risks, if any;	3	2.3		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/GH/2010/3190 dated 16/11/2010 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended

Signature of the Inspecting Officer

Name :- M.K. Sharma

Designation :- A. D.O. (CC)

DO (CD) - E/L

Laym