GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/FH/2014/ 52 57

Dated: 15/01/2019

FIRE SAFETY CERTIFICATE

Certified that the **Regal Mannor Farm House** located at Farm House No. 673, Main Road, Rewla Khanpur, Najafgarh, New Delhi comprised of ground floor only (Two rooms with kitchen & toilet) was inspected by the officers concerned of this department on 06.01.2014 in the presence of Sh. Pragya Gandotra and found that the said farm house have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class Group D Assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

1 The Assistant Engineer (Bldg),
Building Deptt. Najafgarh Zone,
South Delhi Municipal Corporation,
1st Floor, New Zonal Bldg., Dhansa Stand,
Najafgarh, New Delhi-110043.
(Ref. No. EE(B)NGZ/13/D-1158 dated 24.10.2013)

2 Smt. Pooja Gandotra (Owner) Regal Manor Farm House, Farm House No-673, Main Road Rewla Khanpur, Najafgarh, N.D.

	INSPECTION REPORT									
	1. Name & address of the building: Regal Manor of farmhouse no 673, Main Rewaldown Roof, 2. Type of Occupancy 3. Type of Case Assembly Nicola dampur Roof, Assembly									
	2. Type of Occupancy	Regar Ivianos	at tarmhouse no	673, Main Rewlakhandus Rood,						
	3. Type of Case	HSSEMBLY		NDelhi - 1						
	4. Details of Previous NOC									
and the same of th										
	b. Date of inspection									
	7. Name of Inspecting Off:									
	8. Name and designation of officers Do S. K. Tomar and Allo Candel Duggel									
	From the building of the									
	9. Year of Construction : Before 2000									
-	10 Applicant I	Elebra lala	250 a 901al							
S.	Minimum Standards on fire	NBC	1158 dr 24/0/13							
No.	prevention and fire safety U/R 33		Provided at	Remarks						
1.	Access to building	Requirement	site	MR/NMR						
	Road width	Λ								
	Gate width	Accessible		MR						
	Width of internal road	-90	530 & 300 cms	MR						
2.	Number Width Type & Assessment									
	Number, Width, Type & Arrangement of a Number of staircases	† Exits								
	• Upper Floors									
	• Basements	Value and the second		Grand How only						
	b. Width of staircases		* Application of the state of t	-do-						
	Upper Floor		,							
	Basements	•		Ground flavour						
	c. Protection of exits	-		lie do						
	Fire check door			No puserse						
	• pressurization	-		No.						
	d. No. of continuous staircases to			A second						
	terrace to		8							
	e. Width of Corridor			:						
	f. Door Size	-	-	7						
		-	ob we set and							
3.	Compartmentation	<u> </u>	open ground							
	Fire check door									
			-							
	Sealing of electrical shafts Fire Batter - Sealing of the		A							
	Fire Rating of shaft door		Name of the last o							
To a second	Water Curtain									
	• Fire Dampers									
4.	Smoke Management System									
	Pacomout.									
Annual An	Upper floors	30 a/c per hour		No Basement						
			-	No Basement Grand Hoor only						
				The state of the s						

On the second of the		7	8. 	-
		12 a/c per hour		30 3
5.	Eiro Extina de la			e e
J	Fire Extinguishers			
	• Total numbers	04 NO11	possided	MP
	• Types	ABC 4 (02	-de	MP
6.	 IS marking First-Aid Hose Reels 	ISI marked	-de-	ND
0.			2	
	Total numbers on each floor	<u>Bne</u>	at Cround flax	112
	 Length of hose reel hose 	30 m	Provided	410
7.	Nozzle diameter	5 mm	- d'e	MR
1.	Automatic fire detection and alarming	system		
	 Type of detectors 		A second	
	 Location of Main Panel 			
	 Location of Repeater Panel 			
	 Alternate source of power 			
	 Hooters' Location 		4	
8.	MOEFA	Required	Provided	1.60
9,	Public Address System	Not Regin	1 10VVCEG	MK
10.	Automatic Sprinkler System	1 00 00 regive		
	 Basement 	NR		
	Upper Floor	- NR		
	 Sprinkler above false ceiling 	NR	1	
11.	Internal Hydrants	101		
	 Size of riser/down-comer 	100 mm	franded	
	 Number of hydrants per floor 			MA
	 Hose Box 	one	Provided	MK
12.	Yard Hydrants	One	foorided	MK
	 Total number of hydrants 		1.	
	Hose Box		2	
13.	Pumping Arrangements			
,	 Ground Level 			
	Discharge of main Pump		E-manufacture -	
- 140	Head of Main pump			
	Number of main pumps			
	> Jockey Pump out put		The second section of the section of th	-
	Jockey pump head		-	1
	Standby Pump out put			
	Standby Pump Head		Í	
	Auto Starting/Manual			
	stopping		1	
i			1	

Regal Manor, form house no 673, Main Road Rowlakhan pur, N/8 NDellie

	N D						
	> Pump House Access	A promocon and a second					
	Terrace level						
	Discharge of pump	450 C/n	Provided	MR			
	> Head of the pump	40 mm	1.0000				
	Power Supply	Required		MR			
	Auto Starting of pump	Required	-do	MA			
		V					
14.	Captive Water Storage for fire fighting						
	 Underground tank capacity 		***************************************				
	Draw-off connection	-					
	Fire service inlet	-					
	Access to tank						
	 Overhead Tank capacity 	. 01	0 11				
		iooo lly	franced	MIL			
15.	Exit Signage.	Regurred	fronded	MR			
16.	Provision of Lifts.						
20.	Pressurization of Lift Shaft		Γ				
				No lift			
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 			-do-			
			1	The second			
				-do			
				-do			
17.	Standby power supply	Required	Porrided	MR			
18.	Refuge Area.						
	> Total Area	22					
	> Location						
19.	Fire Control Room						
2	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 						
				1			
		Security of the Control of the Contr					
		was a second and a second as a	T-				
		-	The second secon	¥ 1			
20.	Special Fire Protection System for Protection of special Risks, if any:						
				in SV			

Can

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Note: Farm house is composited of ground flow only. The proposed basewest was not consmicted by the country as per the affidaint given by the country dated 12-10-2013. FSC is recommended for ground-flow only.

Signature of Inspecting Officer

Name S.K. Tomav

Designation Divisional Officer

Signature of Inspecting Officer

Name Sandeep Duggal.

Designation Assit Divisional officer