GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax 23412593

E-mail:- cfohq.dlfire@nic.in

No F 6 / DFS / MS / EH / 2014 / NDZ / 75

DATED 17/01/19

FIRE SAFETY CERTIFICATE

Certified that the Great Plates Restaurant at Shop no. 1,2,3, GF, DLF Galleria Mall, Plot no. 1B, District Centre, Mayur Vihar Phase-1, Delhi, owned/occupied by A Unit of M/s Avisons Works Pvt. Ltd., have complied with the fire prevention and fire safety requirements in accordance with N.B.C. Part IV and verified by the officer concerned of the fire service on 04/01/2014 in the presence of Sh. Abhi Jain (Owner) of the restaurant and found that the building (shop no. 1,2,3) is fit for occupancy Group- D 'Assembly Building' (Resturant) with effect from 17/01/19 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service Ph. No. 23414333

To:-

 The Dy. Health Officer, East Delhi Municipal Corporation Health Department, Karkardooma South Zone, Shahdara, Delhi

Copy to:-

2. Great Plates Restaurant A Unit of M/s Avisons Works Pvt. Ltd Shop no. 1,2,3, GF, DLF Galleria Mall, Plot no. 1B, District Centre, Mayur Vihar Phase-1, Delhi

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

6. All comments/ directions of the Licensing Department shall always be permitted and followed.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Great Plates Restaurant at Shop no.1,2,3, GF,DLF Galleria Mall,

Plot No.1B, District Centre, Mayur Vihar -1, Delhi.

2. Building Comprised of

: Basement, ground plus two upper floors

3. Type of Occupancy

: Assembly

4. Type of Case

: New Case

5. Details of Previous NOC

F.6/DFS/MS/2011/642 dated 11.04.2011 for Galleria Mall

6. Fire Safety directives No

7. Date of Inspection

: 03.01.2014

8. Name of the Inspecting Officer: DO Virendra Singh

9. Name of the designation of Officer

From the building side 10. Year of Construction

: Sh. Abhi Jain (Owner) : 2006

11.Ap	oplicant's letter No : DHO/Shd.(S)Z	one/2012/2444 da	ated 11.12.2013			
	Minimum Standards on fire prevention and fire safety U/R33	NBC Requirement	Provided at Site	Remarks MR/NMR		
1	Access to building					
	Road width	12 Mtrs	24 Mtrs.	MR		
	Gate width	4.5 Mtrs.	6 Mtrs.	MR		
	Width of internal road	6 Mtrs.	6 Mtrs.	MR		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	N/A	N/A	N/A		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases					
	Upper Floor	N/A	N/A	N/A		
	Basement	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	N/A	N/A	N/A		
	g. Width of Corridor h. Door Size	N/A	N/A	N/A		
		02 Mtrs.	02. M one no. & 1.20 M three nos.	MR		
3	Compartmentation.					
	Fire check door	Required	Provided	MR .		
	 Sealing of electrical shafts 	Required	Sealed	MR		
	Fire rating of shaft door	2 hrs.	2 hrs	MR		
	Water curtain	N/A	N/A	N/A		
	Fire Dampers	Required	Provided	MR		
	Smoke Management System.					
	• Basement	N/A	N/A	N/A		
	Upper floor	12 a/c per hour	12 a/c per hour	MR		
	Fire Extinguisher					
	Total numbers	04 Nos.	04 Nos.	MR		
	• types	ABC & Co2	ABC & Co2	MR		
-						

	First-aid-Hose Reels.			
	Total numbers of each floor	1 no.	1no.	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
	Automatic fire detection and alarming syste	m.		1
	Type of detectors	Heat & smoke	Provided	MR
	 Location of main panel 	Reception	Provided	MR
	 Location of repeater panel 	Reception	Provided	MR
	 Alternate source of power 	Battery & DG Set	Provided	MR
	Hooters's location	Different	Different	MR
	Tiouters s location	Location	Location	
}	MOEFA	Required	Provided	MR
)	Public address System.	Required	provided	MR
10	Automatic Sprinkler System.			
	• basement	N/A	N/A	N/A
	upper floor	N/A	N/A	N/A
	sprinkler above false ceiling	Required	provided	MR
11	Internal Hydrants	A COMMENT OF THE PROPERTY OF THE SECOND STREET, THE		6 '
11	size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.	The second secon	at the state of th	
12	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.	Provided for	entire mall/bldg.	
	Ground Level	Required	Provided	MR
	Discharge of main Pump	4500 LPM	4500 LPM	MR
	Head of Main Pump	60 mtrs	60 mtrs	MR
	> Number of main pumps	2 nos.	2 nos.	MR
	> Jockey pump out put	180 LPM	180 LPM	MR
	Jockey pump head	60 mtrs.	60 mtrs.	MR
	Standby pump out put	4500 LPM	4500 LPM	MR
	Standby pump Head	60 Mtrs.	60 Mtrs.	MR
	Auto Starting / Manual stopping	Required	Auto	MR
	Pump House Access	Required	Provided	MR
	Terrace Level			
	Discharge of pump	450 LPM	450 LPM	MR
	➢ Head of the Pump	60 Mtrs.	60 Mtrs.	MR
-	Power supply	Required	Provided	MR

	Auto Starting of pump	Required	Auto	MR
14	Captive Water Storage for Fire Fighting.	Provided for	entire building	7 7 1 1 1 1
	 Underground tank capacity 	4,50,000 Ltrs	4,50,000 Ltrs.	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 Ltrs.	20,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided in	Main building	INIIX
	 Pressurization of Lift Shaft 	Required	Provided	MR
	Pressurization of Lift lobby	Required	Provided	MR
	Communication in lift car	Required	Provided	MR
	 Firemen's grounding switch 	Required	Provided	MR
-	Lift Signage	Required	Provided	MR
L7	Standby power supply	Required	Provided	MR
8	Refuge Area.			
	Total area	N/A	N/A	N/A
0	• Location	N/A	N/A	N/A
9	Fire Control Room	Provided for	Entire building	1.7/
	Detector system panel	Required	Provided	MR
	 Flow switch panel 	Required	Provided	MR
	 PA system panel 	Required	Provided	MR
	Battery backup	Required	Provided	MR
	 Building Floor Plans 	Required	Provided	
0	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	MR N/A

The fire protection systems provided in the restaurant including entire building were tested checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010. FSc for main building (alone male) was issued by this dept wale

Signature of the inspecting Officer

Name

VIREMORA SINGH

Designation

Do (E)

Dy CFO (MD2)