GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

Ph.23414333, Fax: 23412593, E-mail:cfohq.dlfire@nic.in

No. f6/Dfs/ms/schwl/noly/M92/168

Dated: 05/02/14

FIRE SAFETY CERTIFICATE

Issued on at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service

de lu

To.

The Principal,
Sadbhawna Shiksha Sadan,
C-39/40, Patel Chowk, Gali No.-1,
Shanti Nagar, Delhi-110094.

Copy:-

The Dy. Director of Education, B–Block, Yamuna Vihar, Delhi-110053.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

IRN/3

INSPECTION REPORT

1. Name & address of the building

: Sadbhawna Shiksha Sadan, C-39/40,

Patel Chowk, Gali No.-1, Shanti Nagar, Delhi-94.

2. Building is comprised of

: Ground plus first floor only.

3. Type of Occupancy

: Educational

4. Type of Case

: New

5. Details of Previous NOC letter

: F.6/DFS/MS/2007/1852 dated-12/07/2007 (Previous NOC for ground floor only)

6. Fire Safety direction letter No

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

7. Date of Inspection

: 18/01/2014

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer:

from the building side

: Mrs. Gita Rathore (Principal)

10. Year of Construction

: 2005

11. Applicant's letter No

: Letter No.-10, Dated-04/01/2014

| S.NO. | Minimum Standards on fire prevention and fire safety U/R33 | Circular Requirement | Provided at Site | Remarks MR/NMR | | |
|-------|--|-------------------------|------------------|--------------------|--|--|
| 1 | Access to building | requirement | Oile | I IVII X/I VIVII X | | |
| | Road width | 06 mtr. | 06 mtr. | MR | | |
| | Gate width | N/A | N/A | N/A | | |
| | Width of internal road | N/A | N/A | N/A | | |
|) | Number, Width, Type and Arrangement of Exits | | | | | |
| | a. Number of Staircases | | . 2 | V, 5 0 0 | | |
| | Upper Floor | 01 Nos. | 02.Nos. | MR | | |
| | Basement | N/A | N/A. | N/A | | |
| | B. Width of Staircases | | | | | |
| | Upper Floor Basement C. Protection of exits Fire check door Pressurization d. No. of continuous staircases to terrace e. Width of Corridor | 1.50 mtr. | 1.10&1.10 mtr. | MR | | |
| | | N/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| | | | | | | |
| | | 01 Nos. | 01 Nos. | MR | | |
| | | 1.50 mtr. | 1.50 mtr. | (MR) | | |
| | f. Door Size | 1.00 Mtr. | 1,00 mtr. | MR | | |
| } | Compartmentation. | | | | | |
| | Fire check door | N/A | N/A | N/A | | |
| | Sealing of electrical shafts | N/A | N/A | N/A | | |
| | Fire rating of shaft door | N/A | N/A | N/A | | |
| | Water curtain | N/A | N/A | N/A | | |
| | Fire Dampers | N/A | N/A | N/A | | |

Sadbhawna Shiksha Sadan, C-39/40, Patel Chowk, Gali No.-1, Shanti Nagar, Delhi-94.

| 4 | Smoke Management System. | | | | | |
|-----|--|---------------------|------------|--|--|--|
| | Basement | N/A | N/A | N/A | | |
| | Upper floor | N/A | N/A | N/A | | |
| 5. | Fire Extinguishers | | | | | |
| | Total numbers | ū5 nos. | 08 nos. | MR | | |
| | types | ABC/CO ₂ | ABC /CO₂ | MR | | |
| | IS marking | ISI marked | ISI marked | MR | | |
| 6 | First-aid-Hose Reels. | | | The state of the s | | |
| | Total numbers on each floor | N/A | N/A | N/A | | |
| | Length of hose reel hose | N/A | N/A | N/A | | |
| | Nozzle diameter | N/A | N/A | N/A | | |
| 7 | Automatic fire detection and alarming | system. | | | | |
| | Type of detectors | N/A | N/A | N/A | | |
| | Location of main panel | N/A | N/A | N/A | | |
| | Location of repeater panel | N/A | N/A | N/A | | |
| | Alternate source of power | N/A | N/A | N/A | | |
| | Hooter's location | N/A | N/A | N/A | | |
| 8 | MOEFA | N/A | N/A | N/A | | |
| 9 | Public address System. | N/A | N/A | N/A | | |
| 10 | Automatic Sprinkler System. | | | | | |
| , 0 | Basement | N/A | N/A | N/A | | |
| | upper floor | N/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| 4.4 | - Opining | | | | | |
| 11 | Internal Hydrants | N/A | N/A | N/A | | |
| | size of riser/down-comer | N/A | N/A | N/A | | |
| | Number of hydrants per floor | | | | | |
| | Hose Box | N/A | N/A | N/A | | |
| 12 | Yard Hydrants. | | | | | |
| | Total number of hydrants | N/A | N/A . | N/A | | |
| | Hose Box | N/A | N/A | N/A | | |
| 13 | Pumping Arrangements. | | | | | |
| | Ground Level | | | | | |
| | Discharge of main Pump | N/A | N/A | · N/A | | |
| | Head of Main Pump | N/A | N/A | N/A | | |
| | Number of main pumps | N/A | N/A | N/A | | |
| | Jockey pump out put | N/A | N/A | N/A | | |
| | Jockey pump head | N/A | N/A | N/A | | |
| | Standby pump out put | N/A | N/A | N/A | | |
| | Standby pump Head | N/A | N/A | N/A | | |
| | Auto Starting /Manual | N/A | N/A | N/A | | |
| | stopping | AIIA | N1/A | NI/A | | |
| | > Pump House Access | . NA | N/A | N/A N/A | | |
| | Terrace Level | N/A | N/A | | | |
| | Discharge of pump | N/A | N/A | N/A | | |
| | > Head of the Pump | N/A | N/A | N/A | | |
| | > Power supply | N/A | N/A | N/A | | |
| | Auto Starting of pump | N/A | N/A | N/A | | |

Sadbhawna Shiksha Sadan, C-39/40, Patel Chowk, Gali No.-1, Shanti Nagar, Delhi-94.



IRN 5"

| 111 | Canting Mater Starage for Fire | NI/A | h 1 / A | K I / A | | |
|----------|--|------|---------|---------|--|--|
| i freely | Captive Water Storage for Fire Fighting. | N/A | N/A | N/A | | |
| | Underground tank capacity | N/A | N/A | N/A | | |
| | Draw-off connection | N/A | N/A | N/A | | |
| | Fire service inlet | N/A | N/A | N/A | | |
| | Access to tank | N/A | N/A | N/A | | |
| | Overhead Tank capacity | N/A | N/A | N/A | | |
| 15 | Exit Signage. | N/A | N/A | N/A | | |
| 16 | Provision of Lifts. | | | | | |
| | Pressurization of Lift Shaft | N/A | N/A | N/A | | |
| | Pressurization of Lift lobby | N/A | N/A | N/A | | |
| | Communication in lift car | N/A | N/A | N/A | | |
| | Firemen's grounding switch | N/A | N/A | N/A | | |
| | Lift Signage | N/A | N/A | N/A | | |
| 17 | Standby power supply | N/A | N/A | N/A | | |
| 18 | Refuge Area. | | | | | |
| | Total area | N/A | N/A | N/A | | |
| | Location | N/A | N/A | N/A | | |
| 19 | Fire Control Room | | | | | |
| | Detector system panel | N/A | N/A | N/A | | |
| | Flow switch panel | N/A | N/A | N/A | | |
| | PA system panel | N/A | N/A | N/A | | |
| | Battery backup | N/A | N/A | N/A | | |
| | Building Floor Plans | N/A | N/A | N/A | | |
| 20 | Special Fire Protection systems for protection of special Risks, if any: | N/A | N/A | N/A | | |

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the circular-F-16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11, it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name

Designation

on ADD

20 (8)