GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

Ph.23414333, Fax: 23412593, E-mail:-cfohq.dlfire@nic.in

No. F6/DFS/MS/School/2014/MD2/163

Dated: 31 01/19

FIRE SAFETY CERTIFICATE

Alun 317,

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

ole y

To,

The Principal, Gian Jyoti Public Middle School, F-7, 40 Foot Road, Ganga Vihar, Delhi -110094.

Copy:-

The Dy. Director of Education B–Block, Yamuna Vihar, Delhi-110053.

CONDITIONS

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/nauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building

: Gian Jyoti Public Middle School, F-7,

40 Foot Road, Ganga Vihar, Delhi -110094.

2. Building is comprised of

: Ground floor only.

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F6/DFS/MS/2010/3429 Dated-27/12/10

6. Fire Safety direction letter No.

: F16/Estate/CC/FS/2011/3298to3398 dt-01/03/11

7. Date of Inspection

: 13/01/2014

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer:

from the building side

: Mr. Brij Mohan Sharma (Manager)

10. Year of Construction

: 1984

11. Applicant's letter No.

: Letter No.-Nil, Dated-19/12/2013

S.NO.	The state of the s	Circular	Provided at	Remarks		
1	prevention and fire safety U/R33	Requirement	Site	MR/NMR		
-	Access to building					
	Road widthGate widthWidth of internal road	06 mtr.	06 mtr.	MR		
		N/A	N/A	N/A		
		N/A	N/A	· N/A		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases			3 - 3		
	 Upper Floor 	N/A	N/A	. N/A		
	 Basement 	N/A	N/A.	N/A		
	B. Width of Staircases			,		
	 Upper Floor 	N/A	N/A	. N/A		
	 Basement 	N/A	N/A	: N/A .		
	c. Protection of exits	N/A	N/A	N/A		
	 Fire check door 					
	 Pressurization 	N/A	N/A	N/A		
	d. No. of continuous staircases to terrace	N/A	N/A	N/A		
	e. Width of Corridor	N/A	N/A	N/A		
	f. Door Size	1.00 Mtr.	1.00 mtr.	AMR		
3	Compartmentation.					
	 Fire check door 	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire rating of shaft door 	N/A	N/A	N/A		
	 Water curtain 	N/A	N/A	N/A		
	 Fire Dampers 	N/A	N/A	N/A		

4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A	N/A			
5.	Fire Extinguishers						
	 Total numbers 	03 nos.	04 nos.	MR			
	types	ABC/CO ₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			
6	First-aid-Hose Reels						
	Total numbers on each floor	N/A	N/A	N/A			
	 Length of hose reel hose 	N/A	N/A	N/A			
	Nozzle diameter	N/A	N/A	N/A			
7	Automatic fire detection and alarming	svstem					
1	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
ρ	MOEFA	N/A	N/A	N/A			
8	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.	IN/A	IN/A	IVA			
IU		N1/A	N1/A	A1/A			
	 Basement 	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
***************************************	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
				` '			
	 Hose Box 	N/A	N/A	'N/A			
12	Yard Hydrants.						
	 Total number of hydrants 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	'N/A			
	> Head of Main Pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jookey pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby pump out put	N/A	N/A	N/A			
	> Standby pump Head	N/A	N/A	N/A			
	> Auto Starting /Manual	N/A	N/A	N/A			
	stopping						
	> Pump House Access	N/A	N/A	N/A			
	Terrace Level	N/A	N/A	N/A			
	➤ Discharge of pump	N/A	N/A	N/A			
	> Head of the Pump	N/A	N/A	N/A			
	> Power supply	N/A	N/A	N/A			
	> Auto Starting of pump	N/A	N/A	N/A			
	Gian Jvoti Public Middle School F-7 40						

Gian Jyoti Public Middle School, F-7, 40 Foot Road, Ganga Vihar, Delhi -110094.

14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A	
	 Underground tank capacity 	N/A	N/A	N/A	
	Draw-off connection	N/A	N/A	N/A	
	Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	 Overhead Tank capacity 	N/A	N/A	N/A	
15	Exit Signage.	N/A	N/A	N/A	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	 Pressurization of Lift lobby 	N/A	N/A	N/A	
	 Communication in lift car 	N/A	N/A	N/A	
	 Firemen's grounding switch 	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	Total area	N/A	N/A	N/A	
	 Location 	N/A	N/A	N/A	
19	Fire Control Room				
	 Detector system panel 	N/A	N/A	N/A	
	 Flow switch panel 	N/A	N/A	N/A	
	PA system panel	N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	 Building Floor Plans 	N/A	N/A	N/A	
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter no.-F6/MS/DFS/2010/3429 dated-27/12/2010 renewal under the circular-F-16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 is recommended.

Signature of the Inspecting Officer

Name Wijoup Berbooler

ADO

Submitted for approval please.