GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

Ph.23414333, Fax: 23412593, E-mail:-cfohq.dlfire@nic.in

No. f6/0fs/ms/school/2014/1402/152 Dated: 31/01/14

FIRE SAFETY CERTIFICATE

Certified that the Dhruv Public School at E-27, Gali No.-03, Bhagirathi Vihar, Phase-1, Delhi -110094. owned/occupied by Dhruv Public School, comprising of ground plus one upper floor was granted NOC vide letter No. F.6/MS/DFS/2008/591 dated 29/02/2008. The school building was inspected by the officer concerned of this department on 08/01/2014 in the presence of Mr. Keshav Singh, Manager of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular No-F-16/Estate/CC/FireSafety/2011/3298to3398 dated-01/03/2011 issued by the Director of Education and found that the school building is fit for occupancy class "B" conditions printed overleaf.

Issued on 31 01 14 at New Delhi by

(Dr. G.O. Misra) Chief Fire Officer Delhi Fire Service

Olc be

To.

The Principal, Dhruv Public School. E-27, Gali No.-03, Bhagirathi Vihar, Phase-1, Delhi -110094.

The Dy. Director of Education B-Block, Yamuna Vihar, Delhi-110053.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall

be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of

unauthorized construction/nauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

IRN-5

INSPECTION REPORT

1. Name & address of the building

: Dhruv Public School, E-27, Gali No.-03,

Bhagirathi Vihar, Phase-1, Delhi -110094.

2. Building is comprised of

: Ground plus first floor only.

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F6//DFS/MS/2008/591 Dated-29/02/2008

6. Fire Safety direction letter No

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

7. Date of Inspection

: 08/01/2014

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer:

from the building side

: Mr. Keshav Singh (Manager)

10. Year of Construction

: 2006

11. Applicant's letter No.

: Letter No.-D.P.S.12-13-14, Dated-16/12/2013

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site	Remarks MR/NMR		
1	Access to building					
4	 Road width 	06 mtr.	06 mtr.	MR		
	 Gate width 	N/A	N/A	N/A		
	 Width of internal road 	N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases			1		
	 Upper Floor 	01 Nos.	02 Nos.	MR		
	 Basement 	N/A	N/A.	N/A		
	B. Width of Staircases					
12.1	 Upper Floor 	1.50 mtr. edess	0.90&0.85 mtr.	MR		
	 Basement 	N/A	N/A	N/A		
	c. Protection of exits	N/A	N/A	N/A		
	Fire check door	N/A	N/A	N/A		
	 Pressurization 	·	States and the second			
	d. No. of continuous staircases to terrace	01 Nos.	02 Nos.	MR		
	e. Width of Corridor	1.50 mtr.	1.50 mtr.	MR		
	f. Door Size	1.00 Mtr.	1.00 mtr.	MR		
3	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire rating of shaft door 	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	 Fire Dampers 	N/A	N/A	N/A		

Dhruv Public School, E-27, Gali No.-03, Bhagirathi Vihar, Phase-1, Delhi -110094.

4	Smoke Management System.				
	Basement	N/A	N/A	N/A	
	 Upper floor 	N/A	N/A	N/A	
5.	Fire Extinguishers				
	 Total numbers 	05 nos.	05 nos.	MR	
	types	ABC /CO ₂	ABC /CO ₂	MR	
	IS marking	ISI marked	ISI marked	MR	
6	First-aid-Hose Reels.				
8	Total numbers on each floor	N/A	N/A	N/A	
	 Length of hose reel hose 	N/A	N/A	N/A	
	 Nozzle diameter 	N/A	N/A	N/A	
7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	N/A	N/A	
	 Location of main panel 	N/A	N/A	N/A	
	 Location of repeater panel 	N/A	N/A	N/A	
	 Alternate source of power 	N/A	N/A	N/A	
(9)	Hooter's location	N/A	N/A	N/A	
8	MOEFA	N/A	N/A	N/A	
9	Public address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.				
	Basement	N/A	N/A	N/A	
	upper floor	N/A	N/A	N/A	
	sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
*	size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
12	Yard Hydrants.		(-29.9.	²⁷ y=	
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
The state of the s	➤ Head of Main Pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby pump out put	N/A	N/A	N/A	
	Standby pump Head	N/A	N/A	N/A	
	Auto Starting /Manual stopping	N/A	N/A	N/A	
	> Pump House Access	N/A	N/A	N/A	
	Terrace Level	· N/A	N/A	N/A	
	Discharge of pump	N/A	N/A	. N/A	
	Head of the Pump	N/A	N/A	N/A	
	Power supply	N/A	N/A	N/A	
	Auto Starting of pump	N/A	N/A	N/A	
	Dhruy Bublia Sabaal E 27 Cali Na		1		

Dhruv Public School, E-27, Gali No.-03, Bhagirathi Vihar, Phase-1, Delhi -110094.

14	Ca ptive Water Storage for Fire	N/A	N/A	N/A
	Fighting.		21/2	N/A
	Underground tank capacity	N/A	N/A	
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	— 1 Line a south ole	N/A	N/A	N/A
		N/A	N/A	N/A
47	Lift Signage Standby power supply	N/A	N/A	N/A
17	Standby power supply	1477		
	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	• Location	14// \	107.	
19	Fire Control Room	N/A	N/A	N/A
	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	 PA system panel 		48 00 00	
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC issued vide letter no.F6//DFS/MS/2008/591 dated 29/02/2008 renewal under the circular no. F16/Estate/CC/FireSafety/2011/3298to3398

dt-01/03/11 is recommended.

Signature of the Inspecting Officer

Name

Vywy Bahadu

Designation

ADD

Submitted for approval please.