GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD OUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID:cfohq.dlfire@nic.in

No F6/MS/DFS/EH/ 2014/ HOZ/ 309 Dated 05/03/14

FIRE SAFETY CERTIFICATE

Certified that the M/s Zen Restaurant at B-25, Connaught Place, New Delhi - 110001 comprises of Ground + mezzanine floor in three storied building was granted NOC by this department vide letter No. F6/MS/DFS/EH/2010/2464 dated 23-08-2010. The premises was reinspected by the officers concerned of this department on 12-02-2014 in the presence of Sh. Ashok Thakur (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy with effect from \$\frac{\pi_3}{-1}\$-1-2014 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G. C. Misra) Chief Fire Officer Delhi fire Service Ph - 011-23414333 of c. Mc

Copy to:-

1. M/s Zen Restaurant at B-25, Connaught Place, New Delhi – 110001.

2. Sh. Devinder Singh special Secretary Tourism Department, Vikas Bhawan-11, 2nd floor, C-Wing, Upper Bela Road, Near Metcalf House Delhi- 110054.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

1. Name & address of the building : M/s Zen Restaurant at B-25, Connaught Place, New Delhi

2. Type of Occupancy : Assembly Bldg. (Restaurant) Gr. + Mezzanine floor

3. Type of Case : Renewal

4. Details of previous NOC : F6/MS/DFS/EH/2010/2464 dated 23/08/2010

5. Fire Safety directives Letter No. : NA

6 Date of inspection : 12/02/2014

7 Name of the Inspecting Officer : Sh. Rajesh Panwar Dy. CFO (NDZ), Sh. Gurmukh Singh

(DO/CD) & Sh. M. K. Sharma (ADO/CC)

8 Name and designation of Officer

from the building side : Sh. Ashok Thakur (Manager)

9 Year of Construction : old Heritage Bldg.

10. Applicant's letter No. : KSH/ZEN/FIR/13-14/03 dated 03/02/2014

| S No | Minimum standards on fire prevention | BBL | Provided at site | Remarks |
|------|---------------------------------------|-------------------|------------------|---------|
| | and fire safety U/R 33 | Requirements | | MR/NMR |
| 1. | Access of building | <u> </u> | | |
| | Road width | 9 Mt | 12 Mt | MR |
| | Gate width | NA | NA | NA |
| | • Width of internal road | NA | NA | NA |
| 2. | Number, width, Type & Arrangements of | fexits | | 12. |
| | a. Number of staircases | | a | |
| | • Upper floors | 2 Nos. | 2 Nos. | MR |
| | Basements | NA | NA | NA |
| | b.Width of staircases | | | |
| | • Upper floors | .80 Mt & 1 Mt old | .80 Mt &1 Mt old | MR |
| | Basements | NA | NA | NA |
| * 1, | c. Protection of exits | | | |
| | | NA | NA | NA |

not

| | Fire check door | NA | NA | NA | |
|----|--|---|--|----|--|
| | Pressurization | NA | NA | NA | |
| | d. No of continuous staircase to terrace | 01 | 01 | MR | |
| | e. Width Of Corridor | NA | NA | NA | |
| | f. Door Size | NA | NA | NA | |
| 3. | Compartmentation | | | | |
| | Fire check door | NA | NA | NA | |
| | Sealing of electrical shafts | NA | NA | NA | |
| | • Fire Rating of shaft door | NA | NA | NA | |
| | Water Curtain | NA | NA | NA | |
| | Fire Dampers | NA | NA | NA | |
| 1 | Smoke managements System | | | | |
| | Basements | NA | NA | NA | |
| | Upper floors | 12 ACPH | NATURAL | MR | |
| 5 | Fire Extinguishers | | | | |
| | Total numbers | 10 Nos. | 12 Nos. | MR | |
| | • Types | ABC, CO ₂ , Wco ₂ | ABC, CO ₂ , Wco ₂ | MR | |
| | IS marking | Required | Provided | MR | |
| 5 | First – Aid Hose Reels | | | * | |
| | Total numbers on each floor | 01 | 01 | MR | |
| | • Length of hose reel hose | 30 Mt | 30 Mt | MR | |
| | Nozzle diameter | 05 MM | 05 MM | MR | |
| 7 | Automatic fire detection and alarming sy | stem | | | |
| | Type of detectors | NA | NA | NA | |
| | Location of Main Panel | NA | NA | NA | |
| | Location of Repeater Panel | NA | NA . | NA | |
| | Alternate source of power | NA | NA | NA | |
| | Hooters' Location | NA | NA | NA | |
| } | MOEFA | Required | Provided | MR | |
|) | Public Address System | NA | NA | NA | |
| 0 | Automatic Sprinkler | | - Annual Control of the Control of t | | |

| | Basements | NA | NA | NA |
|-----|---|----------|-------------|----|
| | Upper Floor | Required | Provided | MR |
| | Sprinkler above false ceiling | NA | NA | NA |
| 11 | Internal Hydrants | | | |
| | Size of riser/down- comer | NA | NA | NA |
| | Number of hydrants per floor | NA | NA | NA |
| | Hose Box | NA | - NA | NA |
| 12 | Yard Hydrants | | | |
| . / | Total number of hydrants | NA | NA | NA |
| | Hose Box | NA | NA | NA |
| 13 | Pumping Arrangements | | | |
| | o Ground Level | | | |
| | Discharge of main pump | NA | NA | NA |
| | Head of main pump | NA | NA | NA |
| | Number of main pumps | NA | NA | NA |
| | Jockey pump out put | NA | NA | NA |
| | Jockey pump head | NA | NA | NA |
| | Standby Pump out put | NA | NA | NA |
| | Standby Pump Head | NA | NA 1 | NA |
| | auto Staring/Manual stopping | NA | NA | NA |
| | Pump House Access | NA | NA | NA |
| | o Terrace level | | in the same | |
| | Discharge of pump | 450 LPM | 900 LPM | MR |
| | Head of the pump | 30 Mtr. | 30 Mtr. | MR |
| | Power supply | Required | Provided | MR |
| | Auto starting of pump | Required | Provided | MR |
| | | 55 | | |
| 4 | Captive water Storage for fire fighting | NA | NA | NA |
| | Under ground tank capacity | NA | NA | NA |
| | Draw of connection | NA | NA | NA |
| | • Fire service inlet | NA | NA | NA |
| | | | · · | |

Mess

| | Access to tank | Required | Provided | MR |
|----|--|------------|----------------------|-----|
| | Overhead Tank capacity | 5,000 Ltr. | 5,000 Ltr. | MR |
| 15 | Exit Signage | Required | Provided | MR |
| 16 | Provision of Lifts | NA | NA | NA |
| | Pressurization of Lift Shaft | NA | NA | NA |
| | Pressurization of lift lobby | NA | NA | NA |
| | Communication in lift Car | NA | NA | NA |
| | Fireman's Grounding Switch | NA | NA | NA |
| | Lift Signage | NA | NA | NA |
| 17 | Standby power supply | Required | Provided | MR |
| 18 | Refuge Area | | | |
| | Total area | NA | NA | NA |
| | • Location | NA | NA | NA |
| 19 | Fire control room | | | * * |
| * | Detector system panel | NA | NA | NA |
| | Flow Switch Panel | NA | NA | NA |
| | PA System Panel | NA | NA | NA |
| - | Batter backup | NA | NA | NA |
| | Building Floor Plans | NA | NA | NA |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any; | Required | ABC, Co ₂ | MR |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/MS/DFS/EH/2010/2464 dated 23/08/2010 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Name:- Rajesh Panwar Designation:- D.C.F.O. (NDZ)

Name :- Sh. Gurmukh Singh Designation :-DO(CD) Name:- Sh. M. K. Sharma Designation :- A. D.O. (CC)