No.

FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE. CONNAUGHT PLACE

NEW DELHI

\$6 DBIMS 2014 421 321

Dated: 10 03/2014

FIRE SAFETY CERTIFICATE

Certified that the Pearls PGF Limited located at Plot no. B - 1, Netaji Subhash Place, Pitampura, Delhi - 110034 comprised of 3 Basement + Ground + 12 Upper Floors was issued FSC vide Letter No. F6/DFS/MS/2010/3108 dated 09-11-2010. The premises was re inspected by the officers concerned of this department on 18-02-2014 in the presence of Mr. Sam Peter (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class " Mercantile & Business Building" Group F & Group E 1-13/14 with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 16/3/19... at New Delhi by.

Chief Fire Officer. Delhi Fire Service. Ph: 011 - 23414250

Copy to:

1. Sh. Ravinder Sharma (Authorised Signatory). Plot No. B - 1. Netaji Subhash Place, Pitampura, Delhi 110034.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

Re inspection to see the compliance of shortcomings communicated vide letter no. F6/DFS/MS/2014/309 dated 06-02-2014.

INSPECTION REPORT

1. Name & address of the building: Pearls PGF Limited, B – 1, Netaji Subhash Place, Pitam Pura, Delhi – 110034.

2. Type of Occupancy : Mercantile + Business (Mixed), 2 Blocks (LG+G+10 Upper Floor & LG+G+5 Upper Floor)

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. F6/DFS/MS/2010/3108 dated 09-11-2010

5. Fire Safety directives Letter No.: Letter No. F6/DFS/MS/BP/2006/824 dated 04-04-2006

6. Date of inspection : 18-02-2014

7. Name of the Inspecting Officer: DO (West) & ADO (MN)

8. Name and designation of Officer

from the building side

: Sh. Sam Peter (Manager)

9. Year of Construction

: 2009

10. Applicant's letter No.

: OL/BD/R-FNOC/Pearl/2014 dated 30-01-2014

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR
	Access of building	requirements	Site	20 %
	Road widthGate widthWidth of internal road	22 m 6 m 6 m	Provided Provided Provided	MR MR MR
2.	Number, width, Type & Arrangeme a. Number of staircases	ents of exits		
	 Upper floors 	6 upto 3 rd , 4 upto 12 th Floor	Provided	MR .
	Basementsb. Width of staircases	6 + 2 ramps	Provided	MR
	Upper floorsBasements	Old Case Old Case	Old Case Old Case	Old Case Old Case
	 c. Protection of exits Fire check door Pressurization d. No of continuous staircase to terrace 	Required 'A	Provided Provided Provided	MR MR MR
	e. Width Of Corridor f. Door Size	Old Case Old Case	Old Case	Old Case Old Case
	Compartmentation			
	Fire check door	Required	Provided	MR

	 Sealing of electrical shafts Fire Rating of shaft door 	Required	Found Provide	ed MR			
	Fire Rating of shaft doorWater Curtain	Required	Found Provide	ed MR			
		Required	Provided	NR			
4	The bampers	Required	Provided	MR			
4.	Smoke managements System						
	 Basements 	30 a/c per hour	Required	MR			
	 Upper floors 	12 a/c per hour	Provided	MR			
5.							
٥.	Fire Extinguishers						
	• Total numbers	141 nos.	Provided	MR			
	• Types	CO2, WCO2.	Provided	MR			
	 IS marking 	ABC	Provided	MR			
6.	First – Aid Hose Reels	ISI marked					
	Total numbers on each	1 for upper fl-	D : 1 - 1				
	floor	4 for upper floor	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MAD			
	Nozzle diameter	5 mm	Provided	MR			
7.	Automatic fire detection and alarmi	ng system	Trovided	MR			
	Type of detectors	Smoke & Heat	Provided	MD			
	 Location of Main Panel 	Required	Provided	MR			
	Location of Repeater	Required	Provided	MR MR			
	Panel	Required	Provided	MR			
	 Alternate source of power 	Required	Provided	MR			
	 Hooters' Location 	- Coquinod	Trovided	IVIX			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System		,				
	Basements	Required	Provided	MR			
	• Upper Floor	Required	Provided	MR			
	Sprinkler above false	Required	Provided	MR			
11.	ceiling Internal Hydrants						
11.		1.70					
	Size of fisch down- comer	150 mm		MR .			
	 Number of hydrants per floor 	4 for upper floors	Provided	MR .			
	Hose Box	Required	D 11 1	N. 470			
12.	Yard Hydrants	required	Provided	MR			
	Total number of hydrants	Dogwinad	D :1.1	14			
	Hose Box	Required Required	A second	MR			
13.	Pumping Arrangements	required	Provided	MR			
	Ground Level						
	Discharge of main pump	2850 lpm	Provided	MID			
	Head of main pump	110 m		MR MR			
	Number of main pumps	2		MR			
	Jockey pump out put	180 lpm		MR			
	Jockey pump head	110 m		MR			
	5 C: II N						
	Standby Pump out put	2850 lpm	Provided	MR			
	Standby Pump out put Standby Pump Head Auto Staring/Manual	2850 lpm 110 m		MR MR			

	-						
	stopping						
	Pump House Access	Required	Provided	MR			
	 Terrace level 						
	Discharge of pump	Not Required	NR	NR			
	Head of the pump	Not Required	NR	NR			
	Power supply	Not Required	NR	NR			
	 Auto starting of pump 	Not Required	NR	NR			
14.	Captive water Storage for fire fighting						
	 Under ground tank 	2,00,000 litres	Provided	MR			
	capacity	Required	Provided	MR			
	Draw of connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	MR			
	Access to tank	20, 000 litres	Provided	MR			
	 Overhead Tank capacity 		0.000				
15	Exit Signage	Required	More Exit	MR			
			Signs				
			Provided				
16.	Provision of Lifts						
	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of lift lobby	Required	Provided	MR .			
	Communication in lift Car	Required	Provided	MR			
	Fireman's Grounding	Required	Provided	MR			
	Switch	Required	Provided	MR			
17	Lift Signage						
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area						
	Total area	Required	Provided	MR			
	Location	4 th , 6, 9 th ,	Provided	MR			
10	T'	Terrace Floor					
19.	Fire control room						
	Detector system panel	Required	Provided	MR			
	Flow Switch Panel	Required	Provided	MR			
	PA System Panel	Required	Provided	MR			
	Battery backup	Required	Provided	MR			
20	Building Floor Plans	Required	Provided	MR			
20.	Special Fire Protection Systems	CO2 flooding	Provided	MR			
	for Protection of special Risks, if	System for HT &		9			
	any;	LT panel					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/2010/3108 dated 109.11-2010 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

1969 Name

Name

Designation

DFA M

Imposo Designation