## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No. F6/DFS/ ans/ 2014/52/365

Dated: 31 03 14

## **FIRE SAFETY CERTIFICATE**

Certified that Fashion Trendz, S-40, Okhla Industrial Area, Phase II, New Delhi-110020, comprised of Basement, Ground + 03 Upper Floors. Factory is running in basement (storage) and ground floor only. The premises was inspected by the officers concerned of this department on 19/03/2014 in the presence of Mr. Sachvinder Singh (Owner) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class-Industrial Building (G-2) with effect from and the premises is fit for occupancy class-Industrial Building (G-2) with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010. This certificate is valid for basement & ground Floor only.

Issued 31/03/14—at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer

28/3/14

Copy to:-

Partner M/s Fashion Trendz, S-40, Okhla Industrial Area, Phase II, New Delhi-110020

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## **INSPECTION REPORT**

1. Name & address of the building: Fashion Trendz, S-40, Okhla Industrial Area,

Phase II, New Delhi-110020

2. Type of Occupancy

: Industrial,(G-2(b-ii), Moderate Hazard)

3. Type of Case

: New case

4. Details of previous NOC

: Nil

5. Fire Safety directives letter No : F-6/DFS/MS/BP/2013/2400 Dated 10.10.2013

6. Date of inspection

: 28/12/2013

7. Name of the Inspecting Officers: DO Dharampal bhardwaj & ADO D.B.Mukherjee

8. Name and designation of officers from the building side: Mr. Sachbir Singh

9. Year of Construction

10. Applicant's letter No. : Nil, Dtd.: 25/10/2013;

(Basement, Ground + Three Upper Floors)

S. No.	Minin	num Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR
1	Access 1	o building			
	• F	Road width	9 m	13 mtrs Provided	MR
	• (	Sate width	05 mtrs	05 mtrs Provided	MR
	• \	Vidth of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits				
¥	a. Numb	er of staircases		***	
	• [	Jpper Floors	02	02	MR
	• E	asements	02	02	MR
	b. Width	of staircases			9
	• U	Jpper Floors	1.25 mtrs	Provided	MR
	• B	asements	1.25 mtrs	Provided	MR
	c. Protec	tion of exits		1	
	• F	ire check door	Required	Provided	MR
	• P	ressurization	N/A	N/A	N/A
	e. No. of	continuous staircases to terrace	Required	Two	MR
	_	of Corridor	N/A	N/A	N/A
	h. Door S	Size	N/A	N/A	N/A



3	Compartmentation.					
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	Exhaust Fan	MR		
	Upper floors	12 a/c per hour	Exhaust Fan	MR		
5	Fire Extinguishers	*				
	Total numbers	e e	50	MR		
	• Types	ISI marked	ABC,Co2 & Foam	MR		
	IS marking		Provided Provided Provided Provided	MR		
5	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system. Not required but provided.					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
3	MOEFA	Not Required	Provided	MR		
)	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
1	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box					

12	Yard Hydrants.	(4 %)		al I		
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.	,	X.			
	Ground Level			<u> </u>		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level	1				
	Discharge of pump	900 LPM	Provided	MR		
	Head of the pump	40 mtr	Provided	MR		
	> Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10000 Ltrs.	Provided	MR		
5	Exit Signage.	Required	Provided	MR		
5	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
,	Fireman's Grounding Switch	N/A	N/A	N/A		
	• Lift Signage	N/A	N/A	N/A		
7	Standby power supply	Required	Provided 62.5 KVA DG Set	MR		

18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
- '	> Location	N/A	N/A	N/A
19	Fire Control Room		1	IVA
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for	N/A	One Co2 extinguisher	MR
	Protection of special Risks, if any:		provided for Electric	
			Panel board.	

The fire protection systems provided in the building were checked as per guidelines issued vide letter no. F-6/DFS/MS/BP/2013/2400 Dated 10.10.2013 and found that the building is comprised of basement, ground and three upper floors whereas the owner of the building has submitted sanctioned building plans for Basement and Ground floor only. The owner has submitted an affidavit and photographs that the upper floors are not in use and they are kept sealed.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010. Accordingly DFA is prepared for perusal and signature.

Submitted please.

Signature of the Inspecting Officer

Name: Dharampal Bhardwaj

Designation: - Div. Officer (South)

Signature of the Inspecting Officer

20/3/1

Name: D.B.Mukherjee

Designation: - Asstt. Div. Officer (BCP)