GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/EH/2014 | 52 | 426

L

Dated : 53/04/14

FIRE SAFETY CERTIFICATE

Certified that the Smokey's Bbq & Grill located at (Ground & Mezzanine Floor), Plot No.2, Local Shopping Complex, Masjid Moth, Greater Kailash-II, New Delhi-110048. comprised of Basement, Ground, Mezzanine + 7 Upper Floors but the restaurant is running on ground & mezzanine floor only was granted NOC in the of M/s Smoke House Grill by this department name No.F6/DFS/MS/EH/2011/3254 dated 29/11/11 The premises was re-inspected by the officer concerned of this department on 31/03/14 in the presence of Mr. Sudhir Singh and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Assembly Building Eating House Group D with effect from -- 3 1 04-1-14----- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire subject to conditions printed below.

Issued -03 /04/14-at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service Ph: - 011-23414333

90

- Copy to:- (1) The Dy. Health Officer, South Zone, Green Park, Municipal Corporation of Delhi, New Delhi.
 - (2) Smokey's Bbq & Grill, Plot No.2, Local Shopping Complex, Masjid Moth, Greater Kailash-II, New Delhi-110048.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:- Smokey's Bbq & Grill, Plot No.2,Local Shopping Complex,Masjid Moth,Greater Kailash-II,New Delhi-110048.
- 2. Type of occupancy:- Assembly Building Eating House Group D.
- 3 Type of case:- Renewal
- 4 Details of previous NOC:- F6/DFS/MS/EH/2011/3254 dated 29/11/11(old NOC issued in
- the name of Smoke House Grill)
 5 Fire safety directives No.- No
- 6. Date of inspection:- 31/03/14
- 7 Name of the inspecting officer:- A.D.O. S.S. Kaushik
- 8 Name & designation of officer
 - From the building side:- Mr. Sudhir Singh.
- 9 Year of construction:- Not known
- 10 Applicant's letter No:- DHO/SZ/2014/D/2333 dated 25/02/14 comprised of

Basement, Ground, Mezzanine + 7 Upper Floors but the restaurant is running on ground & mezzanine floor only

Old case

| | zanine floor only | T= . | D 11.1. | D 1 | | |
|-------|---|-----------------|----------------------|-------------------|--|--|
| S.No. | Minimum Standards on fire Prevention and fire safety U/R 33 | Requirement | Provided at site | Remarks MR/NMR | | |
| 1. | Access to Building | | | | | |
| | 1) Road width | 4.5 mtr. | Provided | MR | | |
| | 2) Gate width | N/A | N/A | N/A | | |
| | 3)Width of internal road | N/A | N/A | N/A | | |
| 2. | Number, Width Type & Arrange | | | | | |
| | A. Number of staircases | | | | | |
| | 1. Upper floors | 2 Nos. | 2 Nos. | MR | | |
| | 2. Basements | N/A | N/A | N/A | | |
| | B. Width of staircase | | | | | |
| | 1. Upper floors | 1.50 mtr. | 150 mtr. & 1.10 mtr. | MR old case | | |
| | 2. Basements | N/A | N/A | N/A | | |
| | C. Protection of exits | | | | | |
| | 1. Fire check door | N/A | N/A | N/A | | |
| | 2. Pressurization | N/A | N/A | N/A | | |
| | D. No. of continuous staircase | N/A | N/A | N/A | | |
| | to terrace | | 1 | | | |
| | E. Width of corridor | N/A | N/A | N/A | | |
| | F. Door size | Two exit | Provided | MR | | |
| 3. | Compartmentation | | | | | |
| | 1) Fire check door | N/A | N/A | N/A | | |
| | 2) Sealing of electrical shafts | N/A | N/A | N/A | | |
| | 3) Fire rating of shaft door | N/A | N/A | N/A | | |
| | 4) Water curtain | N/A | N/A | N/A | | |
| | 5) Fire Dampers | N/A | N/A | N/A | | |
| 4. | Smoke Management System | | | | | |
| | 1) Basements | 30 a/c per hour | N/A | N/A | | |
| | 2) Upper floors | 12 a/c per hour | Provided | MR | | |
| 5. | Fire Extinguishers | | | | | |
| | 1) Total numbers | | 06 Nos. | MR | | |
| | 2) Types | ISI Marked | Co2,W.Co2 & ABC | MR | | |
| | 3) ISI marking | | Yes | MR | | |
| 6. | First-Aid Hose Reel | э. | | 1.00 | | |
| | 1) Total number of each floor | One | One at each floor | MR | | |
| | 2) Length of hose reel hose | 30 m | Yes | MR | | |
| | 3) Nozzle diameter | 5 mm | Yes | MR | | |



| | 41711 — | | | | |
|------|---|--------------|-----------------------------|----------|--|
| 7. | Automatic Fire Detection & Alarmin | | | | |
| | 1) Type of detectors | N/A | N/A | N/A | |
| | 2) Location of main panel | N/A | N/A | N/A | |
| 9 | 3) Location of repeater panel | N/A | N/A | N/A | |
| | 4) Alternate source of power | N/A | N/A | N/A | |
| 0 | 5) Hooter's Location | N/A | N/A | N/A | |
| 9. | MOEFA | Required | Provided | MR | |
| | Public Address System | N/A | N/A | N/A | |
| 10. | Automatic Sprinkler System | 2 | | | |
| | 1) Basement | N/A | N/A | N/A | |
| | 2) Upper floors | Required | Provided in restaurant area | MR | |
| | 3) Sprinkler above false ceiling | N/A | N/A | N/A | |
| 11. | Internal Hydrants | IVA | IN/A | IN/A | |
| | 1) Size of riser/down-comer | 150 mm. | 150 mm. | MR | |
| | 2) Number of hydrants per floor | one | One | MR | |
| | 3) Hose box | one | Provided | MR | |
| 12. | Yard Hydrants | Ollo | TTOVIded | IAIK | |
| | 1) Total number of hydrants | N/A | N/A | N/A | |
| | 2) Hose box | N/A | N/A | N/A | |
| | | 14/21 | IVA | IN/A | |
| 13. | Pumping Arrangement | | | | |
| | 1) Ground level | | | | |
| | a) Discharge of main pump | 450 LPM | 450 LPM | MD | |
| | b) Head of main pump | 35 mtr. | | MR | |
| | c) Number of main pump | One | 35 mtr. | MR | |
| | d) Jockey pump out put | 180 LPM | One | MR | |
| | e) Jockey pump head | 35 mtr. | 180 LPM | MR | |
| | f) Stand by pump.output | N/A | 35 mtr. | MR | |
| | g) Stand by pump head | N/A | N/A | N/A | |
| | h) Auto starting/Manual stopping | | N/A | N/A | |
| | 2) Terrace level | N/A | N/A | N/A | |
| | a) Discharge of pump | N/A | N/A | N/A | |
| | b) Head of pump | N/A | N/A | N/A | |
| | c) Power supply | N/A | N/A | N/A | |
| | d) Auto starting of pump | N/A | N/A | N/A | |
| 14. | Captive Water Storage for Fire Fighti | N/A | N/A | N/A | |
| X 11 | 1) Under ground tank capacity | | 70.000 | | |
| 15. | a) Draw-off connection | 50,000 ltrs. | 50,000 Ltr. | MR | |
| | b) Fire service inlet | N/A | N/A | N/A | |
| | c) Access to tank | N/A | N/A | N/A | |
| | | N/A | N/A | N/A | |
| | d) Over head tank capacity Exit Signage. | 5,000 ltrs. | 5,000 Ltr. | MR | |
| 16. | Provision of Lifts. | Required | Provided | MR | |
| | | N/A | N/A | N/A | |
| | a) Pressurization of lift shaft | N/A | N/A | N/A | |
| | b) Pressurization of lift lobby | N/A | N/A | N/A | |
| | c) Communication in lift car | N/A | N/A | N/A | |
| | d) Fireman's switch | N/A | N/A | N/A | |
| | | 2 3 | | | |
| | e) Lift signage | N/A | N/A | N/A | |
| 17. | Stand by Power Supply | Required | Provided | MR | |
| 18. | Refuge Area | N/A | N/A | N/A | |
| | Total area location | N/A | N/A | N/A | |
| 19. | Fire Control Room | N/A | N/A | N/A | |
| | a) Detector system panel | N/A | N/A | N/A | |
| | | | - " - " | * 11 4 4 | |

| | C my di | - NI | 2 | |
|-----|--|------|-----|-----|
| | b) Flow switch panel | N/A | N/A | N/A |
| | c) PA system panel | N/A | N/A | N/A |
| Yes | d) Battery backup | N/A | N/A | N/A |
| | e) Building floor plan | | N/A | N/A |
| 20. | Special Fire Protection System for Protection of special Risk, if any: | | | N/A |

Earlier Fire Safety Certificate was issued vide this office letter No.F6/DFS/MS/EH/2011/3254 dated 29/11/11 in the name of Smoke House Grill

The fire protection system provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No.F6/DFS/MS/EH/2011/3254 dated 29/11/11 renewal under rule35 of the Delhi Fire Service rules 2010 is recommended.

Accordingly DFA is put up please

Signature of the inspecting officer

Signature of the inspecting officer

Name:-

Designation:-

Name: - S.S.Kaushik.

Maine. S.S.Rausink.

Designation:- Assistant Divisional Officer.

1/4/14