

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No.F.6/DFS/MS/School/2014/ 52/438

Dated: 03/04/14

FIRE SAFETY CERTIFICATE

Certified that the building of **Unique Montessori Public School** located at D-17, Durga Vihar, Ph-II, Deepnpur, Najafgarh, New Delhi-110043 is comprised of ground floor plus one upper floor but the school is running at ground floor only was issued NOC by this department vide letter No.F.6/DFS/MS/2010/3160 dated 12.11.2010 for ground floor plus one upper floor. The School building was re- inspected by the officer concerned of this department on 21.03.2014 in the presence of Sh. M.K. Bhardwaj (Owner) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" **(Ground floor only)** w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on.....03/04/14.....at New Delhi.



(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
Ph:- 011-23414333

O/c M/A

Copy to:-

1. The Principal,
Unique Montessori Public School,
D-17, Durga Vihar, Ph-II, Deepnpur,
Najafgarh, New Delhi-110043.
2. Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi – 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

NB

The school building is comprised of Ground Floor plus one upper floor but the school is running at Ground Floor only (as per the undertaking given by the owner).

INSPECTION REPORT

1. Name & address of the building: Unique Montessori Public School, Durga Vihar, Ph-7, Najafgarh, N.D-43. D-17
 2. Type of Occupancy: Educational (School)
 3. Type of Case: New Case/Renewal
 4. Details of Previous NOC: Letter No. F-6/DFS/MS/2010/3160 Dated 12.11.2010
 5. Fire Safety directives letter No: _____
 6. Date of inspection: 21.03.2014
 7. Name of Inspecting Officer: A.D.O Sandeep Nuggal
 8. Name and designation of officers
 From the building side: Sh. M.K. Bhardwaj (Owner)
 9. Year of Construction: 2004
 10. Applicant's letter No.: UMPS/2014/1 dated 27.02.2014

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Dir. Of Edu. Circular dt.	Provided at site	Remarks MR/NMR
1.	Access to building	01.03.2011		
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	<ul style="list-style-type: none"> Accessible - - 	<ul style="list-style-type: none"> 05 mtr 370 cms, 320, 210 cms - 	<ul style="list-style-type: none"> MR MR -
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> Upper Floors Basements 	<ul style="list-style-type: none"> - - 	<ul style="list-style-type: none"> Three - 	<ul style="list-style-type: none"> - No Basement
	b. Width of staircases			
	<ul style="list-style-type: none"> Upper Floor Basements 	<ul style="list-style-type: none"> - - 	<ul style="list-style-type: none"> 130, 120, 85 cms - 	<ul style="list-style-type: none"> - No Basement
	c. Protection of exits			
	<ul style="list-style-type: none"> Fire check door pressurization 	<ul style="list-style-type: none"> - - 	<ul style="list-style-type: none"> - - 	<ul style="list-style-type: none"> - -
	d. No. of continuous staircases to terrace			
	e. Width of Corridor			
	f. Door Size			
		01 mtr	01 mtr	Double door at G.F only MR
3.	Compartmentation			
	<ul style="list-style-type: none"> Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	<ul style="list-style-type: none"> - - - - - 	<ul style="list-style-type: none"> - - - - - 	<ul style="list-style-type: none"> - - - - -
4.	Smoke Management System			
	<ul style="list-style-type: none"> Basements Upper floors 	30 a/c per hour		
			-	No Basement
			Natural Ventilation	MR

Scanned

N/4

		12 a/c per hour		
5.	Fire Extinguishers			
	• Total numbers	07 Nos	Provided	MR
	• Types	ABC, CO ₂	- do -	MR
	• IS marking	ISI marked	ISI Marked	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor			
	• Length of hose reel hose	30 m		
	• Nozzle diameter	5 mm		
7.	Automatic fire detection and alarming system			
	• Type of detectors			
	• Location of Main Panel			
	• Location of Repeater Panel			
	• Alternate source of power			
	• Hooters' Location			
8.	MOEFA			
9.	Public Address System			
			Provided	
10.	Automatic Sprinkler System			
	• Basement			No Basement
	• Upper Floor			
	• Sprinkler above false ceiling			
11.	Internal Hydrants			
	• Size of riser/down-comer			
	• Number of hydrants per floor			
	• Hose Box			
12.	Yard Hydrants			
	• Total number of hydrants			
	• Hose Box			
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump			
	➤ Head of Main pump			
	➤ Number of main pumps			
	➤ Jockey Pump out put			
	➤ Jockey pump head			
	➤ Standby Pump out put			
	➤ Standby Pump Head			
	➤ Auto Starting/Manual stopping			

50

N/S

Unique Montessori Public School,
D-17, Durga Vihar, Ph-II, Deepapur,
Najaf Garh, New Delhi - 110043.

	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	-	-	-
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	-	-	-
15.	Exit Signage.	-	Provided	-
16.	Provision of Lifts:			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	-	-	No Lift
		-	-	- do -
		-	-	- do -
		-	-	- do -
		-	-	- do -
17.	Standby power supply	-	-	-
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	-	-	-
		-	-	-
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	-	-	-
		-	-	-
		-	-	-
		-	-	-
		-	-	-
20.	Special Fire Protection System for Protection of special Risks, if any:	-	-	-

SM

N/b

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2010/3160 dated 12.11.2010 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Note:- The school building is comprised of ground floor plus one upper floor, but the school is running at ground floor only as per the undertaking given by the owner placed on C-8. There are few class rooms with single door (or) having students less than 45 mention in above said undertaking placed on C-8. ~~Sandeep~~ 25/3/14. fsc is recommended for renewal please.

Signature of Inspecting Officer

Name Sandeep Duggal

Designation Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation