

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/Hospital/2014/ND2/476

Dated: 16/04/14

FIRE SAFETY CERTIFICATE

Certified that the Jeevan Anmol Hospital, Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi-91, comprised of one basement ground plus three upper floors was granted NOC by this department vide letter No. F6/DFS/MS/2008/2011/202 Dated 03.02.11. The Hospital was re-inspected by the officer concerned of this department on 20.03.14 in the presence of Dr. Neera Sondhi (Dy.M.S), and found that the hospital have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and found that the building is fit for occupancy class C -1 "Hospital (Institutional Building)" with effect from 16/04/14... renewed for a period of **three** years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, subject to conditions printed overleaf.

Issued on.....16/04/14.....at New Delhi by



(Dr. G.C. Misra)

Chief Fire Officer

Ph -011- 23414333

O/c
j/c

To,

Dr. Neera Sondhi (Dy.M.S),

Jeevan Anmol Hospital, Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi-91.

Copy to-

The Directorate of Health Services

M.O. I/C Nursing Home Cell,

Govt. of NCT of Delhi, F-17, Karkardooma, Delhi-32.

CONDITIONS:

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
7. Basement shall be used as per BBL.

N/7

INSPECTION REPORT

1. Name & address of the building : Jeevan Anmol Hospital, Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi
 2. Building is comprised of : B+G+3
 3. Type of Occupancy : Institutional Building
 4. Type of Case : Renewal
 5. Details of Previous NOC : F6/DFS/MS/2008/2011/202 Dated 03.02.11
 6. Fire Safety direction letter No : Delhi Fire Service Act, 2007 and Rules 2010.
 7. Date of Inspection : 20.03.14
 8. Name of the Inspecting Officers: : Suresh Singh (ADO)
 9. Name of the designation of Officer
 from the building side : Dr. Neera Sondhi (Dy.M.S)
 10. Year of Construction : 2000
 11. Applicant's letter No : Nil

S.No	Minimum Standards on fire prevention and fire safety U/R33	Requirement /NBC	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	9 m	13 m	MR
	Gate width	4.5 m	5 m	MR
	Width of internal road	N.A.	N.A.	N.A.
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	Upper Floor	2 no	2 no +01 ramp	MR
	Basement	2 no + 1 ramp	2 no + 1 ramp	MR
	B. Width of Staircases			
	Upper Floor	2 m	2 m each, (2.3m Ramp)	MR
	Basement	1.5 m	2 m each	MR
	c. Protection of exits			
	Fire check door	Required	Provided	MR
	Pressurization	N.A.	N.A.	N.A.
	e. No. of continuous staircases to terrace	2 no.	2 no.	MR
	g. Width of Corridor	2 m	2 m	MR
	h. Door Size	1 m	1m, 2m	MR
3	Compartmentation.			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	Fire rating of shaft door	N.A.	N.A.	N.A.
	Water curtain	N.A.	N.A.	N.A.
	Fire Dampers	N.A.	N.A.	N.A.
4	Smoke Management System.			
	Basement	Required	Provided	MR
	Upper floor	Required	Provided	MR

5.	Fire Extinguisher			
	Total numbers	20 no.	52 no.	MR
	types	Co2 & ABC	Co2 & ABC	MR
	IS marking	ISI marked	ISI marked	MR
6	First-aid-Hose Reels.			
	Total numbers of each floor	02 no.	02 no.	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	Smoke	Smoke	MR
	Location of main panel	Required	Provided in fire control	MR
	Location of repeater panel	Required	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooters's location	Required	Provided near staircase	MR
8	MOEFA	Required	Provided	MR
9	Public address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	basement	Required	Provided	MR
	upper floor	N.A.	N.A.	N.A.
	sprinkler above false ceiling	N.A.	N.A.	N.A.
11	Internal Hydrants			
	size of riser/down-comer	100 mm	100 mm	MR
	Number of hydrants per floor	2 no.	2 no.	MR
	Hose Box per floor	2 no.	2 no.	MR
12	Yard Hydrants.			
	Total number of hydrants	N.A.	03 no	MR
	Hose Box	N.A.	03 no.	MR
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> • Ground Level ➤ Discharge of main Pump ➤ Head of Main Pump ➤ Number of main pumps ➤ Jockey pump out put ➤ Jockey pump head ➤ Standby pump out put ➤ Standby pump Head ➤ Auto Starting /Manual stopping ➤ Pump House Access • Terrace Level ➤ Discharge of pump ➤ Head of the Pump ➤ Power supply ➤ Auto Starting of pump 			
		1680 LPM	1680 LPM	MR
		88 m	88 m	MR
		01 no.	01 no	MR
		180 LPM	180LPM	MR
		88 m	88 m	MR
		1680 LPM	1680 LPM	MR
		88 m	88 m	MR
		Required	Provided	MR
		Required	Provided	MR
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.
		N.A.	N.A.	N.A.

N/9

Jeevan Anmol Hospital, Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	1,00,000 Liters	1,15,000 Liters	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Yes	Provided	MR
	Overhead Tank capacity	20,000 Liters	40,000 Liters	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	N.A.	N.A.	N.A.
	Communication in lift car	Required	Provided	MR
	Firemen's grounding switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total area	N.A.	N.A.	N.A.
	Location	N.A.	N.A.	N.A.
19	Fire Control Room	Provided		
	Detector system panel	N.A.	N.A.	N.A.
	Flow switch panel	N.A.	N.A.	N.A.
	PA system panel	N.A.	N.A.	N.A.
	Batter backup	N.A.	N.A.	N.A.
	Building Floor Plans	N.A.	N.A.	N.A.
20	Special Fire Protection systems for protection of special Risks, if any:	N.A.	Provided Local Application	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules the NOC issued letter no. F6/DFS/MS/2008/2011/202 Dated 03.02.11 renewal under Rule 35 of the Delhi Fire Service Rules 2010 is recommended.


Signature of the Inspecting Officer

Name Suresh Singh

Designation ADO (Shah)