GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO.F.6/DFS/MS/School/WZ/ 2014 483

Dated: 16/04/2014

FIRE SAFETY CERTIFICATE

Certified that the S. D. Sarswati Bal Mandir, C-5, Rajeev Nagar. Phase-II, (Sector-22, Rohini), Delhi-110086 comprised of Ground + Two upper floor owned/occupied by S. D. Sarswati Bal Mandir have complied with the fire prevention and fire safety requirements in accordance with the Circular No F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education / NBC- Part IV and verified by the officer concerned of Fire Service on 30/03/2014 in the presence of Mrs. Veena Sharma (Principal) and that the building / premises is fit for occupancy of Group Class B (Educational) building with effect from 16 / 64 / 2014 for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of 2 the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- This certificate cannot be treated in any case for regularizations of unauthorized construction
- The owner / occupier shall submit a declaration every year in form "K" provided in the first Service Rules 2010. The form on of Delhi Fire WWW.dfs.Delhigovt.nic.in

Issued on 16/04/14 at New Delhi

(SANTOKH SINGH) Chief Fire Officer Delhi Fire Service Ph: 011-23414250

cfowz.dlfire@nic.in

Copy to:

The Principal, S. D. Sarswati Bal Mandir, C-5, Rajeev Nagar. Phase-II, (Sector-22, Rohini), 1. Delhi-110086

The Director of Education, Old Secretariat, Delhi-110054. 2.

INSPECTION REPORT

1. Name & address of the building

: S. D. Sarswati Bal Mandir, C-5, Rajeev Nagar. Phase-II,

(Sector-22, Rohini), Delhi-110086

2. Type of Occupancy

: Educational

(G + Two upper floor)

3. Type of Case

: New Case

4. Details of previous NOC

: Nil

5. Fire Safety directives letter No

: Direction of Education

6. Date of inspection

: 30/03/2014

7. Name of the Inspecting Officers

: DO (NW)

8. Name and designation of officers

from the building side

: Mrs. Veena Sharma (Principal)

9. Year of Construction

: 1994

10. Applicant's letter No.

: SD/2014 dated 26/02/2014

PA- 3050 Sq. mtr.

CA-1347.60 Sq. mtr

NOS-501

CR-38+1hall

		1105-301		CR-38+Inall	
	Minimum Standards on fire prevention and fire safety U/R 33	Dir. of Edu. Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
	 Road width 	Accessible	Accessible	M/R	
	• Gate width	Accessible	Accessible	M/R	
	 Width of internal road 				
2	Number, Width, Type & Arrangement	of Exits	4		
	a. Number of staircases				
	 Upper Floors 	02	02	M/R	
	 Basements 				
	b. Width of staircases				
	• Upper Floors	1.5 mtr	1) 1.50m 2)1.60m	M/R	
	 Basements 				
	c. Protection of exits				
	Fire check door				
	Pressurization				
6	e. No. of continuous staircases to terrace		7		
8	g. Width of Corridor				
ŀ	n. Door Size	01 mtr	01 mtr	M/R	

3	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	N/A	N/A		
	Upper floors	12 a/c per hour	N/A	N/A		
5	Fire Extinguishers					
	Total numbers	One @ 300 m each	15	M/R		
	• Types		ABC -15	M/R		
	IS marking	ISI marked	Yes	M/R		
6	First-Aid Hose Reels.					
	Total numbers on each floor	Two at each floor	02	M/R		
	 Length of hose reel hose 	30 m	P	M/R		
	Nozzle diameter	5 mm	P	M/R		
7	Automatic fire detection and alarming	z system.				
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Nam 1 and Location of Repeater Panel	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	200 42002000				
8 9	MOEFA Public Address System.	N/A R	N/A P	N/A M/R		
	· ·	K	1	171/10		
10	Automatic Sprinkler System.	77/4	27/4	27/4		
	Basement	N/A	N/A	N/A		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	R	P	M/R		
	Number of hydrants per floor	R	P	M/R		
	Hose Box	R	P	M/R		

ett.

12	Yard Hydrants.			and the second s		
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
V	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level					
	Discharge of pump	450 LPM	P	M/R		
	➤ Head of the pump	40 m	P	M/R	/	
	Power Supply	R	P	N/A M/R	_	
	Auto Starting of pump	R	P	M/R	1	
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10000 ltr	10000 ltr	M/R	-	
15	Exit Signage.	R	P	M/R		
16	Provision of Lifts.				2	
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
0.	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		

17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name

Name

Designation

Designation