### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. f6/065/MS/School/2014/MO2/525 Dated: 28/04/14

#### FIRE SAFETY CERTIFICATE

Certified that the Bhagwati Memorial Public School at main 33 Ft Road, ShivVihar Karawal Nagar Delhi -110094. owned/occupied by Bhagwati Memorial Public School, comprising of ground plus first floor was granted NOC vide letter No. F.6/MS/DFS/2006/258 dated 27/01/2006. The school building was inspected by the officer concerned of this department on 20/03/2014 in presence of Mr. Jogender, Manager of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular no 262-362 dated-17/01/2005 issued by the Director of Education and found that the school building is fit for occupancy class "B" 'Educational Building' with effect from 28.199/19. for a period of **three** years, subject to conditions printed overleaf.

Issued on 28/09/19 at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service Ph. 011-23414000

olc by

To.

The Manager, Bhagwati Memorial Public School, Main 33Ft Road Shiv Vihar, Karawal Nagar, Delhi -110094.

Copy:-

The Dy. Director of Education B–Block, Yamuna Vihar, Delhi-110053.

#### CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/nauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## IRH/3

1. Name & address of the building : Bhagwati Memorial Public School, Main 33 Ft. Road,

Shiv Vihar, Karawal Nagar, Delhi -110094

2. Building is comprised of Ground Plus First floor only

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous NOC letter : F-6/MS/DFS/2006/258 Dated-27/01/2006

6. Fire Safety direction letter No : Dir. Of Edu. Circular Letter No 262-362 Dated-17/01/05

7. Date of Inspection : 20/03/2014

8. Name of the Inspecting officers : ADO Vijay Bahadur

9. Name and designation of Officer:

from the building side : Mr. Jogender (Manager)

10. Year of Construction : 2004

11 Applicant's letter No : Letter No- Nil Dated 10/03/2014

S.NO	The second second	num Standards on fire ntion and fire safety U/R33	Circular Requirement	Provided at Site	Remarks MR/NMR			
1	Access to building							
		Road width	06 mtr.	09 mtr.	MR			
	•	Gate width	N/A	N/A	N/A			
		Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits							
	a. Nui	mber of Staircases						
		Upper Floor	01 Nos.	02 Nos.	MR			
	•	Basement	N/A	N/A.	N/A			
	B. Width of Staircases				and the second s			
		Upper Floor	1.50 mtr.	1.00 mtr each	MR			
		Basement	N/A	N/A	N/A			
		tection of exits	N/A	N/A	N/A			
	•	Fire check door Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to terrace	01 Nos.	01 Nos.	MR				
	e. Width of Corridor		1.50 mtr.	1.50 mtr.	MR			
	f. Door Size		1.00 Mtr.	1.00 mtr.	MR			
3	Compartmentation.							
	. 0	Fire check door	N/A	N/A	N/A			
		Sealing of electrical shafts	N/A	N/A	N/A			
		Fire rating of shaft door	N/A	N/A	N/A			
		Water curtain	N/A	N/A	N/A			
		Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.							
	•	Basement	N/A	N/A	N/A			
	•	Upper floor	N/A	N/A	N/A			
5.	Fire Extinguishers							
	9	Total numbers	06 nos.	06 nos.	MR			
	. •	types	ABC /CO <sub>2</sub>	ABC /CO <sub>2</sub>	MR			
		IS marking	ISI marked	ISI marked	MR			

6	First-aid-Hose Reels.						
	Total numbers on each floor	01 No.	01 No.	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 mtr.	30 mtr.	MR			
	Nozzle diameter	6.5 mm	6.5 mm	MR			
7	Automatic fire detection and alarming systematic			Ø			
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.		10				
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants	1					
11	size of riser/down-comer	N/A	N/A	N/A			
-	Number of hydrants per floor	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Hose Box	IVA	IWA	14/74			
12	Yard Hydrants.	N/A	N/A	N/A			
j.	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	IWA	14/74	14174			
13	Pumping Arrangements.						
	Ground Level	A LIZA	N/A	N/A			
	Discharge of main Pump	N/A		N/A			
	➤ Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	> Standby pump out put	N/A	N/A	N/A			
	> Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A N/A	N/A N/A	N/A			
	> Pump House Access	Required	Provided	MR			
	Terrace Level	220 Lpm.	220 Lpm.	MR			
	> Discharge of pump	40 M	40 M	MR			
	> Head of the Pump	Required	Provided	MR			
	> Power supply	Required	Provided	MR			
	> Auto Starting of pump	-	N/A	N/A			
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A			
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A N/A	N/A			
	> Access to tank	N/A	2500 Ltr.	MR			
	Overhead Tank capacity	2500 Ltr.	2500 Ltr. N/A	N/A			
15	Exit Signage.	N/A	IVA	19/7			
16	Provision of Lifts.	1 1/A	NA	N/A			
	Pressurization of Lift Shaft	N/A					
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication in lift car	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Thomas growniang officer	N/A	N/A	N/A			

# IRN/5

17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
*******************************	Total area	N/A	N/A	N/A		
	<ul> <li>Location</li> </ul>	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	/ N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping In view the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC issued vide letter No.F6/MS/DFS/2006/258 dated 20/11/2009 renewal under the circular letter No. 262-362 dated-17/01/05 is recommended.

Signature of the Inspecting Officer
Name Lijay Bahadu

Designation