## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2014/ 52 / 625

Dated: 21/5/14

## FIRE SAFETY CERTIFICATE

Certified that the Guest House Nand Kartar Orchid Suites located at 15A/18, WEA, Karol Bagh, New Delhi-110005 is comprised of Basement, Stilt, ground floor plus three upper floors, using basement as hall, Stilt for parking & reception, ground floor having 05 guest rooms, first floor having 07 guest rooms, second floor having 06 guest rooms, third floor having 03 guest rooms and one personnel room (Total 21 guest rooms), and a pantry for staff in temporary shed on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2011/354 dated 21.02.2011 for 22 guest rooms in the name of Saim Orchid Suites owned/occupied by Ms. Satvinder Khurana. The guest house building was re-inspected by the officers concerned of this department on 07.05.2014 in the presence of Sh. Ashok Kumar Rana (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.)

  1<sup>st</sup> floor, P.S., Defence Colony, New Delhi.

  (Re. No.15087-90/Addl. C.P./Lic.(H), Dated 27.03.2014)
- 2. Ms. Satvinder Khurana (Owner), Guest House Nand Kartar Orchid Suites, 15A/18, WEA, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

N/3

	INSPECT	TION REPORT		3			
	1. Name & address of the building:	Vanal Kartar	Coral II Com	:			
	1. Name & address of the building: Nand Kartar Orchid Swites, 15A/18, WEA Kas  2. Type of Occupancy  3. Type of Case  Residential (Guest House)  Back No.						
	3. Type of Case	DUCTAT MOUNE	Bagh, No				
	T. Details of Previous NOC .	Fire Safety directives letter No:  Date of inspection  Name of Inspecting Officer  Letter No. F.6   DFS   MS   GH   2011   354   Date 21.02.20    Date of inspecting Officer					
	5. Fire Safety directives letter No						
	6. Date of inspection						
	<ol><li>Name of Inspecting Officer :</li></ol>						
	8. Name and designation of officers	D 0 3 1 ( 10)	nur p H.D.O	P.S. Sahiya			
	From II I II II			<i>V</i>			
	9. Year of Construction	2010	Kumar Rana (	Manager)			
	10. Applicant's letter No.	5087-90/Addi	C.P./LIC. (H) d				
S.	Minimum Standards on fire	NBC/ BBL	Provided at	ated 27.03.2014			
No.	prevention and fire safety U/R 33	Requirement		Remarks			
I	Access to building	1. equilibril	2116	MR/NMR			
	<ul> <li>Road width</li> </ul>	Accessible	06mtr	1			
	Gate width			MR			
	Width of internal road		185 cm3	MR			
	Number, Width, Type & Arrangement	-fr. ',					
	a. Number of staircases	OT EXITS					
	• Upper Floors						
	• Basements		One	MR, Being Old Co			
	b. Width of staircases		One	- do			
	Upper Floor						
	Basements	-	130 cmp	MO Res MILO			
	c. Protection of exits		122 cms, 01 E. Ex	MR, Being Old Co			
	Fire check door		is well so viewed	17 - as -			
	• pressurization						
	d. Not of continuous staircases to terrace						
		<b></b>	One	of actions designed the control of t			
	e. Width of Corridor f. Door Size	700					
	1. 0001 3126		120cms to 190cms				
	Compartmentation		86cms x 218cms	:			
				The state of the s			
	Fire check door	-		And the state of t			
	Sealing of electrical shafts		Cont				
	Fire Rating of shaft door		Sealed				
	Water Curtain			•			
	• Fire Dampers						
	Smoke Management System						
	<ul> <li>Basements</li> </ul>	30 a/c per Exhaust Fons are					
	Upper floors	1	Brovioled	MR			
		hour	tural Ventilation	MR			

Programme and the second		14-	so a grade	-	
		12 a/c per hour			
B <sub>1</sub>		8	-		-5
5.	Fire Extinguishers				
	<ul> <li>Total numbers</li> </ul>	Two at each floor	Provided	MR	
	<ul><li>Types</li></ul>	ABC, WCo2	- da -	MR	
1	<ul><li>IS marking</li></ul>	ISI marked	151 Marked	MR	
6.	First-Aid Hose Reels		1	17/	
	<ul> <li>Total numbers on each floor</li> </ul>	One	Provided	MOR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	- do -	MR	
1	<ul> <li>Nozzle diameter</li> </ul>	5 mm	- do 4	MR	1
7.	Automatic fire detection and alarming	system		<u> </u>	
	Type of detectors				-
Ĭ	<ul> <li>Location of Main Panel</li> </ul>				
	<ul> <li>Location of Repeater Panel</li> </ul>			+ + + +	
	Alternate source of power		N.C. Cadadoonia	1 1	
	<ul> <li>Hooters' Location</li> </ul>		D.G. Set of 125 K	+	-
8.	MOEFA		Provided		-
9.	Public Address System	Parent		J?R	-
10.	Automätic Sprinkler System	Required	- do -	MR	-
-	Basement	NIR	Parital	D. 0	
	Upper Floor	14/	Provided	MR, Area less th	on Loo sq.
	<ul> <li>Sprinkler above false ceiling</li> </ul>	47		+	-
11.	Internal Hydrants				
	Size of riser/down-comer		·		
	<ul> <li>Number of hydrants per floor</li> </ul>				
	Hose Box			17 1	-
12.	Yard Hydrants				8
	• Total number of hydrants		J.		
	* Hose Box				-
13.	Pumping Arrangements				
,	Ground Level	-			-
	Discharge of main Pump				-
Se .	> Head of Main pump				-
	> Number of main pumps				
	> Jockey Pump out put	_			
	> Jockey pump head	-			
	<ul><li>Standby Pump out put</li></ul>	) Parameter			
	Standby Pump Head				
	> Auto Starting/Manual		6		
	stopping		i		
					-1

## N/S. ISA/18, WEA, Karol Bogh, New Delli-110005.

-				4			
2	Pump House Access						
	Terrace level						
	Discharge of pump	450 LPM	450 LPM Each	20100			
	Head of the pump	30 M		MR (021			
	Power Supply	Required	30M Each Provided	-do -			
	Auto Starting of pump	1,7-7	1 201146	1°17			
14.	Captive Water Storage for fire fighting		9				
	<ul> <li>Underground tank capacity</li> </ul>		_				
	Draw-off connection						
	Fire service inlet		Provided	100			
	Access to tank		rounded	MR			
	<ul> <li>Overhead Tank capacity</li> </ul>	5000 LAY	10000 ltr	MR			
		0000 4					
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.			ě			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> </ul>	-					
			Provided	MR			
	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>	Required	- do -	MR			
	Life Signage	-do-	-do-	MR			
17.	Standby power supply	Required -do- Required	Provided	MR			
18.	Refuge Area.						
	> Total Area		7, 2	,			
	> Location		-				
		-	<u> </u>				
19.	Fire Control Room						
	<ul><li>Detector System Panel</li><li>Flow Switch Panel</li></ul>	-					
	PA System Panel						
	<ul><li>Batter backup</li><li>Building Floor Plans</li></ul>	0	0				
		Required	Provided	MR			
				, k			
20.	Special Fire Protection System for						
	Protection of special Risks, if any:		-				

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/GH/2011/354 dated 21.02.2011 renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended.

Note: - The fire Safety Certificate issued viole letter No. F.6/DFS/MS/GH/2011/354 dated 21.02.2011 in the name of Siam Orchid Swites for 22 Rooms. The renewal is recommended in the name of Nand Kartar Orchid Swites for 21 Rooms as per reference recived from Addi. Commissioner of Police, Licensing Unit Vide letter No. 15087-90/Addi. C.P./Lic. (H) dated 27.03.2014.

Signature of Inspecting Officer

Name C.K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation AspH. Divisional Officer.