GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/2014/S2 /597

Dated: 12/5/14

FIRE SAFETY CERTIFICATE

Issued 1215)14 at New Delhi by.

(Dr. GC Misra) Chief Fire Officer Ph. 011-23414333

Copy to:- (1) The Joint Commissioner of Police, (Lic.), 1st Floor, PS Defence Colony, New Delhi.

ONT

(2) M/s S Pangaea-Lounge & Bar, Hotel The Ashoka,50-B,Chanakya Puri,New Delhi. Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

-N/2-

INSPECTION REPORT

- 1. Name & address of the building:- M/s S Pangaea-Lounge & Bar, Hotel The Ashoka, 50-B, Chanakya Puri, New Delhi.
- Type of occupancy:- Group -D Assembly Building.
- Type of case:- New
- 4. Details of previous NOC:- FSC to Ashoka Hotel already issued vide letter N0.F6/DFS/MS/2012/1851 dated 22/05/12
- 5. Fire safety directives No.- N.A.
- 6. Date of inspection: 21/04/14
- 7. Name of the inspecting officer:- A.D.O. S.S. Kaushik
- 8. Name & designation of officer
 - From the building side:- Mr. Hridesh Shah
- 9. Year of construction:- 1956 onwards.
- 10. Applicant's letter No:- 8540-46/Joint C.P./Lic. dated 19/02/14. Restaurant is running on upper ground floor level.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
1.	Access to Building		D 11-1	MR
	1) Road width	4.5 Mtrs.	Provided.	MR
	2) Gate width	5 mtr.	5 mtr.	
	3)Width of internal road	N/A.	N/A.	N/A
2.	Number, Width Type & Arrange	ement of Exits		
4.	A. Number of staircases			DI/A
	1. Upper floors	N/A.	N/A.	N/A
	2. Basements	N/A.	N/A.	N/A
	B. Width of staircase			DT/A
	1. Upper floors	N/A.	N/A	N/A
	2. Basements	N/A.	N/A	N/A
	C. Protection of exits			N/A
	1. Fire check door	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase	N/A	N/A	N/A
	to terrace		27/4	N/A
	E. Width of corridor	N/A	N/A.	MR
	F. Door size	2 mtrs.	Provided.	IVIK
3.	Compartmentation			DT/A
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		1 1 4	N/A
4.	1) Basements	N/A	N/A	
	2) Upper floors	Exhaust Fan	Provided	MR
5.	Fire Extinguishers		10.37	MR
-	1) Total numbers		10 Nos.	MR
	2) Types	ISI Marked	Co2,W.Co2 ABC,	IVIK
		151 Warked	Yes	MR
	3) ISI marking		103	Y

000

6.	First-Aid Hose Reel:	Provided & Maintai	ned by Hotel Mar	nagement		
	1) Total number of each floor	Required	2 Nos. provided near lounge & bar	MR		
	2) Length of hose reel hose	30 m	Yes	MR		
	3) Nozzle diameter	5 mm	Yes	MR		
7.	Automatic Fire Detection & Alarming System:- Provided & maintained by hotel management					
	1) Type of detectors	Smoke	Smoke	MR		
	2) Location of main panel	Required	Lower Ground floor	MR		
	3) Location of repeater panel	Required	Provided in lounge bar	MR		
	4) Alternate source of power	Required	Yes	MR		
0	5) Hooter's Location	Requiredo	Browded	MRC		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System	rinkler System Provided & Maintained by Hotel Management				
	1) Basement	do	do	do		
	2) Upper floors	do	do	do		
11.	3) Sprinkler above false ceiling Internal Hydrants	do	do	do		
			Provided & Maintained by Hotel Management			
	1) Size of riser/down-comer	do	do	do		
	2) Number of hydrants per floor	do	do	do		
	3) Hose box	do	do	do		
12.	Yard Hydrants		ntained by hotel n			
	1) Total number of hydrants	do	do	do		
	2) Hose box .	do	do	do		
13.	Pumping Arrangement	Provided & Maintained by Hotel Management				
	1) Ground level			,		
	a) Discharge of main pump	do	do	do		
	b) Head of main pump	do	do	do		
	c) Number of main pump	do	do	do		
	d) Jockey pump out put	do	do	do		
	e) Jockey pump head	do	do	do		
	f) Stand by pump bood	do	do	do		
	g) Stand by pump headh) Auto starting/Manual stopping	do	do	do		
	h) Auto starting/Manual stopping 2) Terrace level	do	do	do		
	a) Discharge of pump	da	1			
	b) Head of pump	do	do	do		
) Product pullip	do	do	do		

13. Pumping Arrangement Provided & Maintained by			ntained by Hotel	Mana	gement	
	1) Ground level			T	8	
	a) Discharge of main pump	do	do		-do	
	b) Head of main pump	do	do	-	-do	
	c) Number of main pump	do	do	-	-do	
	d) Jockey pump out put	do	do		-do	
	e) Jockey pump head	do	do	-	-do	
	f) Stand by pump output	do	do		-do	
	g) Stand by pump head	do	do	-	-do	
	h) Auto starting/Manual stopping	do	do		-do	
	2) Terrace level				40	
	a) Discharge of pump	do	do		-do	
	b) Head of pump	do	do	_	-do	
	c) Power supply	do	do		-do	
	d) Auto starting of pump	do	do		-do	
14.	Captive Water Storage for Fire Fighting Provided & Maintained by Hotel Management					
	 Under ground tank capacity 	do	do	_	-do	
	a) Draw-off connection	do	do	_	-do	
	b) Fire service inlet	do	do	-	-do	
	c) Access to tank	do	do		-do	
	d) Over head tank capacity	do	do		-do	
15.	Exit Signage.	Required	Provided	MR	40	

Mary

16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A

	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area			
	Total area location	N/A	N/A	N/A
19.	Fire Control Room			1.63
	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for	r Protection of speci	al Risk, if any:	MR

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010-----

Accordingly DFA is put up please

Signature of the inspecting officer

Signature of the inspecting officer

Name:-

Designation:-

Dosouth

Name: - S.S. Kaushik 24/2/14

Designation:- Assistant Divisional officer