


NO.F6/DFS/MS/EH/2014/SZ/ 614


DATED: 16/5/14

FIRE SAFETY CERTIFICATE

Certified that the M/s Terminus Restaurant at shop no. 238, Ambience Mall, Vasant Kunj, New Delhi is running at the second floor of a building comprised of three tier basement, ground plus three upper floors owned/occupied by M/s Terminus Restaurant. have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 08.05.2014 in the presence of Sh. Vikrant Batra (Owner), of the restaurant and that the building is fit for occupancy class D "Assembly building (Restaurant)" with effect from.....16/5/14.. for a period of **three** years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rule, 2010, as mentioned below.

Issued on16/5/14..... at New Delhi by


16/5
(Dr. G.C. Misra)
Chief Fire Officer
Delhi Fire Service

9c 
16/5/14

Copy To:-

1. The DHO (South Zone), Office of Deputy Health Officer, M.C.D. Public Health Department, Green Park, New Delhi.
2. Sh. Shard Batra (Owner), M/s Terminus Restaurant at shop no. 238, Ambience Mall, Vasant Kunj, New Delhi

Conditions for the validity of fire safety certificate

1. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
3. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye laws.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1	Name & address of the building	M/s Terminus Restaurant at shop no. 238, Second floor, Ambience Mall, Vasant Kunj, New Delhi		
2	Type of Occupancy	Assembly Building "D" Restauant		
3	Type of case	New		
4	Details of previous NOC	No		
5	Fire safety directives letter No	Nil		
6	Date of inspection	08.05.2014		
7	Name of the inspecting Officers :	D.O. (South) D.P. Bhardwaj ,		
8	Name and designation of officers from the building side	Sh. Vikrant (Owner),		
9	Year of construction			
10	Applicant's letter No.	DHO/S2/2014-D-180/24.4.14	(Resturant running at second floor shop no. 238)	
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR / NMR
1	Access to building			
	1) Road width	9 Mtr	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
2	Number, width Type & arrangement of exits			
	a. Number of staircases			
	1. Upper floors	2 Nos	Provided	MR
	2. basements	N/A	N/A	N/A
	b. Width of staircase			
	1. Upper floors	1.5 Mtr	Provided	MR
	2. basements	N/A	N/A	N/A
	c. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrac	N/A	N/A	N/A
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	2 Mtr	2.00 & 1.22 Mtrs Provided	MR
3	Compartmentation.			
	1. Fire check door	N/A	N/A	N/A
	2. Sealing of electrical shafts	N/A	N/A	N/A
	3. Fire Rating of shaft door	N/A	N/A	N/A
	4. water curtain	N/A	N/A	N/A
	5. Fire dampers	N/A	N/A	N/A
4	Smoke Management system.			
	basement	30 a/c per hour	N/A	N/A
		12 a/c per hour	Provided	MR
5	Fire Extinguishers			
	total numbers		7 Nos	MR
	Types		ABC, Water Co2	MR
	ISI marking	ISI	Yes	MR
6	First-Aid Hose Reels.		Provided & Maintain by Mall	
	total numbers on each floor	do	do	do
	Length of Hose reel hose	do	do	do

	Nozzle Diameter	do	do	do
7	Automatic fire detection and alarming system:-	Provided & Maintain by Mall		
	Type of detectors	do	do	do
	location of Main Panel	do	do	do
	location of Repeater panel	do	do	do
	Alternate source of power	do	do	do
	hooter's location	do	do	do
8	MOEFA	Provided & Maintain by Mall		
9	Public Address System.	Provided & Maintain by Mall		
10	Automatic Sprinkler System.	Provided & Maintain by Mall		
	basement	do	do	do
	upper floors	do	do	do
	sprinkler above false ceiling	do	do	do
11	Internal Hydrants	Provided & Maintain by Mall		
	Size of riser/down-corner	do	do	do
	Number of Hydrants per floor	do	do	do
	hose Box	do	do	do
12	Yard Hydrants.	Provided & Maintain by Mall		
	total number of hydrants	do	do	do
	hose box	do	do	do
13	Pumping arrangements	Provided & Maintain by Mall		
	1. Ground level			
	a. Discharge of main Pump	do	do	do
	b. Head of main pump	do	do	do
	c. Number of main pumps	do	do	do
	d. jockey pump out put	do	do	do
	e. jockey pump head	do	do	do
	f. Standby Pump output	do	do	do
	g. Stanby Pump head	do	do	do
	h. Auto Starting/Manual stopping	do	do	do
	pump house access	do	do	do
	2. Terrace level	do	do	do
	a. Discharge of pump	do	do	do
	b. head of the pump	do	do	do
	c. Power supply	do	do	do
	d. Auto starting of pump	do	do	do
14	Captive water storage for fire fighting	Provided & Maintain by Mall		
	1. Underground tank capacity	do	do	do
	a. Draw-off connection	do	do	do
	b. fire service inlet	do	do	do
	c. Access to tank	do	do	do
	Over head tank Capacity	do	do	do
15	Exit Signage.	do	do	do
16	Provision of lifts.	Provided & Maintain by Mall		
	a. Pressurization of lift shaft	do	do	do
	b. pressurization of lift lobby	do	do	do
	c. communication in lift car	do	do	do
	d. Fireman's grounding switch	do	do	do
	e. Lift signage	do	do	do
17	Standby power supply	Provided & Maintain by Mall		
18	Refuge Area.	Provided & Maintain by Mall		
	total area	do	do	do

	location	do	do	do
9	Fire control room	Provided & Maintain by Mall		
	a. detector system Panel	do	do	do
	b. Flow switch Panel	do	do	do
	c. PA system Panel	do	do	do
	d. Batter backup	do	do	do
	e. Building floor plans	do	do	do
20	Special Fire Protection systems for protection of special risks, if any: N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

This department has already issued fire safety certificate vide letter No. F6/DFS/MS/2013/SZ/1140 dated 30.10.2013 for mall.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule. The grant of Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for your approval and signature please.

Signature of the Inspecting Officer
Name D.P. BHARDWAJ
Designation:- D.O. (South)

