## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/2014/NDZ/63/

Dated: 22/5/19

## FIRE SAFETY CERTIFICATE

Certified that the Galleria Mall at plot no.01B, District Centre Mayur Vihar Ph-I, Delhi, owned/occupied by M/s Paliwal Developers Ltd., comprising of basement, ground vide Fire Safety Certificate issued floors was upper no.F6/DFS/MS/2011/642 dated 11.04.2011.The Mercantile building was inspected by the officers concerned of this department on 14.04.2014 in the presence of Sh.Ravinder Ahuja (Centre Manager) and found that the Mercantile building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group "Mercantile Building" with effect from for a period of three years, subject to conditions printed overleaf.

(Dr.G.C.Misra) Chief Fire Officer Ph.011-23414333

> Ola for

To,
M/s Paliwal Developers Ltd
Galleria Mall, plot no.01B,
District Centre Mayur Vihar Ph-I, Delhi -92,

## **CONDITIONS:**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. Basement shall be used as per BBL.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

1.Nar	me & address of the building: DLF Gall		lo.1B,District Cer	ntre,		
2 Bui	Mayur Vihar -1,Delhi.  ilding Comprised of Basement,ground plus two upper floors					
	pe of Occupancy : Mercal		о аррог посто			
	pe of Case : Renewa					
5. De		S/MS/2011/642 da	ated 11.04.2011			
	re Safety directives No : F.6/DFS			4.		
	ate of Inspection : 14.04.20					
8. N	lame of the Inspecting Officer : DO Vir	endra Singh & Al	OO Suresh Singh			
	ame of the designation of Officer					
		avinder Ahuja (Ce	entre Manager)			
	fear of Construction : 2008					
11.Ap		11.03.2014				
	Minimum Standards on fire	BBL/NBC	Provided at	Remarks		
1	prevention and fire safety U/R33	Requirement	Site	MR/NMR		
1	Access to building	10 Min	0.4 1.44	MAD		
	Road width	12 Mtrs	24 Mtrs.	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	6 Mtrs.	6 Mtrs.	MR		
2	Number, Width, Type and Arrangemer	IT OT EXITS				
	a. Number of Staircases	6 Noo	6 Noo	MD		
	<ul><li>Upper Floor</li><li>Basement</li></ul>	6 Nos.	6 Nos.	MR		
	Basement     B. Width of Staircases	9 NOS.	9 No.+1Ramp	MR		
		1.25 M	1.5 M	MR		
	<ul><li>Upper Floor</li><li>Basement</li></ul>	1.25 M	1.5 M& 1 no.	MR		
	Dasement	1.23 101	of 1.75 M	IVIT		
	c. Protection of exits		01 1.70 101			
	Fire check door	Required	Provided	MR		
	Pressurization	Required	Provided	MR		
	e. No. of continuous staircases to	2 nos.	2 nos.	MR		
	terrace	1.5 M	3.0 M	MR		
	g. Width of Corridor	1.0 Mtrs.	1.0 M	MR		
	h. Door Size	1.0 101015.	1.0 101	IVIIX		
3	Compartmentation.	_				
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Sealed	MR		
	Fire rating of shaft door	2 hrs.	2 hrs	MR		
	Water curtain	N/A	N/A	N/A		
	Fire Dampers	Required	Provided	MR		
4	Smoke Management System.					
	Basement	30 a/c per	30 a/c per	MR		
	Upper floor	hour	hour	MD		
		12 a/c per	12 a/c per	MR		
5.	Fire Extinguisher	hour	hour			
0.	Total numbers	70 Nos.	80 Nos.	MR		
	Total Hambors	Water type &	Water type &	MR		
	Types	Co2	Co2			
	IS marking	ISI marked	ISI marked	MR		
6.	First-aid-Hose Reels.					
	Total numbers of each floor	5 nos.	5 nos.	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	30 m	MR		
	Nozzle diameter					
-	A	5 mm	5 mm	MR		
7	The state of the s					
	Type of detectors	Heat or	smoke	MR		
	I continue of marin	smoke	Drawish L	MD		
	Location of main panel     Location of repositor panel	control room	Provided	MR		
	Location of repeater panel	Reception	Provided	MR		
	Allegrand	Battery & DG	Provided	MR		

)	Automatic Sprinkler System.	Required	provided	MR
	Basement		provided	MR
	• upper 11001	Required	provided	MR
	sprinkler above false	Required	provided	
	ceiling			
1	Internal Hydrants	450 mm	150 mm	MR
	size of wet riser	150 mm	5 nos.	MR
V.	<ul> <li>Number of hydrants per</li> </ul>	5 nos.	3 1103.	
	floor	5 nos.	5 nos.	MR
	Hose Box	5 1105.	011001	
2	Yard Hydrants.	06 Nos.	8 Nos.	MR
188 1	Total number of hydrants	06 Nos.	08 Nos.	MR
	Hose Box	00 1403.		
3	Pumping Arrangements.	Required	Provided	MR
	Ground Level     Fracin Rump	4500 LPM	4500 LPM	MR
	Discharge of main Pump	60 mtrs	60 mtrs	MR
	Head of Main Pump	2 nos.	2 nos.	MR
	Number of main pumps	450 LPM	450 LPM	MR
	> Jockey pump out put	60 mtrs.	60 mtrs.	MR
	> Jockey pump head	4500 LPM	4500 LPM	MR
	> Standby pump out put	60 Mtrs.	70 Mtrs.	MR
	> Standby pump Head	Required	Auto	MR
	> Auto Starting /Manual	1,090,00		
	stopping  > Pump House Access	Required	Provided	MR
		Required	Provided	MR
	Terrace Level	900 LPM	900 LPM	MR
	<ul><li>Discharge of pump</li><li>Head of the Pump</li></ul>	60 Mtrs.	60 Mtrs.	MR
		Required	Auto	MR
	Auto Starting of numn	Required	Provided	MR
· ·	Auto Starting or pump			
4.4	Captive Water Storage for Fire			
14				140
	<ul><li>Fighting.</li><li>Underground tank capacity</li></ul>	4,50,000 Ltrs	s 4,50,000 Ltrs	. MR
	> Draw-off connection	Required	Provided	IVIL
	Fire service inlet	Required	Provided	MR
-	> Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 Ltrs.	20,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
10	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby		Provided for	MR
	1,00041111411511 5, 114	1	basement	1.45
	Communication in lift car	Required	Provided	MR
	Firemen's grounding	Required	Provided	MR
	switch		2 4 Aug 12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
-	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
10	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			
19	Detector system panel	Required	Provided	MR
	-1 21 11	Required	Provided	MR
		Required	Provided	MR
			Provided	MR
	Battery backup	Required	N/A	N/A
10	<ul> <li>Building Floor Plans</li> </ul>	N/A	IN/A	TV//

NB

20	Special Fire Protection systems for protection of special Risks, if any:	N/A	Manually operated Co2 fire	MR
			extinguishers provided	

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire Safety measures as required under the rules. The fire safety certificate issued vide letter no. F.6/DFS/MS/2011/642 dated 11.04.2011, renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Stuget 14

Signature of the Inspecting Officer

Name:-Suresh Singh

Designation: - ADO (Shah)

Signature of the Inspecting Officer

Name:-Virendra Singh Designation: - DO (ED)