GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail: cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/School/2014/ 52/692

Dated: 06/06/14

FIRE SAFETY CERTIFICATE

Certified that the **Tagore School (Sr. Sec.)** located at 18, Mayapuri Marg, New Delhi-110064 having two blocks namely Block A & Block B (Administrative Block). Only Block A which is under consideration is comprised of ground floor plus three upper floors was issued NOC by this department vide letter No.F.6/MS/DFS/2006/1663 dated 19.07.2006. The School building was re-inspected by the officer concerned of this department on 30.05.2014 in the presence of Sh. Mohit Kumar Ahuja (Principal) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- The Principal, Tagore School (Sr. Sec.), 18, Mayapuri Marg, New Delhi-110064.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110 054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

Following fire safety directives must be adhered to:-

Ground plus three upper flora

(Block A)

INSPECTION REPORT 1. Name & address of the building: Tagene School, 18, Mayapuri Masg, Mayapuri, Educationa 3. Type of Case : New Case/Renewal 4. Details of Previous NOC Letter No. F6 MS/DFS/2006/1663 Date 19/07/2006 5. Fire Safety directives letter No 6. Date of inspection 30/5/2014 7. Name of Inspecting Officer ADO Sandeep Duggal 8. Name and designation of officers From the building side In Mohit Kumar Abrija (Principal) 9. Year of Construction 2001-2002 10. Applicant's letter No. TGRS/2013-14/26 dated 21/04/2014 S. Minimum Standards on fire NBC Provided at Remarks prevention and fire safety U/R 33 No. Requirement site MR/NMR 1. Access to building Road width Accessible 12 mm MR Gate width 450,600 4 580 cms MR Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases · ... Upper Floors 02NO" O2NOS MR Basements No Basement b. Width of staircases Upper Floor 168 cm 4 100 cm 1.5 mm Basements No Basement c. Protection of exits Fire check door pressurization Not of continuous staircases to OL Width of Corridor 170 cous f. Door Size MR (Students Conthair 1 mm 1 mhy (stringe 45 in each dan 3. Compartmentation Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers Smoke Management System 4. Basements 30 a/c per Upper floors No Baseman hour Natural Ventilation

	NIT	- Control	e e i i i i i i i i i i i i i i i i i i	
		12 a/c per		
		hour		
5.	Fire Extinguishers			
	• Total numbers		0 4 1	
	Types	ABC 4CO	Borided	MR
	 IS marking 	ISI marked	740	MR
6.	First-Aid Hose Reels		- 45	MC
	 Total numbers on each floor 	one	Proided	W 4 4
	 Length of hose reel hose 	30 m	-do	A of
	Nozzle diameter	5 mm	-10-	N. d
7.	Automatic fire detection and alarming	system		The contract of the contract o
	 Type of detectors 			
1	 Location of Main Panel 			
	 Location of Repeater Panel 			
	 Alternate source of power 		<u> </u>	
	 Hooters' Location 			
8.	MOEFA		Provided	
9.	Public Address System		Proided	
10.	Automatic Sprinkler System		1	
	 Basement 			
	 Upper Floor 	*		
	 Sprinkler above false ceiling 			
11.	Internal Hydrants			
	 Size of riser/down-comer 		100 mm	
	 Number of hydrants per floor 		one/flow	*
	Hose Box		one / floor	
12.	Yard Hydrants		J.	
	 Total number of hydrants 			
13.	* Hose Box			
13.	Pumping Arrangements • Ground Level			
	Discharge of main PumpHead of Main pump			
	Number of main pumps			
	> Jockey Pump out put			
	> Jockey pump head			
	Standby Pump out put			
	Standby Pump Head			
	Auto Starting/Manual			
	stopping			

N/8 Tagere School, 18, Mayapuri Marg, Mayapuri, N Dellii-11064, Mayapuri,

	Pump House Access			T to the state of
	Terrace level		and the same of th	
	Discharge of pumpHead of the pump	450 c/m	450 UM	ME
	Power Supply	1 Deep	aymm	MR (Being old case
	Auto Starting of pump		Commence of the Commence of th	
14.	Captive Water Storage for fire fighting		Acres and Acres	
	 Underground tank capacity 	-	25000 em	
	Draw-off connection		25000 4.4	
	Fire service inlet		2	
	Access to tank			
	Overhead Tank capacity		10000 dh	MR
15			A	MIC
15.	Exit Signage.	Required	Bonided	me
16.	Provision of Lifts.			200 /00
	Pressurization of Lift Shaft		· ·	No tyr
	 Pressurization of Lift lobby 		×	
	 Communication In lift Car 			
	* Fireman's Grounding Switch			
	Lift Signage			
17.	Standby power supply			
18.	Refuge Area.		***	
	> Total Area			
	> Location		•	200
		•		
19.	Fire Control Room		: 	
	Detector System Panel			
	Flow Switch Panel		<u> </u>	1
	PA System Panel			:
	Batter backup Building Element			
	Building Floor Plans	- Charles - Char		
20.	Special Fire Protection System for Protection of special Risks, if any:			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/MS/DFS/2006/1663 dated 19/07/2006 renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended.

Note: - The Echost building having two Blocks A and Block B CAdministrative). The Block A is under Consideration, as the undertaking given by principal states that Block B'sonstruction has been Stalled. The Block A is comprised of ground plus three upper floors Remed by two staircases having width 168 & locus. There are classes having single door with 01 min width. There are len than ut students in each class as per undertaking given by the principal placed at C-10. FSC is recommended for remedial please.

Signature of Inspecting Officer

Signature of Inspecting Officer

Name

Name

Sandeel Duggal

Asst. Divisional Officer. Designation

Designation

DO (SW)

Renewal F.S.C. for 6+3 floor netrool bldg is put up for Kind

approval and signature please.