GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI- 110001**

NO. F6/DFS/ms/school/2014/MD2/722 DATED: 13/06/14

FIRE SAFETY CERTIFICATE

Certified that the Hindon Public School at B-3/411, 33 Foota Road, Harsh Vihar, Delhi -110093, comprised of ground plus two upper floor owned/occupied by Hindon Public School was granted NOC vide letter no. No.F.6/DFS/MS/2009/3703 dated 04/12/2009 for ground plus first floor. The school building was inspected by the officer concerned of this department on 24/05/2014 in the presence of Mrs. Rajni Singh, Vice-Principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy class B "Educational Building" with effect from .1.2 for a period of three years, subject to conditions printed overleaf.

Issued on ...1.3. | O.6/1.4...... at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer Ph.011-23414333

To.

The Manager, Hindon Public School. B-3/411, 33 Foota Road, Harsh Vihar, Delhi -110093

Copy to:-

The Dy. Director of Education, North-East, B-Block, Yamuna Vihar, Delhi-110053.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

IRH/3

1. Name & address of the building : Hindon Public School, B-3/411,

33 Foota Road, Harsh Vihar, Delhi -110093.

2. Building is comprised of Ground plus two upper floor only.

3. Type of Occupancy : Educational

4. Type of Case New for ground plus two.

5. Details of Previous NOC letter : F6/DFS/MS/2009/3703 Dated-04/12/2009

(ground plus first only)

6. Fire Safety direction letter No : NBC. Part-IV

7. Date of Inspection : 24/05/2014

8. Name of the Inspecting officers : ADO Vijay Bahadur

9. Name and designation of Officer:

from the building side : Mrs. Rajni Singh (Vice-Principal)

10. Year of Construction : (G+1)-2005 & (IInd Floor)-2010

11. Applicant's letter No : Letter No.- Nil Dated-28/04/2014

S.NO	Minimum Standards on fire	NBC Part-IV	Provided at Site	Remarks			
	prevention and fire safety U/R33	Requirement		MR/NMF			
1	Access to building	00	OC mate	MR			
	 Road width 	06 mtr.	06 mtr.				
	Gate width	N/A	N/A	N/A			
	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
ď	a. Number of Staircases		2011	2.6			
	Upper Floor	01 Nos.	03 Nos.	MR			
	 Basement 	N/A	N/A.	N/A			
	B. Width of Staircases	4.50	1.36 mtr. 1.38	MR			
	Upper Floor	1.50 mtr.	mtr. & 1.52 Mtr.	IVIT			
	Basement Brataction of outs	N/A	N/A	N/A			
	c. Protection of exits • Fire check door	N/A	N/A	N/A			
	Pressurization						
	d. No. of continuous staircases to	N/A	N/A	N/A			
	terrace	01 Nos.	01 Nos.	MR			
	e. Width of Corridor	1.50 mtr.	3.00 mtr.	MR			
	5 Deer Size	01 mtr.	01 mtr.	MR			
3	f. Door Size Compartmentation.						
<u> </u>	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	• Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.						
-	Basement	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A	N/A			
5.	Fire Extinguishers						
	Total numbers	11 nos.	12 nos.	MR			
	• types	ABC /CO₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			

6	First-aid-Hose Reels.						
	Total numbers on each floor	01 No.	01 No.	MR			
	 Length of hose reel hose 	30 mtr.	30 mtr.	MR			
	 Nozzle diameter 	05 mm	05 mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.	1 27, 1		1			
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
4	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace Level	Required	Provided	MR			
	Discharge of pump	450 Lpm.	450 Lpm.	MR			
	Head of the Pump	40 M	40 M	MR			
	➢ Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A			
Marie C. Societa and Historia princing	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	> Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
01	Overhead Tank capacity	10,000 Ltr.	10,000 Ltr.	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	1 1000011111111111111111111111111111111	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Firemen's grounding switchLift Signage	N/A	N/A	N/A			

TKH

IRN/5

17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.		1 23 / 3	14773		
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	 Detector system panel 	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	 PA system panel 	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	 Building Floor Plans 	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. Earlier NOC was issued for ground plus first floor only. Now the building is comprised of ground plus two upper floors.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Office

Name – Vijay Bahadur Designation – A.D.O

٨