GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, Tel:- 011-23414333

NO.F6/ DFS/ MS/School/2014/ 57/70/

Dated: 09/06/14

FIRE SAFETY CERTIFICATE

Certified that, **Kids Home International School**, Located at B-999, Phase-IV, Bandh Road, Aya Nagar, New Delhi-110047, running in ground and first floor of a building comprised of Ground + 02 Upper floors, having total 12 rooms, (10 class room, 01 office, 01 Computer room) owned/occupied by Kids Home International School Management. The premises was inspected by the officer concerned of this department on 23/05/2014 in the presence of Mr. Dilbagh Singh (Manager) and found that the School have complied with the fire prevention and fire safety requirements in accordance with the Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational (School)" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the below mentioned conditions.

(Dr. G.C. Misra) Chief Fire Officer

of c hope (14)

Copy to: -

Mr. Dilbagh Singh, Manager, Kids Home International School, B-999,Phase-IV,Bandh Road,Aya Nagar, New Delhi-110047

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building :Kids Home International School, B-999, Phase-IV,

Bandh Road, Aya Nagar, New Delhi-110047

2. Type of Occupancy

: Educational (School)

3. Type of Case

: New

4. Details of previous NOC

: Nil

5. Fire Safety directives letter No: F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011.

6. Date of inspection

: 23/05/2014

7. Name of the Inspecting Officers : ADO D.B.Mukherjee

8. Name and designation of officers

from the building side

: Mr. Dilbagh Singh

9. Year of Construction

:2010

10. Applicant's letter No.

: Kh/125/2014-2015 dated: 08/05/2014,

S. No.	Building is comprised of Ground + 2 up Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remark
-1	Access to building	quir ement		MR/NMF
	Road width	Required	Provided	
	Gate width	Required	approachable from road	MR
	 Width of internal road 	N/A	N/A	MR N/A
2	Number, Width, Type & Arrangeme	ent of Exits		IN/A
a. Nu	mber of staircases			
	Upper Floors	02	02	1.00
•	Basements	N/A	N/A	MR
b. Wie	lth of staircases		IVA	N/A
•	Upper Floors	Required	1m & 1.42m	MR
•	Basements	N/A	N/A	
c. Prot	ection of exits		1.11.1	N/A
•	Fire check door	N/A	N/A	N T/A
•	Pressurization	N/A	N/A	N/A
e. No.	of continuous staircases to terrace	01	01	N/A
g. Widt	h of Corridor	N/A	N/A	MR N/A
. Door	·Size	1m	Provided	MR

3	Compartmentation.		9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		
	Fire check door	N/A	N/A	X	
	Sealing of electrical shafts	N/A		N/A	
	 Fire Rating of shaft door 	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.	IVA	N/A	N/A	
	Basements 30 g/g = 1		¥		
	Upper floors	30 a/c per hour 12 a/c per hour	N/A	N/A	
5	Fire Extinguishers	12 we per nour	N/A	N/A	
	 Total numbers 	Required			
	• Types	ABC,Co ₂	06 nos	MR	
	IS marking	Required	Provided	MR	
5	First-Aid Hose Reels.	Required	Provided	MR	
	 Total numbers on each floor 	N/A	27/		
	 Length of hose reel hose 	N/A	N/A	N/A	
	Nozzle diameter	N/A	N/A	N/A	
	Automatic fire detection and alarming system				
	• Type of detactors				
	• Location of Main Panel		N/A	N/A	
		N/A	N/A	N/A	
	• Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power Hooters' Location	N/A	N/A	N/A	
-	Trooters Education	N/A	N/A	N/A	
	MOEFA	N/A	N/A		
	Public Address System.	N/A	N/A	N/A	
F	Automatic Sprinkler System				
	Basement	N/A	N/A	N/A	
	• Upper Floor	N/A	N/A		
-	Sprinkler above false ceiling	N/A	N/A	N/A	
11	internal Hydrants			N/A	
	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floorHose Box	N/A	N/A	N/A	
		N/A		11//1	

1	 Total number of hydrants 	of hydrants N/A N/A				
	Hose Box	ALC: 1	N/A	N/A		
1	3 Pumping Arrangements	N/A	N/A	N/A		
	Ground Level					
	Discharge of main Pump	N/A	NI/A			
1	Head of Main pump	N/A	N/A	N/A		
	 Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put 	N/A	N/A	N/A		
			N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	Discharge of pump					
	> Head of the pump	N/A	N/A	N/A		
	> Power Supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A N/A	N/A	N/A		
4	Captive Water Storage for fire fighting	IN/A	N/A	N/A		
	Underground tank capacity	N/A				
	> Draw-off connection		N/A	N/A		
	Fire service inletAccess to tank	N/A N/A	N/A	N/A		
			N/A	N/A		
	Overhead Tank capacity	N/A	N/A	N/A		
	Exit Signage.	N/A	N/A	N/A		
-	Provision of Lifts.	Required	Provided	MR		
	The state of the s					
	Tressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A			
	Fireman's Grounding SwitchLift Signage	N/A		N/A		
			N/A	N/A		
0	tandhy	N/A	N/A	N/A		
10	Standby power supply	N/A	N/A	N/A		

18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	One Co ₂ extinguisher near electric panel board		

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcomings issued vide letter no.F6/MS/DFS/School/2014/891 dated: 16/04/2014 have been rectified.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules as per the directives of Education Department vide Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011 it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

DO (South)

Name (D.B.Mukherjee)

try 26/5/14

Designation :- Assistant Divisional Officer

20/ 20/ +CON-