GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No.F.6/DFS/MS/School/2014/ 52 / 780

Dated: 24/06/14

FIRE SAFETY CERTIFICATE

Certified that the building of **New Diamond Public School** located at G-83, Vishwas Park, Matiala Road, Uttam Nagar, New Delhi-110059 is comprised of ground floor only was issued NOC by this department vide letter No.F.6/DFS/MS/2006/1957 dated 04.08.2006. The School building was re- inspected by the officer concerned of this department on 16.06.2014 in the presence of Sh. Vishnu Sharma (Manager) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on 24/06/14 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- The Manager, New Diamond Public School, G-83, Vishwas Park, Matiala Road, Uttam Nagar, New Delhi-110059.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ground Floor only

N2.

| | INSPECT | TION REPORT | | | | | | |
|-----|---|--|-----------------------------|--|--|--|--|--|
| | 1. Name & address of the building: | May Nieven | Pulle Cally | C 00 1/11 0 | | | | |
| | 2. Type of Occupancy | 19: New Diamond Public School, G-83, Vishwas Par Educational (School) Matiala Rd. Utton No. | | | | | | |
| | 0 7 | : New Case/Renewal Matiala Rd, UHamin | | | | | | |
| | | | 07 0-1-101 | | | | | |
| | 5. Fire Safety directives letter No: | . Letter NO. F. 6 | '7 Dated 04.08.20 | | | | | |
| | 6. Date of inspection | 16.06.2014 - A.D.O P.S. Dahiya | | | | | | |
| | 7. Name of Inspecting Officer | | | | | | | |
| | 8 Name and designation of affice | | | | | | | |
| | 8. Name and designation of officers From the building side : Sh. Vishny (harma (Manager)) | | | | | | | |
| | 9. Year of Construction | Sh. Vishy | Sh. Vishnu Sharma (Manager) | | | | | |
| | | Nil dated 05.06.2014 | | | | | | |
| C | 10. Applicant's letter No. | | | | | | | |
| S. | Minimum Standards on fire prevention | Dir. Of Edu. | Provided at site | Remarks | | | | |
| No. | and fire safety U/R 33 | Circular dt. | | MR/NMR | | | | |
| 4 | | 01.03.2011 | | | | | | |
| 1. | Access to building | 8. | | | | | | |
| | Road width | Accessible | 06 mtr | MR | | | | |
| | Gate width | ← | 270 cms | MR | | | | |
| | Width of internal road | _ | • | | | | | |
| 2. | Number, Width, Type & Arrangement of Exits | | | | | | | |
| | a. Number of staircases | | | | | | | |
| | Upper Floors | | | C 1 C1 | | | | |
| | Basements | | | Ground Floor only | | | | |
| | | | Name | No Basement | | | | |
| | b. Width of staircases | | | 5 | | | | |
| | Upper Floor | | | Ground Floor cont | | | | |
| | Basements | - | No. | No Basement | | | | |
| | c. Protection of exits | | | NO DUSCINENC | | | | |
| | Fire check door | The state of the s | 2 | | | | | |
| | pressurization | | | | | | | |
| | | - | | Čana. | | | | |
| | d. No. of continuous staircases to | | | | | | | |
| | terrace | | | | | | | |
| | e. Width of Corridor f. Door Size | | | Ground Floor only | | | | |
| | | | | | | | | |
| | | _ | 98 cms +190 cms | | | | | |
| | Compartmentation | - | | | | | | |
| | Fire check door | 2 | 3 | | | | | |
| | Sealing of electrical shafts | | | | | | | |
| | Fire Rating of shaft door Water Curtain | _ | 8 | ~ | | | | |
| | | | | | | | | |
| | Fire Dampers | | | | | | | |
| | The Dampers | | | | | | | |
| 1. | Smoke Management System | | | The second secon | | | | |
| | | 20 7 1 | T | | | | | |
| | Basements | 30 a/c per hour | | 1 10 October 1 | | | | |
| | | | | No Basement | | | | |
| | · Upper floors Ground Floor | | | | | | | |
| | | | | The state of the same of the s | | | | |



| т | | N14, | 4.4 | |
|------------------------------|---|--|------------|------------|
| | - | 12 a/c per | | |
| | • | hour | * 1 | _ |
| | | | | |
| | Fire Extinguishers | | | |
| | Total numbers | 04 Nos | Provided | MR |
| | Types | Co, , ABC, WG, | - do - | MR |
| | IS marking | ISI marked | 151 Marked | MR |
| | First-Aid Hose Reels | | 3 2 | |
| | Total numbers on each floor | | | |
| | Length of hose reel hose | 30 m | | |
| | Nozzle diameter | 5 mm | | |
| | Automatic fire detection and alarming | | | |
| ner i Philippine (in cumanos | Type of detectors | | | |
| ì | Location of Main Panel | | | |
| | Location of Repeater Panel | _ | | |
| | Alternate source of power | | | |
| | Hooters' Location | | | |
| 8. | MOEFA | | | |
| 9. | Public Address System | - | Provided | |
| 10. | Automätic Sprinkler System | | 7 30 1010 | |
| FE-MORPH & BOOK VALUE | • Basement | | | No Bosemen |
| | Upper Floor | 4 | | |
| | Sprinkler above false ceiling | | | |
| 11. | Internal Hydrants | | | |
| manifestation and the second | Size of riser/down-comer | | | |
| | Number of hydrants per floor | | | - |
| | Hose Box | | | |
| 12. | Yard Hydrants | Control of the Contro | J . | |
| alla desar e | • Total number of hydrants | | | |
| | Hose Box | | | |
| 13. | Pumping Arrangements | | # | |
| | Ground Level | | | 2 |
| | Discharge of main Pump | | | |
| 104 | > Head of Main pump | | | |
| | > Number of main pumps | | | |
| | > Jockey Pump out put | | | |
| | > Jockey pump head | | - | - |
| , | > Standby Pump out put | | | |
| | Standby Pump Head | | | - |
| | Auto Starting/Manual | | i. | |
| | stopping | | | |
| | | | | |

(10)

G-83 Vishwas Park, Matiala Road, N/5. Uttam Nagar, New Delli-110059.

| | Pump House Access | | | _ |
|-----|---|-----|----------|---------|
| | Terrace level | | | ı, k |
| | Discharge of pump | | | |
| | Head of the pump | | | |
| | Power Supply | | | |
| | Auto Starting of pump | | | |
| 14. | Captive Water Storage for fire fighting | | · | |
| | Underground tank capacity | | | |
| | Draw-off connection | | | |
| | Fire service inlet | | | |
| | > Access to tank | | | |
| | Overhead Tank capacity | | | |
| | | - | | |
| 15. | Exit Signage. | | Provided | |
| 16. | Provision of Lifts. | | | |
| | Pressurization of Lift Shaft | | | No Lift |
| | Pressurization of Lift lobby | | | -do - |
| | Communication In lift Car | | | -do- |
| | Fireman's Grounding Switch | | | -do- |
| | Lift Signage | | - | |
| | | | - | -do- |
| 17. | Standby power supply | | | - 1 |
| 18. | Refuge Area. | | | |
| | > Total Area | 144 | | |
| | ➤ Location | | 8 2 2 V | |
| | | | | |
| 19. | Fire Control Room | | | 9 S B |
| il. | Detector System Panel | | | |
| | Flow Switch Panel | | 9 | |
| | PA System Panel | | | |
| | Batter backup | | 0 | |
| | Building Floor Plans | - | Provided | _ |
| | | | | |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | | | |
| | | | 1 | |



The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6 | D.F.S | M.S | 2006 | 1957 dated 04.08.2006 renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name P.S. Dahiya

Designation ABBH. Divisional Officer.

Signature of Inspecting Officer

Name

Designation

Cho (yas) F.T. letter in put up. for signature bl. Malya