## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. 66/065/015/2014/1102/806

Dated: 30/06/19

## FIRE SAFETY CERTIFICATE

Certified that the Star City Mall at plot no.01A, District Centre Mayur Vihar Ph-I, Delhi, owned/occupied by M/s Mahatta Tower Pvt. Ltd., comprising of basement, ground plus two upper floors was issued NOC vide letter no.F6/DFS/MS/2007/1287 dated 08.05.2007. The Mercantile building was inspected by the officers concerned of this department on 21.06.2014 in the presence of Sh. Anand Tyagi (Manager) and found that the Mercantile building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group "Mercantile Building" with effect from ... 2.0./ ... 6. ... 1.7... for a period of three years, subject to conditions printed overleaf.

Issued on ... \$ . . . . . . . . . . . . at New Delhi by

(Dr.G.C.Misra)

Chief Fire Officer

To,

The Director
M/s Mahatta Tower Pvt. Ltd
Star City Mall, plot no.01A,
District Centre Mayur Vihar Ph-I, Delhi -92,

Ph.011-23414333

## **CONDITIONS:**

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures,

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.

5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. Basement shall be used as per BBL.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six six months prior to its expiry"

1.Name & address of the building: Star City Mall at Plot No.1A, District Centre, Mayur Vihar -1, Delhi. : Basement, ground plus two upper floors 2. Building Comprised of 3. Type of Occupancy : Mercantile Renewal 4. Type of Case F.6/DFS/MS/2007/1287 dated 08.05.2007 5. Details of Previous NOC : F.6/DFS/MS/BP/2004/1969 Dated: 30.08.2004. 6. Fire Safety directives No. 7. Date of Inspection : 16.06.2014 8. Name of the Inspecting Officer : DO Virendra Singh & ADO Suresh Singh 9. Name of the designation of Officer Sh.Anand Tyagi(Manager) From the building side 10. Year of Construction dated 15.05.2014 11.Applicant's letter No Provided at Site Remarks BBL/NBC Minimum Standards on fire MR/NMR Requirement prevention and fire safety U/R33 Access to building 1 MR 13 Mtrs. 12 Mtrs Road width MR 6 Mtrs. 4.5 Mtrs. Gate width MR 6 Mtrs. 6 Mtrs. Width of internal road Number, Width, Type and Arrangement of Exits 2 a. Number of Staircases MR 5 Nos. 5 Nos. Upper Floor MR 9 No.+1Ramp 9 Nos. Basement B. Width of Staircases MR/as 1 no. of 1.35 m, 1.25 M Upper Floor accept 3 nos. of 1.25 m earlier &1 no.of .90 to 1.10 m 1.20 to 1.35 m MR 1.25 M Basement c. Protection of exits Fire check door MR Required Provided Pressurization MR Provided Required e. No. of continuous staircases to MR 5 nos. 3 nos. terrace MR 2.5 M 2.5 M g. Width of Corridor MR 1.0 Mtrs. 1.2 M h. Door Size Compartmentation. Provided MR Required Fire check door MR Required Sealed Sealing of electrical shafts MR 2 hrs 2 hrs. Fire rating of shaft door N/A N/A N/A Water curtain MR Provided Required Fire Dampers Smoke Management System. 4 MR 30 a/c per hour 30 a/c per **Basement** hour MR 12 a/c per 12 a/c per hour Upper floor hour 5. Fire Extinguisher MR 60 Nos. 45 Nos. Total numbers MR Water type & Water type & Co<sub>2</sub> Types ISI marked MR ISI marked IS marking First-aid-Hose Reels. MR 5 nos. 5 nos. Total numbers of each floor MR 30 m 30 m Length of hose reel hose Nozzle diameter MR 5 mm 5 mm Automatic fire detection and alarming system. 7 MR Heat & smoke Heat or smoke Type of detectors MR control room basement Location of main panel MR Provided Location of repeater panel Reception Provided MR Required Alternate source of power supply Provided MR Strategic

0	MOEFA	Required		MR
9	Public address System.	Required	provided	MR
10	Automatic Sprinkler System.			
	Basement	Required	provided	MR
	upper floor	Required	provided	MR
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	size of wet riser	150 mm	150 mm	MR
	Number of hydrants per floor	5 nos.	5 nos.	MR
	Hose Box	5 nos.	5 nos.	MR
12	Yard Hydrants.			
	<ul> <li>Total number of hydrants</li> </ul>	06 Nos.	8 Nos.	MR
	Hose Box	06 Nos.	08 Nos.	MR
13	Pumping Arrangements.	s		
	Ground Level	N/A	N/A	N/A
	Discharge of main Pump	4500 LPM	4500 LPM	MR
" "	Head of Main Pump	50 mtrs	50 mtrs	MR
	Number of main pumps	2 nos.	2 nos.	MR
	Jockey pump out put	450 LPM		MR
7	Jockey pump head	50 mtrs.	50 mtrs.	MR
	Standby pump out put	4500 LPM		MR
	Standby pump Head	50 Mtrs.		MR
•	<ul><li>Auto Starting /Manual stopping</li></ul>	Required		MR
	Pump House Access	Required		MR
	Terrace Level	All above		terrace
	Discharge of pump	N/A		N/A
	Head of the Pump	N/A		N/A
	Power supply	N/A		N/A
	Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting.			
	<ul> <li>Underground tank capacity</li> </ul>	2,00,000 Ltrs		MR
	Draw-off connection	Required		MR
	Fire service inlet	Required		MR
	Access to tank	Required		MR
	<ul> <li>Overhead Tank capacity</li> </ul>	25,000 Ltrs.		MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		provided N/A  150 mm 5 nos.  5 nos.  8 Nos. 08 Nos.  N/A 4500 LPM 50 mtrs 2 nos. 450 LPM 50 mtrs. 4500 LPM 50 mtrs. Auto  Provided pumps on N/A N/A N/A N/A N/A  Trs 2,00,000 Ltrs. Provided	MAD
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	Required		MR
	Pressurization of Lift lobby	Required	basement	MR
	Communication in lift car	Required		MR
	<ul> <li>Firemen's grounding switch</li> </ul>	Required		MR
	Lift Signage	Required		MR
17	Standby power supply	Required	1500 KVA	MR
18	Refuge Area.			N1/A
	Total area	N/A		N/A
,	<ul> <li>Location</li> </ul>	N/A	N/A	N/A
19	Fire Control Room			
	Detector system panel	Required		MR
	<ul> <li>Flow switch panel</li> </ul>	Required		MR
	PA system panel	Required	Provided	MR
	Battery backup	Required	Provided	MR

N/10

Special Fire Protection systems for protection of special Risks, if any:	N/A	Provided IN LT & HT panels	MR
--	-----	----------------------------------	----

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire Safety measures as required under the rules. The fire safety certificate issued vide letter no. F.6/DFS/MS/2007/1287 dated 08.05.2007, renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

23.6.15

Signature of the Inspecting Officer Name:-Suresh Singh Designation: - ADO (Shah) Signature of the Inspecting Officer

Name:-Virendra Singh Designation: - DO (ED)

Dy. CFO (NDZ) - M EIL

Submitted for approval please.

Wrigh

CFO (HOW)

Am SSIG

25 6 14

25-614 2535